



Private Vehicle Inspection Report

Decal Number: FV12321
Decal Expiry Date: 2023-Nov-30
Inspection Number: 20323631

Inspection Result: **PASS**

Facility: J. KAMAJUTO REPAIR LTD. / S6203
Inspector: Dhaliwal, Jarnail Singh / 105512
Work Order Number: 57837

Inspection Type: Complete
Inspection Class: Class 1 - Light Vehicle with LGVW 5500 kg or less
Inspection Reason: Salvage Vehicle

Inspection Start Date/Time: 2022-Nov-12 02:00 PM
Inspection Complete Date/Time: 2022-Nov-19 12:40 PM
Collision Repair Facility: RED SEAL COLLISION LTD
Collision Repair Facility Phone: (604) 753-8571
Collision Repair Technician: Mahmoud Haghmohammadi 01351-AB-08

Vehicle Jurisdiction: British Columbia

Brake Type: Hydraulic

Owner/Lessee Name: CRAFT, BEST BUY GROUP MOTOR LTD

Registration Number: 10352108

Fuel Type: Gasoline

Address: 7832 - EDMONDS ST

VIN: WAUWFBFH6BN010424

Odometer: 98410 KM

City: Burnaby

Plate Number: N/A

Hub Odometer:

Province/State: British Columbia

Licensed GVW (kg): 0

Body Style: 2 Door Convertible

Postal Code/ZIP: V3N1B8

Vehicle Year: 2011

Model:

Country: Canada

Make: AUDI

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Passed	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	Rplcd rt frnt susp,rprd sacatches & paint rt side
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Not Applicable	

Tire Tread Depth (mm)

Axles (front)	Outer Left	Inner left	Inner Right	Outer Right	Steering Axle?
1	3			3	
2	3			3	✓

Comment:

Brake Lining/Pad Measurement (mm)

Axles (front)	Lining/Pad	Left	Right
1	Pad	7	7
2	Pad	7	7

Comment:

Rotor Thickness or Drum inside Diameter Measurement (mm)

Axles (front)	Rotor/Drum	Left	Right
1	Rotor	29.02	29.02
2	Rotor	10.56	10.56

Comment:

Inspection Comments: Repaired by Craft Tech Collision (778-987-9090) insp by j kam auto repair (604-591-1531)

Has this Vehicle been road tested? Yes When? Before and After Inspection Name of the person who did the road test: J Dhaliwal

Inspector Name: Dhaliwal, Jarnail Singh

Signature:

This Inspection Report was submitted to CVSE on 2022-Nov-21 11:16 AM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/M.P. at the Commercial Vehicle Safety Enforcement

CVSE0013

11/21/2022 11:17:56 AM



BRITISH COLUMBIA

Ministry of Transportation and Infrastructure

Designated Inspection Facility

(DIF must issue this form for completion by an autobody technician)

Structural Integrity Declaration Report

Commercial Vehicle Safety and Enforcement Branch

PASS All requirements met

FAIL Requirements NOT met

Designated Inspection Facility Information

Designated Inspection Facility Number: S 6 2 0 3

Facility Name: J. Kam Auto Repair LTD

Authorized Inspector Number: 1 0 5 5 1 2

Inspector Name: Jarnail S. Dhaliwal

Inspector Signature: *[Signature]*

Date: 19/Nov/2022 Decal No.: FV12321

Vehicle Information

Owner: BEST BUY GROUP MOTORS

Registration #: 103521-B Plate #: N/A

Address: 2965-PHEASANT ST

VIN #: WAUWF8FH8BN010424

City: COQUITLAM Prov: BC PCV3B5M4

Make: AUDI Model: A5 Year: 2011

Structural Integrity Declaration Report

Repair Standard and Vehicles Dimensions

1. I confirm that the repair / rebuild process for this vehicle has met or exceeded the rebuilding standards specified by the Inter-Industry Conference On Auto Collision Repair (I-CAR) and / or the Original Equipment Manufacturer (OEM), that the unitized vehicle body repair, including engine cradle, conforms to the OEM dimension standards and that a full-framed vehicle complies with the OEM, I-CAR repair standard.

Wheel alignment (all 4 wheels-attach printout) Alignment performed (facility name and address if other than above): NAME: J. Kam Auto Repair LTD

ADDRESS: 217 12745 78 avenue

Please indicate numbers and measurements on diagram below:

From inside vehicle:		Front Left	Front Right
-1.25°	Camber		Camber -1.45°
4.9°	Caster		Caster 4.8°
0.20°	Toe		Toe 0.20°
5.1°	SAI		SAI 4.9°
3.8°	Included Angle		Included Angle 3.4°
	Turning Angle		Turning Angle

Occupant Protection and Vehicle Components

2. I confirm that the assembly of body components have been performed in a manner that provides occupant protection that is equal to or exceeding OEM or I-CAR standards.

3. I confirm that the repairable structural components of the vehicle body have been assembled and repaired in accordance with methods, procedures and standards that will return the components to its original standard, quality and properties in accordance with the OEM, I-CAR standards.

4. I confirm that the assembly joints of the vehicle body are located in places and repaired in accordance with the OEM, I-CAR procedures and standards.

Rear Left		Rear Right
-1.50°	Camber	Camber -1.60°
	Caster	Caster
0.25°	Toe	Toe 0.10°
	SAI	SAI

Wheel Alignment

5. I confirm that a four-wheel alignment has been performed and that steering angles and wheel tolerances are within the OEM, requirements for this vehicle. A four-wheel alignment computer printout has been included as part of this declaration.

I certify that this vehicle has been repaired in accordance with OEM/I-CAR standards as noted in items 1 - 5 above.

ALIGNMENT PASS FAIL

Technician Name: Mahmoud Haghmohammadi

Autobody Tech Trade Qualification #: 01351-AB-08

Date Rebuilt Completed: 19/Nov/2022

Autobody Tech Trade Jurisdiction: B.C 604-753-8571

Rebuilder Name: CRAFT TEC COLLISION

Technician Signature: *[Signature]*

Rebuilder Name (if different from technician)

Rebuilder Address: 5411-IMPERIAL ST BURNABY BC V5T1E6

* The ORIGINAL copy of this form must be forwarded to the designated inspection facility indicated above, and MUST be retained by the facility. * This form must be the authentic original version signed by the autobody technician. Any photocopied, modified, altered, or changed form is unacceptable and must be rejected. * A photocopy must accompany the customer's copy of the Vehicle Inspection Report (CVSE0013).



Body Integrity Inspection Report

To be completed by the Designated Inspection Facility's Authorized Vehicle Inspector

Designated Inspection Facility Information

Designated Inspection Facility Number: S6203, Authorized Inspector Number: 105512, DIF Facility Name: J. Kam Auto Repair LTD., Inspector Name: Jarnail S. Dhaliwal, Inspection Start Date: 12/11/2012, Inspection Completion Date: 11/11/2012, Inspector Signature: [Signature]

VEHICLE OWNER NAME OF REBUILDER (if other than owner)

Name: BEST BUY GROUP MOTOR, Address: 2965-PHEASANT ST, City: COQUITLAM, Prov BC, PC V3B5M9, Tel #: 778-987-9090. Name: CRAFT TEC COLLISION, Address: 5411-IMPERIAL ST, City: BURNABY, Prov BC, PC V5T1E6, Tel #: 778-987-9090

Vehicle Information

TYPE OF VEHICLE: [X] Passenger Car, [] MPV, [] Truck, [] Motorhome, [] Taxi, [] Bus. Licence Plate: N/A, Odometer: 096410, Year: 2011, Make: AUDI, Model: A5. Registration Number: 10352108, VIN/Serial #: WAUWFBFH6BN010424

I am satisfied that this rebuilt motor vehicle is the same as the one described in the record of rebuilding. [X] Yes [] No

Table with 4 columns: Requirements of Rebuilding, Components, R, C, VIM Reference Section. Rows include: Photographs prior to rebuilding, Structural Integrity Declaration Report, 4 Wheel Alignment Printout, Welded and structural components that require protection, Vehicle meets symmetric and asymmetric specifications.

Noted A7 fuel pump, replaced it 7 days. "R" marked when item rejected, "C" marked when item corrected

Blended EV 12321

I certify that this rebuilt vehicle meets all Structural Integrity requirements as defined in the Motor Vehicle Act Regulations and the BC Vehicle Inspection Manual.

Authorized Inspector Name (print): Jarnail S. Dhaliwal, Signature: [Signature]

J KAM AUTOMOTIVE
 #217 12745 78AVE
 SURREY, BC
 604.591.1531


Customer: CRAFT TEH
 Company:

License No:
 Odometer: 098410

Order No.:
 VIN:
 WAUWFBFH6BN010424

Date: 11/19/2022 12:01
 Technician: JK

Vehicle AUDI 2011 A5 [8T/8F] Cabriolet [8F] (1BL)



Your vehicle has been aligned using a precision **JohnBean** wheel aligner.

4.4.2, United States Domestic, US2021R3