



Private Vehicle Inspection Report

Decal Number: FV12475
Decal Expiry Date: 2023-Dec-31
Inspection Number: 20346324

Inspection Result: **PASS**

Facility: J. KAM AUTO REPAIR LTD. / S6203
Inspector: Dhaliwal, Jarnail Singh / 105512
Work Order Number: 57897

Inspection Type: Complete
Inspection Class: Class 1 - Light Vehicle with LGVW 5500 kg or less
Inspection Reason: Salvage Vehicle

Inspection Start Date/Time: 2022-Dec-05 11:55 AM
Inspection Complete Date/Time: 2022-Dec-09 11:45 AM
Collision Repair Facility: RED SEAL COLLISION LTD
Collision Repair Facility Phone: (604) 753-8571
Collision Repair Technician: Mahmoud Haghmohammadi 01351-AB-08

Vehicle Jurisdiction: British Columbia

Brake Type: Hydraulic

Owner/Lessee Name: CRAFT, BEST BUY GROUP MOTOR LTD

Registration Number: 12310407
VIN: JM1BN1M39H1146486
Plate Number: N/A
Licenced GVW (kg): 0
Vehicle Year: 2017
Make: MAZDA

Fuel Type: Gasoline
Odometer: 150391 KM
Hub Odometer:
Body Style: Hatchback
Model: MZDA3

Address: 7832 - EDMONDS ST
City: Burnaby
Province/State: British Columbia
Postal Code/ZIP: V3N 1B8
Country: Canada

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Passed	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	Rplcd frnt bmpr asmbly,hd lts,fndrs,hood,rad sup,rad,a/c
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Not Applicable	

Tire Tread Depth (mm)

Axles (front)	Outer Left	Inner left	Inner Right	Outer Right	Steering Axle?
1	3			3	✓
2	3			3	

Comment:

Brake Lining/Pad Measurement (mm)

Axles (front)	Lining/Pad	Left	Right
1	Pad	7	7
2	Pad	7	7

Comment:

Rotor Thickness or Drum Inside Diameter Measurement (mm)

Axles (front)	Rotor/Drum	Left	Right
1	Rotor	24.31	24.31
2	Rotor	10.52	10.52

Comment:

Inspection Comments:

Repaired by Craft Tech Collision (778-987-9090) insp by j kam auto repair (604-591-1531)

Has this Vehicle been road tested? Yes

When? Before and After Inspection

Name of the person who did the road test:

J Dhaliwal

Inspector Name: Dhaliwal, Jarnail Singh

Signature:

This Inspection Report was submitted to CVSE on 2022-Dec-09 03:16 PM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/M.P. at the Commercial Vehicle Safety Enforcement

CVSE0013

12/9/2022 3:17:34 PM



BRITISH COLUMBIA

Ministry of Transportation and Infrastructure

Designated Inspection Facility

(DIF must issue this form for completion by an autobody technician)

Structural Integrity Declaration Report

Commercial Vehicle Safety and Enforcement Branch

PASS All requirements met

FAIL Requirements NOT met

Designated Inspection Facility Information

Designated Inspection Facility Number: S 6 2 0 3

Facility Name: J. Kam Auto Repair LTD

Authorized Inspector Number: 1 0 5 8 1 2

Inspector Name: Jarnail S. Dhaliwal

Inspector Signature: [Signature]

Date: 09/Dec/2022 Decal No.: FV12475

Vehicle Information

Owner: BEST BUY GROUP MOTOR LTD

Registration #: 13310407

Plate #: N/A

Address: 7832 - EDMONDS ST

VIN #: JM1BN1M39H1146486

City: BURNABY

Prov: BC PCV3N1BB

Make: MAZDA

Model: 3

Year: 2017

Structural Integrity Declaration Report

Repair Standard and Vehicles Dimensions

1. I confirm that the repair/rebuild process for this vehicle has met or exceeded the rebuilding standards specified by the Inter-Industry Conference On Auto Collision Repair (I-CAR) and/or the Original Equipment Manufacturer (OEM), that the unitized vehicle body repair, including engine cradle, conforms to the OEM dimension standards and that a full-framed vehicle complies with the OEM, I-CAR repair standard.

Wheel alignment (all 4 wheels - attach printout) Alignment performed (facility name and address if other than above): NAME: J. Kam Auto Repair LTD

ADDRESS: 217 12745 78 avenue

Please indicate numbers and measurements on diagram below:

Table with columns for Front Left, Front Right, Rear Left, Rear Right and rows for Camber, Caster, Toe, SAI, Included Angle, Turning Angle.

Occupant Protection and Vehicle Components

2. I confirm that the assembly of body components have been performed in a manner that provides occupant protection that is equal to or exceeding OEM or I-CAR standards.

3. I confirm that the repairable structural components of the vehicle body have been assembled and repaired in accordance with methods, procedures and standards that will return the components to its original standard, quality and properties in accordance with the OEM, I-CAR standards.

4. I confirm that the assembly joints of the vehicle body are located in places and repaired in accordance with the OEM, I-CAR procedures and standards.

Wheel Alignment

5. I confirm that a four-wheel alignment has been performed and that steering angles and wheel tolerances are within the OEM requirements for this vehicle. A four-wheel alignment computer printout has been included as part of this declaration.

I certify that this vehicle has been repaired in accordance with OEM/I-CAR standards as noted in items 1-5 above.

Technician Name please print: Mahmoud Haghmohammadi

Autobody Tech Trade Qualification #: 01351-AB-08

Autobody Tech Trade Jurisdiction: B.C 604-753-8571

Technician Signature: [Signature]

Table for Rear Left and Rear Right alignment measurements including Camber, Caster, Toe, and SAI.

ALIGNMENT [X] PASS [] FAIL

Date Rebuilt Completed: 09/Dec/2022

Rebuilder Name: CRAFT TEC-COLLISIO

Rebuilder Address: 5111 - IMPERIAL ST BURNABY BC V5T1E6

* The ORIGINAL copy of this form must be forwarded to the designated inspection facility indicated above, and MUST be retained by the facility. * This form must be the authentic original version signed by the autobody technician. Any photocopied, modified, altered, or changed form is unacceptable and must be rejected. * A photocopy must accompany the customer's copy of the Vehicle Inspection Report (CVSE0013).

J KAM AUTOMOTIVE
 #217 12745 78AVE
 SURREY, BC
 604.591.1531

Customer: CRAFT TEH

License No:

Order No.:

Date:


Company:

Odometer: 150391

VIN: JM1BN1M39H1146486

Technician: JK

Vehicle MAZDA 2017 3 All Models



Besides improved fuel economy, handling and safety, what do these measurements mean?



CASTER is the tilt of the axis that the wheel steers around. It affects how the vehicle tracks as you drive down the road and can affect handling.



CAMBER is the angle of the tire in relation to the road surface. It affects tire wear, and handling when turning.



TOE is a measurement of how much the wheel is turned in or out from a straight-ahead position. It affects tire wear, handling and can make your steering wheel crooked.

Your vehicle has been aligned using a precision **John Bean** wheel aligner.

4.4.2, United States Domestic, US2021R3



Body Integrity Inspection Report

To be completed by the Designated Inspection Facility's Authorized Vehicle Inspector

Designated Inspection Facility Information

Designated Inspection Facility Number S 6 2 0 3

Authorized Inspector Number 1 0 5 5 1 2

DIF Facility Name J. Kam Auto Repair LTD.

Inspector Name Jarnail S. Dhaliwal

Inspection Start Date 05/12/2022, Inspection Completion Date 09/12/2022

Inspector Signature [Signature]

VEHICLE OWNER

NAME OF REBUILDER (if other than owner)

Name BEST BUY GROUP MOTOR LTD

Name CRAFT TEC - COLLISION

Address 7832 - EDMONDS ST

Address 5111 - IMPERIAL ST

City BURNABY Prov BC PCV3N1BB

City BURNABY Prov BC PCV351E6

Tel # 778-987-9090

Tel # 778-987-9090

Vehicle Information

TYPE OF VEHICLE: [X] Passenger Car [] MPV [] Truck [] Motorhome [] Taxi [] Bus

Licence Plate N/A Odometer 150391 Year 2017 Make MAZDA Model 3

Registration Number 12310407 VIN/Serial # JM1BN1M39H1146486

I am satisfied that this rebuilt motor vehicle is the same as the one described in the record of rebuilding. [X] Yes [] No

Table with 4 columns: Requirements of Rebuilding, Components, R, C, VIM Reference Section. Rows include STRUT, HINGE (A) PILLAR, CENTRE (B) PILLAR, LOCK (C) PILLAR, ROCKER PANEL, REAR STRUT TOWER, BUMPERS, CROSSMEMBER, HOOD, RAD SUPPORT, BODY, FRAME, BULKHEAD, DOORS, QUARTER PANELS, FLOOR PAN.

Inspected by J. Kam Auto Repair, 42225, FENNELL, HORN, BURNABY, BC, CANADA. "R" marked when item rejected, "C" marked when item corrected.

Signature: J. Kam Auto Repair, etc. FV12475

I certify that this rebuilt vehicle meets all Structural Integrity requirements as defined in the Motor Vehicle Act Regulations and the BC Vehicle Inspection Manual.

Authorized Inspector Name (print) Jarnail S. Dhaliwal Signature [Signature]