



Private Vehicle Inspection Report

Decal Number: FV12490
 Decal Expiry Date: 2023-Dec-31
 Inspection Number: 20348416

Inspection Result:
PASS

Facility: J. KAMAUTO REPAIR LTD. / S6203	Inspection Type: Complete	Inspection Start Date/Time: 2022-Dec-03 02:00 PM
Inspector: Dhaliwal, Jarnail Singh / 105512	Inspection Class: Class 1 - Light Vehicle with LGWW 5500 kg or less	Inspection Complete Date/Time: 2022-Dec-12 08:35 AM
Work Order Number: 58015	Inspection Reason: Salvage Vehicle	Collision Repair Facility: RED SEAL COLLISION LTD
		Collision Repair Facility Phone: (604) 753-8571
		Collision Repair Technician: Mahmoud Haghmohammadi 01351-AB-08

Vehicle Jurisdiction: British Columbia	Brake Type: Hydraulic	Owner/Lessee Name: INLINE, INLINE MOTORS
Registration Number: 13627172	Fuel Type: Gasoline	Address: 333 - 12 ST
VIN: 5YFBPRBEXLP136535	Odometer: 21112 KM	City: New Westminster
Plate Number: N/A	Hub Odometer:	Province/State: British Columbia
Licensed GVW (kg): 0	Body Style: 4 Door Sedan	Postal Code/ZIP: V3M4H5
Vehicle Year: 2020	Model: CROLA	Country: Canada
Make: TOYOTA		

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Passed	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	Rplcd rt indr,rt frnt door,rprd lft 1/4
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Not Applicable	

Tire Tread Depth (mm)					
Axles (front)	Outer Left	Inner Left	Inner Right	Outer Right	Steering Axle?
1	3			3	✓
2	3			3	
Comment:					

Brake Lining/Pad Measurement (mm)			
Axles (front)	Lining/Pad	Left	Right
1	Pad	8	8
2	Pad	8	8
Comment:			

Rotor Thickness or Drum Inside Diameter Measurement (mm)			
Axles (front)	Rotor/Drum	Left	Right
1	Rotor	22.49	22.49
2	Rotor	9.56	9.56
Comment:			

Inspection Comments: Repaired by MJA body shop (604-325-5000) insp by j kam auto repair (604-591-1531)

Has this Vehicle been road tested? Yes When? Before and After Inspection Name of the person who did the road test: J Dhaliwal

Inspector Name: Dhaliwal, Jarnail Singh Signature:

This Inspection Report was submitted to CVSE on 2022-Dec-12 03:29 PM

The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MIP at the Commercial Vehicle Safety Enforcement

CVSE0013

12/12/2022 3:30:05 PM



Body Integrity Inspection Report

To be completed by the Designated Inspection Facility's Authorized Vehicle Inspector

Designated Inspection Facility Information

Designated Inspection Facility Number S 6 2 0 3

Authorized Inspector Number 1 0 5 5 1 2

DIF Facility Name J. Kam Auto Repair LTD.

Inspector Name Jarnail S. Dhaliwal

Inspection Start Date 03 12 2022 Inspection Completion Date 12 12 2022

Inspector Signature Dhaliwal

VEHICLE OWNER NAME OF REBUILDER (if other than owner)

Name INLINE MOTORS

Name M.J.A AUTO BODY

Address 333-12 ST

Address 107-13112-84 AVE

City NEW WESTMINSTER Prov BC PCV3M4H5

City SURREY Prov BC PCV3W122

Tel # 778-325-5000

Tel # 778-325-5000

Vehicle Information

TYPE OF VEHICLE: Passenger Car MPV Truck Motorhome Taxi Bus

Licence Plate N/A Odometer 021112 Year 2020 Make TOYOTA Model COROLLA

Registration Number 13627122 VIN/Serial # SYFBPRBEXLP136535

I am satisfied that this rebuilt motor vehicle is the same as the one described in the record of rebuilding. Yes No

Table with 4 main columns: Requirements of Rebuilding, Components, R, C, and VIM Reference Section. Rows include items like STRUT, HINGE (A) PILLAR, CENTRE (B) PILLAR, LOCK (C) PILLAR, and ROCKER PANEL.

Handwritten notes: "R" marked when item rejected, "C" marked when item corrected

I certify that this rebuilt vehicle meets all Structural Integrity requirements as defined in the Motor Vehicle Act Regulations and the BC Vehicle Inspection Manual.

Authorized Inspector Name (print) Jarnail S. Dhaliwal

Signature Dhaliwal



BRITISH COLUMBIA

Ministry of Transportation and Infrastructure

Designated Inspection Facility

(DIF must issue this form for completion by an autobody technician)

Structural Integrity Declaration Report

Commercial Vehicle Safety and Enforcement Branch

PASS All requirements met

FAIL Requirements NOT met

Designated Inspection Facility Information

Designated Inspection Facility Number: S 6 2 0 3

Facility Name: J. Kam Auto Repair LTD

Authorized Inspector Number: 1 0 5 5 1 2

Inspector Name: Jarnail S. Dhaliwal

Inspector Signature: [Signature]

Date: 12/Dec/2022 Decal No: FV12490

Vehicle Information

Owner: INLINE MOTORS

Registration #: 13627172 Plate #: N/A

Address: 333-12 ST

VIN #: 5YFBPRBE1LP136535

City: NEW WESTMINSTER Prov: BC PC: V3M4M5 Make: TOYOTA Model: COROLLA Year: 2020

Structural Integrity Declaration Report

Repair Standard and Vehicles Dimensions

1. I confirm that the repair / rebuild process for this vehicle has met or exceeded the rebuilding standards specified by the Inter-Industry Conference On Auto Collision Repair (I-CAR) and / or the Original Equipment Manufacturer (OEM), that the unitized vehicle body repair, including engine cradle, conforms to the OEM dimension standards and that a full-framed vehicle complies with the OEM, I-CAR repair standard.

Wheel alignment (all 4 wheels-- attach printout). Alignment performed (facility name and address if other than above): NAME: J. Kam Auto Repair LTD

ADDRESS: 217 12745 78 avenue

Please indicate numbers and measurements on diagram below:

Table with columns for Front Left, Front Right, Rear Left, Rear Right and rows for Camber, Caster, Toe, SAI, Included Angle, Turning Angle.

Occupant Protection and Vehicle Components

2. I confirm that the assembly of body components have been performed in a manner that provides occupant protection that is equal to or exceeding OEM or I-CAR standards.
3. I confirm that the repairable structural components of the vehicle body have been assembled and repaired in accordance with methods, procedures and standards that will return the components to its original standard, quality and properties in accordance with the OEM, I-CAR standards.
4. I confirm that the assembly joints of the vehicle body are located in places and repaired in accordance with the OEM, I-CAR procedures and standards.

Wheel Alignment

5. I confirm that a four-wheel alignment has been performed and that steering angles and wheel tolerances are within the OEM, requirements for this vehicle. A four-wheel alignment computer printout has been included as part of this declaration.

I certify that this vehicle has been repaired in accordance with OEM/I-CAR standards as noted in items 1 - 5 above.

Technician Name: Mahmoud Haghmohammadi

Autobody Tech Trade Qualification #: 01351-AB-08

Autobody Tech Trade Jurisdiction: B.C 604-753-8571

Technician Signature: [Signature]

Date Rebuilt Completed: 12/Dec/2022

Rebuilder Name: M.J.A - AUTO BODY

Rebuilder Address: 107-13112-64 AVE SURREY BC-V3W1L2

* The ORIGINAL copy of this form must be forwarded to the Designated Inspection Facility indicated above, and MUST be retained by the facility.
* This form must be the authentic original version signed by the autobody technician. Any photocopied, modified, altered, or changed form is unacceptable and must be rejected.
* A photocopy must accompany the customer's copy of the Vehicle Inspection Report (CVSE0013).

J KAM AUTOMOTIVE
 #217 12745 78AVE
 SURREY, BC
 604.591.1531

Customer: **INLINE**
 Company:

License No:
 Odometer: 21112

Order No.:
 VIN:
 5YFBPRBEXLP136535

Date:
 Technician: JK

Vehicle **TOYOTA 2020 COROLLA 15" Wheels Sedan**

BEFORE		AFTER		FRONT WHEELS		AFTER		BEFORE	
TOE		TOE		TOTAL TOE		TOE		TOE	
				0.15°					
-0.10°		0.05°				0.10°		0.20°	
CAMBER		CAMBER				CAMBER		CAMBER	
-0.10°		-0.10°				-0.55°		-0.60°	
CASTER		CASTER				CASTER		CASTER	
6.8°		6.8°				6.9°		6.9°	
REAR WHEELS		REAR WHEELS		TOTAL TOE		TOTAL TOE		TOTAL TOE	
TOE		TOE		0.05°		TOE		TOE	
0.20°		0.00°				0.05°		0.10°	
CAMBER		CAMBER				CAMBER		CAMBER	
-1.40°		-1.35°				-1.35°		-1.35°	
THRUST		THRUST		-0.05°		THRUST		THRUST	

The vehicle has been aligned to factory settings.

Besides improved fuel economy, handling and safety, what do these measurements mean?

CASTER is the tilt of the axis that the wheel steers around. It affects how the vehicle tracks as you drive down the road and can affect handling.

CAMBER is the angle of the tire in relation to the road surface. It affects tire wear, and handling when turning.

TOE is a measurement of how much the wheel is turned in or out from a straight-ahead position. It affects tire wear, handling and can make your steering wheel crooked.

Your vehicle has been aligned using a precision **JohnBean** wheel aligner.