



Private Vehicle Inspection Report

Decal Number: FS60315
 Decal Expiry Date: 2023-Jun-30
 Inspection Number: 20141659

Inspection Result:
PASS

Facility: J, KAM AUTO REPAIR LTD. / S6203
 Inspector: Dhaliwal, Jarnail Singh / 105512
 Work Order Number: 56646

Inspection Type: Complete
 Inspection Class: Class 1 - Light Vehicle with LGWW 5500 kg or less
 Inspection Reason: Salvage Vehicle

Inspection Start Date/Time: 2022-Jun-06 10:35 AM
 Inspection Complete Date/Time: 2022-Jun-13 08:35 AM
 Collision Repair Facility: RED SEWAL COLLISION LTD
 Collision Repair Facility Phone: (604) 753-8571
 Collision Repair Technician: Mahmoud Haghmohammadi
 01351-AB-08

Vehicle Jurisdiction: British Columbia
 Registration Number: 12514760
 VIN: 3VV2B7AX0JM085770
 Plate Number: N/A
 Licenced GVW (kg): 0
 Vehicle Year: 2018
 Make: VOLKSWAGEN

Brake Type: Hydraulic
 Fuel Type: Gasoline
 Odometer: 67494 KM
 Hub Odometer:
 Body Style: 4 Door Stationwagon
 Model: TIGUAN

Owner/Lessee Name: INLINE, INLINE MOTORS
 Address: 333 - 12 ST
 City: New Westminster
 Province/State: British Columbia
 Postal Code/ZIP: V3M4H5
 Country: Canada

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Passed	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	Rplcd hood,sun roof,rprd doors
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Not Applicable	

Tire Tread Depth (mm)

Axles (front)	Outer Left	Inner left	Inner Right	Outer Right	Steering Axle?
1	2.3			2.3	✓
2	2.3			2.3	

Comment:

Brake Lining/Pad Measurement (mm)

Axles (front)	Lining/Pad	Left	Right
1	Pad	5	5
2	Pad	6	6

Comment:

Rotor Thickness or Drum Inside Diameter Measurement (mm)

Axles (front)	Rotor/Drum	Left	Right
1	Rotor	27.59	27.59
2	Rotor	10.55	10.55

Comment:

Inspection Comments: Repaired by Craft Tech Collision (604-767-1933) insp by j kam auto repair (604-591-1531)

Has this Vehicle been road tested? Yes When? Before and After Inspection Name of the person who did the road test: J Dhaliwal

Inspector Name: Dhaliwal, Jarnail Singh

Signature:

This Inspection Report was submitted to CVSE on 2022-Jun-13 10:53 AM


The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 215 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MP at the Commercial Vehicle Safety Enforcement

CVSE0013

6/13/2022 10:53:27 AM



Body Integrity Inspection Report

To be completed by the Designated Inspection Facility's Authorized Vehicle Inspector

Designated Inspection Facility Information

Designated Inspection Facility Number S 6 2 0 3

Authorized Inspector Number 1 0 5 5 1 2

DIF Facility Name J. Kam Auto Repair LTD.

Inspector Name Jarnail S. Dhaliwal

Inspection Start Date 06/06/2022, Inspection Completion Date 13/06/2022

Inspector Signature [Signature]

VEHICLE OWNER

NAME OF REBUILDER (if other than owner)

Name INLINE MOTORS

Name CRAFT TEC COLLISION

Address 333-TWELFTH ST

Address 5111-IMPERIAL ST

City NEW WESTMINSTER Prov BC PCV3M4K5

City BURNABY Prov BC V5J1E6

Tel # 604-767-1933

Tel # 604-767-1933

Vehicle Information

TYPE OF VEHICLE: Passenger Car, MPV, Truck, Motorhome, Taxi, Bus

Licence Plate N/A, Odometer 067494, Year 2018, Make VOLKSWAGEN, Model TIQUIDA

Registration Number 12514760, VIN/Serial # 3VV2B7AX0JM085770

I am satisfied that this rebuilt motor vehicle is the same as the one described in the record of rebuilding. Yes No

Table with columns: Requirements of Rebuilding, Components, R, C, VIM Reference Section, Components, R, C, VIM Reference Section. Rows include Strut, Hinge (A) Pillar, Centre (B) Pillar, Lock (C) Pillar, Rocker Panel, Rear Strut Tower, Bumpers, Crossmember, Hood, Rad Support, Body, Frame, Bulkhead, Doors, Quarter Panels, Floor Pan.

Replaced Hood, Replaced Doors Sunroof

"R" marked when item rejected "C" marked when item corrected

certify that this rebuilt vehicle meets all Structural Integrity requirements as defined in the Motor Vehicle Act Regulations and the BC Vehicle Inspection Manual.

Authorized Inspector Name (print) Jarnail S. Dhaliwal

Signature [Signature]



BRITISH COLUMBIA

Ministry of Transportation and Infrastructure

Designated Inspection Facility

(DIF must issue this form for completion by an autobody technician)

Structural Integrity Declaration Report

Commercial Vehicle Safety and Enforcement Branch

PASS All requirements met

FAIL Requirements NOT met

Designated Inspection Facility Information

Designated Inspection Facility Number: S 6 2 0 3

Facility Name: J. Kam Auto Repair LTD

Authorized Inspector Number: 1 0 5 5 1 2

Inspector Name: Jarnail S. Dhaliwal

Inspector Signature: [Signature]

Date: 13/JUN/2022 Decal No.: FS 60315

Vehicle Information

Owner: INLINE MOTORS

Registration #: 12514760 Plate #: N/A

Address: 333 - TWELFTH ST

VIN #: 3VV2B7AX0JM085770

City: NEW WESTMINSTER Prov: BC PC: V3M4H5

Make: VOLKS Model: TIQUA Year: 2018

Structural Integrity Declaration Report

Repair Standard and Vehicles Dimensions

1. I confirm that the repair / rebuild process for this vehicle has met or exceeded the rebuilding standards specified by the Inter-Industry Conference On Auto Collision Repair (I-CAR) and / or the Original Equipment Manufacturer (OEM), that the unitized vehicle body repair, including engine cradle, conforms to the OEM dimension standards and that a full-framed vehicle complies with the OEM, I-CAR repair standard.

Wheel alignment (all 4 wheels- attach printout) Alignment performed (facility name and address if other than above): NAME: J. Kam Auto Repair LTD

ADDRESS: 217 12745 78 avenue

Please indicate numbers and measurements on diagram below:

Table with columns for Front Left, Front Right, Rear Left, Rear Right and rows for Camber, Caster, Toe, SAI, Included Angle, Turning Angle.

Occupant Protection and Vehicle Components

2. I confirm that the assembly of body components have been performed in a manner that provides occupant protection that is equal to or exceeding OEM or I-CAR standards.

3. I confirm that the repairable structural components of the vehicle body have been assembled and repaired in accordance with methods, procedures and standards that will return the components to its original standard, quality and properties in accordance with the OEM, I-CAR standards.

4. I confirm that the assembly joints of the vehicle body are located in places and repaired in accordance with the OEM, I-CAR procedures and standards.

Wheel Alignment

5. I confirm that a four-wheel alignment has been performed and that steering angles and wheel tolerances are within the OEM, requirements for this vehicle. A four-wheel alignment computer printout has been included as part of this declaration.

I certify that this vehicle has been repaired in accordance with OEM/I-CAR standards as noted in items 1 - 5 above.

Technician Name please print: Mahmoud Haghmohammadi

Autobody Tech Trade Qualification #: 01351-AB-08

Autobody Tech Trade Jurisdiction: B.C 604-753-8571

Technician Signature: [Signature]

Table for alignment results with checkboxes for PASS and FAIL.

Date Rebuilt Completed: 13/JUN/2022

Rebuilder Name: CRAFT TEC COLLISION

Rebuilder Address: 5411 - IMPERIAL ST BURNABY BC V5J1E6

* The ORIGINAL copy of this form must be forwarded to the designated inspection facility indicated above, and MUST be retained by the facility. * This form must be the authentic original version signed by the autobody technician. Any photocopied, modified, altered, or changed form is unacceptable and must be rejected. * A photocopy must accompany the customer's copy of the Vehicle Inspection Report (CVSE0013).

J KAM AUTOMOTIVE
 #217 12745 78AVE
 SURREY, BC
 604.591.1531

Customer: INLINE

License No:

Order No.:

Date: 06/09/2022 09:48


Company:

Odometer: 67494

VIN: 3VV2B7AX0JM085770

Technician:

Vehicle VOLKSWAGEN 2018 TIGUAN [AD] (G02/G03/G05) Base Suspension



Besides improved fuel economy, handling and safety, what do these measurements mean?

CASTER is the tilt of the axis that the wheel steers around. It affects how the vehicle tracks as you drive down the road and can affect handling.

CAMBER is the angle of the tire in relation to the road surface. It affects tire wear, and handling when turning.

TOE is a measurement of how much the wheel is turned in or out from a straight-ahead position. It affects tire wear, handling and can make your steering wheel crooked.

Your vehicle has been aligned using a precision **JohnBean** wheel aligner.

4.4.2, United States Domestic, US2021R2