SO# B209911

Visual 40 Point Inspection

Contact	3j Motors	Tech	David V
VIN	3GTU2NEC9JG340157	Vehicle	2018 G

David Winn 2018 GMC SIERRA 1500 Completed Date Odom 11/15/2024 192653

Visual Inspection

•					
Inspect Horn Operation					
Works: No					
Inspect Heat/Defrost Inspection					
Inspect Instrument Cluster/Interior Lights					
Inspect Seatbelt Operation and Condition					
Inspect Mirrors					
Inspect Windshield					
Inspect Wipers and Operation					
Inspect Floor Mat Condition at Accelerator					
Inspect Vehicle for Spare Tools					
: No					
Inspect all Doors and Latches for Operation					
Inspect all Exterior Lights					
Inspect Seat Operation					
DF: No					
RF: No					
Rear: No					
Inspect Block Heater and Cord, Check for Operation					
Operation Inspect Alternator					
Output:					
Volts:					
Amps: Inspect all Engine Wiring and Connectors					
Inspect all Engine Wiring and Connectors Inspect Spark Plug Condition/Pull 1 Plug					
Inspect Cooling System and Coolant Strength					
Strength:					
Inspect all Hoses					
Inspect Rad Condition					
Inspect Water Pump abd Thermostat for Leaks					
Inspect Air filter					
Inspect PCV Operation					
Inspect Hood Latch Operation					
Inspect All Fluid Levels and Condition					
Inspect Belts, Tensioner and Idler					
Inspect Tires					
LF: 9					
RF: 9					
LR: 8					
RR: 8					
Inspect Rims					
Inspect Wheel Bearings for Adjustment/Noise					
Inspect Brakes and Measure Pads					
LF: 10					
RF: 10					
LR: 8					
RR: 8					
Inspect Brake Hoses					
Visual Inspection of Steering Linkage					
Inspect CV Axle Boots					
Inspect Exhaust System	\checkmark				
Inspect Engine oil and Power Steering Leaks					
Visual Inspection of Fuel Tank and Lines for					
Leaks					
Inspect Engine/Trans Mounts					
Inspect Body Condition					