

Vehicle History Report (BC) #: 50214007 Report Date: December 9, 2023 | 12:16 PM EST

Report Status: Complete

2017 CHEVROLET CRUZE

3G1BE6SM6HS556372 Country of Assembly: n/a Last Reported Odometer: 72,258 KM



Accident/Damage Records Found



Last Registered In: British Columbia (Normal)



8 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of December 09, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report (BC)



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
① 2019 Feb 28	British Columbia, Canada	THE PARTY OF THE P
	Police Reported Accident: Accident reported	
	Estimate: COLLISION Estimate Date: n/a	\$0.00
	Claim: COLLISION	\$0.00
9 2019 Dec 5	British Columbia, Canada	an arean en
	Claim: COLLISION	\$0.00
0 2020 Feb 1	British Columbia, Canada	
	Claim: COLLISION	\$0.00
① 2020 Nov 13	British Columbia, Canada	
	Estimate: RIGHT REAR CORNER Estimate Date: n/a	\$1,771.60
,	Claim: COLLISION RIGHT REAR CORNER	\$1,771.60
① 2021 Jan 4	British Columbia, Canada	
	Estimate: RIGHT FRONT CORNER Estimate Date: n/a	÷ \$2,355.16
	Claim: COLLISION RIGHT FRONT CORNER	\$2,210.31
2022 Sep 30	British Columbia, Canada	
	Claim: COLLISION	\$0.00

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
① 2022 Mar 24	Vancouver, British Columbia, Canada	
	Auction Announcement: AUCTION ANNOUNCED AS ACCIDENT REPAIR	

Surrey, British Columbia, Canada



Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact CHEVROLET or visit GM's website.



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

D	ATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
20	017 Jul 15		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
20	017 Oct 18	The Control of the Co	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
20	018 Apr 22		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
20	119 Feb 28		Police Reported Accident	Police Report	Accident Reported:
20	19 Feb 28		Insurance Records British Columbia, Canada	COLLISION	
20	19 Feb 28		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a COLLISION
20	19 Mar 9	33,159 KM	Jiffy Lube #1084 Surrey, British Columbia, Canada	Service Record	Vehicle serviced
20	19 Apr 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
20	19 Jul 26	41,106 KM	Jiffy Lube #1084 Service Record Surrey, British Columbia, Canada		Vehicle serviced
20	19 Nov 25	48,031 KM	Jiffy Lube #1084 Surrey, British Columbia, Canada	Service Record	Vehicle serviced



Registration

This vehicle has been registered in the province of British Columbia in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2019 Mar 9	33,159 KM	Jiffy Lube #1084	Vehicle serviced
		Surrey, British Columbia, Canada	Recommended maintenance performed
		*	Oil and filter changed
			Vehicle washed/detailed
		.	 Fluids checked
2019 Jul 26	41,106 KM	Jiffy Lube #1084	Vehicle serviced
		Surrey, British Columbia, Canada	Recommended maintenance performed
		Janey, British Coldinbia, Canada	Oil and filter changed
			Fluids checked
			Vehicle washed/detailed
			Engine oil system flushed
2019 Nov 25	48,031 KM	Jiffy Lube #1084	Vehicle serviced
	10,007 1111		
		Surrey, British Columbia, Canada	 Recommended maintenance performed Fluids checked
			Vehicle washed/detailed
***************************************			Oil and filter changed
2020 Mar 23	53,548 KM	Jiffy Lube #1084	Vehicle serviced
		Surrey, British Columbia, Canada	 Recommended maintenance performed
			Fluids checked
			 Transmission fluid changed
			Automatic transmission serviced
			 Air filter replaced
			Oil and filter changed
			Vehicle washed/detailed
			 Air filter checked
			Transmission serviced
2020 Jul 24	59,195 KM	Jiffy Lube #1084	Vehicle serviced
		Surrey, British Columbia, Canada	Recommended maintenance performed
		Sarrey, British Columbia, Canada	Fluids checked
			Brake fluid flushed/changed
			Vehicle washed/detailed
			Oil and filter changed
020 Nov 20	64,499 KM	Jiffy Lube #1084	Vehicle serviced
	- I/ I INIVI		
		Surrey, British Columbia, Canada	Recommended maintenance performed
			Vehicle washed/detailed
POPURATE CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CO			Oil and filter changed
021 Mar 22	69,572 KM	Jiffy Lube #1084	Vehicle serviced
		Surrey, British Columbia, Canada	 Recommended maintenance performed
		Appropriate Control State Cont	Fluids checked
			 Vehicle washed/detailed
			 Oil and filter changed
			Compared Decorations (Appendix Control

2019 Dec 5		Insurance Records British Columbia, Canada		
2020 Feb 1		Insurance Records British Columbia, Canada	COLLISION	
2020 Mar 23	53,548 KM	Jiffy Lube #1084 Surrey, British Columbia, Canada	Service Record	Vehicle serviced
2020 May 9		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jul 24	59,195 KM	Jiffy Lube #1084 Surrey, British Columbia, Canada	Service Record	Vehicle serviced
2020 Nov 13		Insurance Records British Columbia, Canada	COLLISION	RIGHT REAR CORNER
2020 Nov 13		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a RIGHT REAR CORNER
2020 Nov 20	64,499 KM	Jiffy Lube #1084 Surrey, British Columbia, Canada	Service Record	Vehicle serviced
2021 Jan 4		Insurance Records British Columbia, Canada	COLLISION	RIGHT FRONT CORNER
2021 Jan 4		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a RIGHT FRONT CORNER
2021 Mar 22	69,572 KM	Jiffy Lube #1084 Surrey, British Columbia, Canada	Service Record	Vehicle serviced
2021 Apr 20		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2022 Mar 15		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2022 Mar 17	71,724 KM	Mainland Ford Surrey, British Columbia, Canada	vernice serviced	
2022 Mar 24	72,258 KM	Auto Auction Vancouver, British Columbia, Canada	Auction Announcement AUCTION ANNOUNCE lumbia, ACCIDENT REPAIR	
2022 Mar 24		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed

			New Owner reported Vehicle colour noted a gray
2022 Aug 30	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2022 Sep 30	Insurance Records British Columbia, Canada	COLLISION	



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disdaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle daims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at http://apps.icitc.com/registration/ychr/Limitation.html, ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition,

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, deciderations, accident information, service records, recall information, obometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable to nesponsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an assis where is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantablely, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada and are any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. Conditions of Use

© 2024 CARFAX Canada ULC. All rights reserved.



JK PRIDE AUTO SERVICE

1380 Dominion Avenue Port Coquitlam, BC. V3B 8G7 Phone - 778-918-0537

INVOICE

2285

INVOICE

yvr used car gallery Itd

2017 chevy - cruze 1.4

Lic #: 556372

Odometer In: 93007

Print Date: 04/12/2024

Unit #:

in #: 3G1BE6SM6HS556372

Cust ID :	1401		Ref#:ps	st1442-0209	Vin # : Hat # :	3G1BE6SM6HS556372	
Part Description	/ Number	Qty	Sale	Extended	Labor Descr	iption	Extended
oxygen sansor(b1 *471009910 maf sensor	s1)	1.00	125.00	125.00	engine light or	ncheck and replace air filter,maf xygen sensor	Extended 200.00
*c36912/6 air filter		1.00	149.00	149.00			
* turbo cooler lower	r hose	1.00	25.00	25.00			
* gas		1.00	300.00	300.00			
*		1.00	40.00	40.00			

[Technicians : Please Select, Technician]

Org. Estimate \$558.88	Revisions \$0.00	Current Estimate 6 550.00	A 1 1111			
		Current Estimate \$ 558.88	Additional Cost	Revised Estimate	Labor:	200.00
					Parts:	639.00
					Sublet:	0.00
					1	
					Sub:	839.00
					Tax:	41.95
					Short Articles of the Controls	
[Payments -]					Total:	880.95
					Bal Due:	\$880.95
T1 1 1 1 1 1						

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of

SIGNATURE.....

Dat



Black Bear Auto Service

5162 Still Creek Ave Burnaby, BC V5C 4E4 Ph: 236 477-5938

Email:chris@blackbearautoservice.com

GST: 795489541 RT0001

Invoice

Bill To YVR USED CAR GALLERY LTD 1065 Lougheed Hwy Coquitlam, BC Canada

Home (604) 588-1999 Email

Invoice # 1160 Work Order # 2303 Service Advisor Duane Boudreau

Technician Justin Innanen

Plate BC NO PLATE

Description 2017 Chevrolet Cruze LT L4 1.4L 1399CC 85CII

VIN M

VIN 3G1BE6SM6HS556372

Odometer 92,801

Invoice Date 3/1/2024 5:56 PM Appointment 2/28/2024 4:11 PM Promised 2/28/2024 4:11 PM

Inspection

CVI Complete Vehicle Inspection

Labor

1 Hour

\$135.00 / Hour

\$135.00 *GP

Sub \$135.00

Service

Disc Brake Pads & Rotors (Front)

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor CERAMIC PAD SET COATED BRAKE ROTOR 1.2 Hour

\$135.00 / Hour

\$162.00 *GP

1 Unit 2 Unit \$101.30 / Unit \$141.55 / Unit \$101.30 *GP \$283.10 *GP

Sub

\$546.40

Suspension Control Arm, Lower Left

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Labor

0.84 Hour

\$135.00 / Hour

\$113.40 *GP

Suspension Control Arm

1 Unit

\$382.14 / Unit

\$382.14 *GP

Sub \$495.54

Suspension Control Arm, Lower Right

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Labor

0.84 Hour

\$135.00 / Hour

\$113.40 *GP

Suspension Control Arm

1 Unit

\$382.14 / Unit

\$382.14 *GP

Sub

\$495.54

Exterior Light Bulb(s)

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

license plate bulb

1 Unit

\$14.33 / Unit

\$14.33 *GP \$14.33

Lube, Oil & Filter Service - Synthetic oil

Drain and refill engine oil, change engine oil filter and lubricate chassis grease fittings and friction points as required. Check and top off fluid levels, additional charges may apply where fluids are required. Complete a complimentary visual vehicle inspection. Labor

0.3 Hour 1 Unit \$135.00 / Hour

\$40.50 *GP

OIL FILTER

\$17.86 / Unit

\$17.86 *GP

Synthetic Engine Oil

4.6 Litre

\$12.67 / Litre

\$58.28 *GP

Sub

Sub

\$116.64

				*
				*

* ,	Total Parts Total Labor Total Before Taxes & Miscellaneous Charges		\$1,239.15 \$564.30 \$1,803.45
	(*) Shop Supplies (G) Canadian Goods and Services Tax (GST) (P) BC Provincial Sales Tax (PST)* Exemption #: 14420209	5 %	\$54.10 GP \$92.88 \$0.00
	Grand Total		\$1,950.43

YVR USED CAR GALLERY LTD paid \$1,950.43 by American Express

Thanks for the Business! I acknowledge receipt of the vehicle and the indebtedness indicated herein.

Customer Signature:

			E



Black Bear Auto Service

5162 Still Creek Ave Burnaby, BC V5C 4E4 Ph: 236 477-5938

Email:chris@blackbearautoservice.com

GST: 795489541 RT0001

Inspection Sheet With Inspection Results

Bill To YVR USED CAR GALLERY LTD 1065 Lougheed Hwy Coquitlam, BC Canada

Home (604) 588-1999 Email

Invoice # 1160 Work Order # 2303 Service Advisor Duane Boudreau Technician Justin Innanen Plate BC NO PLATE
Description 2017 Chevrolet Cruze LT L4 1.4L 1399CC 85CII
VIN M
VIN 3G1BE6SM6HS556372
Odometer 92,801

Invoice Date 3/1/2024 5:56 PM Appointment 2/28/2024 4:11 PM Promised 2/28/2024 4:11 PM

CVI Complete Vehicle Inspection

CVI Complete Vehicle Inspection	0	S	R	NA	
Oil, Lube & Maintenance Service					
LUBE, OIL & FILTER SERVICE	1				Last Sticker Service: Date: Feb 29/2024 Odometer: 92,801
Lube Chassis					
Provincial / State / Safety Inspection				1	Due Date:
Emission Sticker				1	Due Date:
Other:					
Accessories					
Horn(s)	1				
Release Cable: Hood, Hatch, Trunk, Fuel Door	1				
Lift Support(s): Hood, Hatch, Trunk	1				
Power Windows / Power Door Locks / Power Seat	V				
Cruise Control	V				
Wiper	1				(Front / Rear)
Washer Fluid / Reservoir / Pump / Nozzles / Hoses (Front / Rear)	V				
Speedometer / Tachometer	V				
Dash Gauges / Indicator Lights	$\sqrt{}$				
Rear Defroster	√				
Seat Belts	V				
Mirrors (Rear View / Side)	√				
Fuses / Fuseable Link	√				
Switches / Relays	1				
Other:					
Electrical					
AVR Test	1				
Exterior Lights (Front / Rear / Side / Turn)	√				
Flasher (Turn / Hazard)	V				
Interior Lights (Instrument / Courtesy / Warning)	1				
Fuse / Fuseable Link	1				
Switches / Relays	1				
Battery / Cables / Cable Connections	$\sqrt{}$				
Alternator / Starter	V				
DRIVE / SERPENTINE BELT & Belt	1				

					* 7

CVI Complete Vehicle Inspection	0	S	R	NA	
Tensioner	+	-	1	INA	
Other:	-	-	-		
Cooling	+	-	-	-	
Pressure Test	1		-	-	H
Pressure rest	1	_		_	lbs.
Anti-Freeze / Coolant	1				Strength: pH Level: Electrolite:
COOLING SYSTEM FLUSH				1	
Coolant Overflow Reservoir / Cap / Lines	1				
Radiator / Cap	1				
COOLING SYSTEM HOSES	1				
Water Pump / Thermostat	1				
Fan / Fan Clutch				V	
Electric Fan / Auxiliary	1				
Fuses / Fuseable Link	1.				
Switches / Relays	1				
Freeze / Frost Plug(s)	V				
Block Heater / Cord	V				
Other:					
HVAC (Heating, Ventilation & Air Conditioning)					
PERFORMANCE TEST A/C	V				
CABIN AIR FILTER	V				
Blower Motor / Switch / Relay / Resistor	1				
AC Hoses	1				
Compressor / Clutch / Coil	1				
Evaporator / Condensor	1 V				
Automatic Temperature Control (ATC)	1				
Heater Hoses	V				
Other:					
Driveability (Fuel, Ignition, Emissions)	+				
CEC / Service Soon Light	1				
Computer System Scan	1				
MAINTENANCE TUNE-UP	V				
AIR FILTER	1				
SPARK PLUGS / PLUG WIRES	TV				
Coil / Boot / Insulator	TV		-		
Distributor / Cap / Rotor	11	-+			
FUEL FILTER	1	\dashv			
FUEL INJECTION FLUSH	1				
Fuel Tank / Lines / Hoses / Fittings	1				
Other:					
Suspension & Steering					
Ball Joints (Upper / Lower)	1				control arm with ball joints replaced during this service
Control Arms (Upper / Lower)	V				and deliver and parties replaced daring the deliver
Tire Rod Ends (Inner / Outer)	11	-		-1	
Pitman Arm / Idler Arm		-		V	
Steering Gear / Rack & Pinion	1	-			
Power Steering Pump / Hoses	1	-			
POWER STEERING FLUID FLUSH	1	-			
STRUTS (Front / Rear)	1				
SHOCKS (Front / Rear)	1	-			
Springs (Front / Rear)	1			-	
WHEEL ALIGNMENT	1			-	
Other	+ +	-		-	
Tires & Wheels	+	-i		—i	
Tires	1				Size:
					OILO.

			, , , , , , , , , , , , , , , , , , ,

CVI Complete Vehicle Inspection	0	S	R	NA	
Tire Condition & Tread Depth	V				5mm"LF, 5mmRF 5mmLR, 5mmRR
ROTATE / BALANCE / ROTATE & BALANCE	√				·
Wheel Studs / Nuts	V			Ì	
Wheels / Rims				V	
Other:					
Brakes					
Disc Brake Pad	√				front brakes replaced during this service- Rear Brakes at 6mm
Disa Baska Batas	V				Front:
Disc Brake Rotor	V				Rear:
Drum Brake Shoe				1	Front:/32" /% /MM Rear:/32" /% /MM
Brake Drum				√	Front: Rear:
Brake / Caliper Hardware (Front / Rear)	√				
Brake Rotors / Drums					
Brake Calipers (Front / Rear)	√				
Wheel Cylinders				1	
Master Cylinder / Power Brake Booster	V				
Brake Hoses / Lines	1				
Brake Cables	V				
BRAKE FLUID FLUSH	V				
Parking Brake	√				
ABS Brake Diagnosis	V				
Wheel Speed Sensor(s)	V				
Other:					
Drive Train					
Drive Shaft / Universal Joint(s) / Center Support	V				
CV Joint / Boot / Axle Shaft	V				
Pinion / Axle Seal(s)	V				
Bearings	V				
DIFFERENTIAL FLUID EXCHANGE	V				
Other:					
Engine					
Engine Wash & Recheck Leaks	1				
Valve Cover / Intake / Cylinder Head Gasket	1				
Oil Pan / Drain Plug / Gaskets	1				
Front Main / Rear Main Seals	V				
Timing Chain / Gears	V				
TIMING BELT				1	
Motor Mounts / Torque Strap	1				
VALVE ADJUSTMENT	1				
Bearings				√	
Other:					
Transmission & Clutch					
TRANSMISSION FLUID & FILTER SERVICE	1				
TRANSMISSION FLUID FLUSH / EXCHANGE	V				
Seals (Front / Rear / Shift / Speedometer)	1				
Shifter / Linkage / Cable	1				
Clutch Disc / Pressure Plate / Release Bearing / Fork				1	
Clutch Cable / Linkage / Adjustment				1	
Clutch Master Cylinder / Slave Cylinder				V	
Transfer Case / Shifter				1 1	
Transmission Mount(s)					

		· · · · · · · · · · · · · · · · · · ·

CVI Complete Vehicle Inspection	0	S	R	NA
Other:				
Exhaust				
Catalytic Converter	V			
Muffler / Resonator	V			
Exhaust pipe	V			
Manifold / Gasket	V			
Clamps / Hangers	V			
Other:				
Additional Notes & Observations:				