

Private Vehicle Inspection Report

Decal Number: **Decal Expiry Date:** Inspection Number:

FW42730 2024-Jan-31 20363712

Inspection Result: **PASS**

Facility: Inspector: ABBOTSFORD TUNE-UP CENTER /

MOHAMMAD YUSOF, MOHAMMAD ARIS /

203635

Work Order Number:

Inspection Type: Inspection Class:

Inspection Reason:

Complete

Class 1 - Light Vehicle with LGVW 5500

Salvage Vehicle

Inspection Start Date/Time:

2022-Dec-17 02:30 PM

Inspection Complete Date/Time: 2023-Jan-02 06:00 PM AMC AUTO

Collision Repair Facility: Collision Repair Technician:

Collision Repair Facility Phone: (778) 317-1840 ARIS YUSOF

Vehicle Jurisdiction:

British Columbia

Brake Type:

Hydraulic

Owner/Lessee Name:

AINI ENTERPRISE LTD., AINI

ENTERPRISE LTD.

Registration Number: VIN:

12183600 2HGFC1F40GH112211

Fuel Type:

Gasoline 96640 KM

333 TWELFTH STREET

Plate Number:

Odometer: Hub Odometer:

Province/State:

New Westminster

Licenced GVW (kg):

D 2016 Body Style:

Model:

4 Door Sedan

Postal Code/ZIP:

British Columbia V3M4H5

Vehicle Year: Mako

CIVIC

Country:

Canada

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Passed	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Passed	

THE HEAD DEPARTMENT)					
Axles (front)	Outer Left	Inner left	Inner Right	Outer Right	Steering Axle?
1	8			8	v.
2	9			9	
Comment:					

srake Lining/Pad Measurement (mm	1)
Axles (front)	

Axles (front)	Lining/Pad	Left	Rìght
1	Pad	6	6
2	Pad	7	7
Comment:			

Rotor Thickness or Drum Inside Diameter Measurement (mm)

Axles (front)	Rotor/Drum	Left	Right
11	Rator	24.15	24.55
2	Rotor	8.91	8.87

Inspection Comments:

Has this Vehicle been road tested?

When?

After Inspection

Name of the person who did the road test

Inspector Name:

MOHAMMAD YUSOF, MOHAMMAD ARIS

This Inspection Report was submitted to CVSE on 2023-Jan-02 09:30 PM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of The personal monitories on this content of the section and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MP at the Commercial Vehicle Safety Enforcement

CVSE0013

1/2/2023 9:30:41 PM



Ministry of Transportation and Infrastructure

Body Integrity Inspection Report

	nation		بهتا انکاک	ie Designate			Ale mopes
Designated Inspection Facility Num	ıber	S 5 8 3 8	Author	rized Inspecto	* Number		
	i	3131310			921C/2		
DIF Facility Name ABBOTSFORD TU			Inspec	tor Name	Pas YUSO		
Day Month Year	9 0	nspection Completion Date Month Month Year		tor Signature	as y ase		>
VEHICLE OWNER	Day	WORLT Year	NAME	NE DEDIL			
Name Zn: E	<i>_</i>	- 200	Name		LDER (if other than ov		
Address Reg 1	<u>+Cr js.</u>	rise LPD	Name	Au	C Areto		
<u>003 70</u>			Address	#31	1435 135	G (-)	
City NEW WE	Prov	BC PC 13/44	//Fity				-30
Tel# 604767						rov <u>B</u> e PC	VEH
· · · · · · · · · · · · · · · · · · ·	770	03	Tel#	77	2817184	0	
Vehicle Information	. :						
TYPE OF VEHICLE: 🛛 🖾 P	Passenger	Car MPV	☐ Truck		otorhome 🔲 Ta	axi 🗌 Bu	S
Licence Plate N/A Oc	dometer	96640 Year	201	Maka			
——————————————————————————————————————		6	32010	- Make	Horalu	Model _	we
Registration Number 13183	500	VIN/Serial #	2 FI Gi	FC1	Fir Cost	11.2	1117
am satisfied that this rebuilt moto	r vehicle is	the same as the one desc	ribed in the	record of reb	uilding 🖂	Yes \square	No
Requirements of Rebuildi	ng	Components	R C	VIM Reference Section	Components	RC	VIM Reference
hotographs prior to rebuilding	✓ Yes	STRUT	 	Jection	REAR STRUT TOWER	" "	Section 8 - 4 (b)
learly showing vehicle damage	25 .63	- Left		8 - 4	- Left		1 (6)
tructural Integrity Declaration Report	✓ Yes	- Right			- Right		1
	<u> </u>	HINGE (A) PILLAR			BUMPERS (Front/Rea	ar) L	8-5
Wheel Alignment Printout	✓ Yes	- Left		8-19	CROSSMEMBER		8 - 3 (c)
		- Right	!		HOOD		1 (-)
Welded and structural		CENTRE (B) PILLAR				1 1	8-1
components that require			<u> </u>		RAD SUPPORT		
votoction have been a contraction because the		- Left		8 - 19	RAD SUPPORT BODY		8-1
Protection have been protected	⊠ Yes	- Left - Right		8 - 19			8-1
s required by OEM or I-CAR	⊠ Yes			8 - 19	BODY		8-1
is required by OEM or I-CAR	⊠ Yes	- Right		8 - 19	BODY FRAME		8-1 8-2 8-3
is required by OEM or I-CAR tandard. Yehicle meets symmetric and	⊠ Yes	- Right LOCK (C) PILLAR			BODY FRAME BULKHEAD (cowl) DOORS		8-1 8-2 8-3
s required by OEM or I-CAR tandard. Tehicle meets symmetric and symmetric specifications as		- Right LOCK (C) PILLAR - Left			BODY FRAME BULKHEAD (cowl) DOORS QUARTER PANELS		8-1 8-2 8-3
s required by OEM or I-CAR tandard. Yehicle meets symmetric and symmetric specifications as andicated on the Structural	⊠ Yes	- Right LOCK (C) PILLAR - Left - Right ROCKER PANEL		8 - 19	BODY FRAME BULKHEAD (cowl) DOORS QUARTER PANELS - Left		8-1 8-2 8-3
s required by OEM or I-CAR tandard. Tehicle meets symmetric and symmetric specifications as andicated on the Structural		- Right LOCK (C) PILLAR - Left - Right ROCKER PANEL - Left			BODY FRAME BULKHEAD (cowl) DOORS QUARTER PANELS - Left - Right		8-1 8-2 8-3 8-6 8-2 (c)
s required by OEM or I-CAR tandard. Tehicle meets symmetric and symmetric specifications as andicated on the Structural ntegrity Declaration Report.		- Right LOCK (C) PILLAR - Left - Right ROCKER PANEL - Left - Right		8 - 19	BODY FRAME BULKHEAD (cowl) DOORS QUARTER PANELS - Left - Right FLOOR PAN	V	8-1 8-2 8-3 8-6 8-2 (c) 8-4 (a)
s required by OEM or I-CAR tandard. Yehicle meets symmetric and symmetric specifications as andicated on the Structural		- Right LOCK (C) PILLAR - Left - Right ROCKER PANEL - Left - Right	Spen	8 - 19	BODY FRAME BULKHEAD (cowl) DOORS QUARTER PANELS - Left - Right FLOOR PAN	rked when item	8-1 8-2 8-3 8-6 8-2 (c) 8-4 (a) rejected
/ehicle meets symmetric and isymmetric specifications as indicated on the Structural integrity Declaration Report.		- Right LOCK (C) PILLAR - Left - Right ROCKER PANEL - Left - Right	Spen	8 - 19	BODY FRAME BULKHEAD (cowl) DOORS QUARTER PANELS - Left - Right FLOOR PAN	V	8-1 8-2 8-3 8-6 8-2 (c) 8-4 (a) rejected
orotection have been protected as required by OEM or I-CAR standard. Vehicle meets symmetric and asymmetric specifications as indicated on the Structural integrity Declaration Report.		- Right LOCK (C) PILLAR - Left - Right ROCKER PANEL - Left - Right	Spen	8 - 19	BODY FRAME BULKHEAD (cowl) DOORS QUARTER PANELS - Left - Right FLOOR PAN	rked when item	8-1 8-2 8-3 8-6 8-2 (c) 8-4 (a) rejected
required by OEM or I-CAR standard. Wehicle meets symmetric and asymmetric specifications as andicated on the Structural entegrity Declaration Report.	✓ Yes	- Right LOCK (C) PILLAR - Left - Right ROCKER PANEL - Left - Right		8-19 8-19	BODY FRAME BULKHEAD (cowl) DOORS QUARTER PANELS - Left - Right FLOOR PAN - "R" ma. "C" ma	rked when item	8-1 8-2 8-3 8-6 8-2 (c) 8-4 (a) rejected
/ehicle meets symmetric and asymmetric specifications as indicated on the Structural integrity Declaration Report.	Yes Scanning Yes	- Right LOCK (C) PILLAR - Left - Right ROCKER PANEL - Left - Right		8-19 8-19	BODY FRAME BULKHEAD (cowl) DOORS QUARTER PANELS - Left - Right FLOOR PAN - "R" ma. "C" ma	rked when item	8-1 8-2 8-3 8-6 8-2 (c) 8-4 (a) rejected

DYNAMICAUTO CENTRE LID.

CNITHERS AVERAGE SO

Phone Number: 4 st. fog. 27 m For Number: 604-701-97m

The second of th	والرابين الجانيان ويحفر برائح والإنقاع كالمارات الجانب المتأراتها بقاطا والتؤافيا بالتاكم والتقارب الما	CAS AGREECT OURSELECTED	
	anst custainise	13:86	2/17 2022 1:02:05 PM
202. [22 V]			
y Libertser No.		Coded. icn:	2hgfc/f40gh112211
e service and	No. 6 Aug.	:	era c
		Water Fig.	

VEHICLE ALIGNMENT REPORT HONDA 2016, CIVIC All Monchs

Primary Angles		isiin:	Sectionic s		Tipal	
	* **			Max	Max	2 5,0049 (
	- chact	<u>£eā</u>		47	5 9"	The second second
Freed Cladines	Kanali Kanali	er og er	3.70	5.9°	5,45	
	Tubble .	- H	-0.3	9.2"	10,15	
T HI TAVE	1	Right	Commence of the second	0.55	0.20	0.1
	ž (řž	#35°	-0.794	0.100	0.04	
	३ भिद्र	Right	4. 1	-6. (√°	0.10%	0.65
			er ere	.0.759	0.15%	6.10
	1 144 mg	1. 4. 1.		-1.0 ^k	0.54	-1.7
	to were a	en in filming and	The second secon	-1.65	-(<u>1</u> 5°	1.2
10.12	***	£ 4/43		Or Carlotte	0.130	9.05
	To:	民動物	+43 ⁴⁹	1.00	0.150	13,05°
	The second secon	iest	ا المعالم على المعالمين المعالمين المعالمين المعالمين المعالمين المعالمين المعالمين المعالمين المعالمين المعالم	9.10°	0,30%	0.63
term of a contract of a major		ar Toronto en esperante de la companya		mental and the second of the s	mentenan da managarah dan mendalan da mend	4,00
高速1000 (1.15) · 图	y Angles		fritin.	Specif	acom com menonimum 26/10/14	Figal
10 miles		The second of the second of the second	and the second	Mac	Max.	(4541)
		多的情况	Edi	 One of the second second	read a broken is been independent of the state of the sta	(5.2)
* * * * * * * * * * * * * * * * * * *	A CONTRACTOR OF THE STATE OF	Kişli	t min 1921	to del ser in agrega a p	Printed to ref. march 44	14.7"
neduded Aug	les.	11:51		entreport	The state of the state of the same temperature and	the sea of the season of the s
**** * * * * * * * * * * * * * * * * * *	to defend the conductivity of according		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	to Marke the Especial	***** * *** *	14.60
第5章的特殊的 的 第	LECTON	1.41.	Company of the Compan	C D	tions as an initial cases of a stationary as	And the second s
		Kişli:	the second secon	0.7°	3.0%	
, * · · · · · · · · · · · · · · · ·	TIN .	2 A 1	And the second s	377	San s	the wholes beauty and had had a
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	en en menter en en en menter en	May be		3/4/19	42.19	
- 10 10 10 10 10 10 10 10 10 10 10 10 10	aow.	2 144 2 123 X	in the production of the second of the secon	entres son i escribbras son son son son son son son son son so	The A section of the	all area described at a form of the same department of the same depa
Access to the contract of the	enter en	Kindle	Markey or Art .	* endamning	STATE OF THE PARTY	
without		£1.smt	A comment of the second of the	entropologico de esta de distribuido que la elementa de la composição de	Maner J. M. W. P. Herbindhow A. Hart had been parametering and all the control of	The same of the sa
	المنافعة والمنافعة	Profession and a service		M. # lews pro	manufacture and an in-	teral (
izan Weat				the second state of the second second	er dan - ddC parke - er og parter men lift alle file for former light und appeal	the contract of their sections of the contract
• • • • • • • • • • • • • • • • • • • •		And the second second second second				mag _{in} a.
		1.06	والمدود والمدين الحارب والمدين والمحارب المحارب المدين والمدين المحارب المدين المحارب المحارب المحارب المدين ا المدين والمدين المدين المحارب	en e	and the second of the second s	E P
	TVE ST	Right	All the second or an area	w.elteners	Address on the later	
ing Spir Sel		1.021	The Billing of the tell and the transport and another transport to the continue of the second of the	min destruction and experience of the community of the destruction of the community of the	Part to arrange of tigan absolute and before and a factor	de altres de arrige es. La spein caprague a dalfera de la suddeste seculo e
	•	ARTON DAR	ter en e			****
		Hereas and the second and the second and the second	· .	The state of the s	er der er de stater kanner i in s	The second secon