



Vehicle History Report #: 40542952
 Report Date: July 9, 2022 | 12:01 PM EST
 Report Status: Complete
 Reference:

2015 MITSUBISHI RVR SE

Sport utility vehicle | 4 Cylinders | Gas
 4A4AJ3AU3FE605753
 Country of Assembly: United States
 Last Reported Odometer: 159,270 KM



No Accident/Damage Records Found



Last Registered In:
 Ontario (Normal)



3 Service Records Found



No U.S. History Found



4 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of July 09, 2022 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

There are no accidents/damage reported on this vehicle.



Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2016 Mar 24	31,722 KM	Active Green & Ross Sarnia, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Tire condition and pressure checked Four tires balanced Four tires mounted Alignment checked
2016 Apr 21	34,075 KM	Active Green & Ross Sarnia, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2021 Aug 11	159,270 KM	Midas Auto Service Experts Keswick, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Front brake rotor(s) replaced Front brake pads replaced Rear brake pads replaced



Open Recalls

Recall #: SR-17-005 | 2015 OUTLANDER SPORT / RVR - REPLACE (2) ELECTRICAL POWER CONTRO Recall Date: 2017 Sep 29

Recall Description

DUE TO AN INAPPROPRIATE MAINTENANCE PROCEDURE USED ON A WELDING MACHINE AT A RELAY SUPPLIER, WELDING OF COMPONENTS WITHIN THE RELAY MAY HAVE BEEN PERFORMED INCORRECTLY RESULTING IN IMPROPER ELECTRICAL CONDUCTION. AS A RESULT, ONE OF THE FOLLOWING CONDITIONS MAY OCCUR DEPENDING ON WHICH SYSTEM IS USING THE DEFECTIVE RELAY:-IF THE RELAY FOR THE ENGINE CONTROL UNIT FAILS, THE ENGINE WILL STALL WHILE DRIVING AND CANNOT BE RESTARTED.-IF THE RELAY FOR THE ENGINE VALVE LIFT CONTROL FAILS, THE ENGINE WARNING LAMP WILL ILLUMINATE AND FAIL-SAFE MODE WILL BE ACTIVATED, LIMITING AVAILABLE ENGINE POWER.-IF THE RELAY FOR THE RADIATOR FAN FAILS, THE ENGINE COOLANT TEMPERATURE WILL RISE, THE COOLANT TEMPERATURE WARNING LAMP WILL ILLUMINATE, AND THE ENGINE MAY OVERHEAT.

Remedy

OWNERS OF ALL AFFECTED VEHICLES WILL BE NOTIFIED AND ENCOURAGED TO BRING THEIR VEHICLES IN TO REPLACE THE RELAY WITH A

COUNTERMEASURE UNIT.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact MITSUBISHI or visit [Mitsubishi's website](#).

Recall #: SR-18-002 | REAR PARKING BRAKE - 4A MODELS **Recall Date:** 2018 Jan 26

Recall Description

(1) DUE TO INSUFFICIENT RUST PREVENTION TO THE SHAFT OF PARKING BRAKE AND INSUFFICIENT SEALING PERFORMANCE OF THE REAR BRAKE CALIPER BOOT, WATER MAY PENETRATE INSIDE THE CALIPER AND THE PARKING BRAKE OPERATING SHAFT, CAUSING THE CALIPER BODY AND THE SHAFT CORROSION. AS A RESULT, THE SHAFT MAY POTENTIALLY BECOME STUCK, CAUSING BRAKE DRAGGING AND/OR PARKING BRAKE PERFORMANCE DECREASING.(2) DUE TO INADEQUATE MANUFACTURING PROCESS, AUTOMATIC ADJUSTER FOR BRAKE PAD CLEARANCE OF THE REAR BRAKE CALIPER WITH BUILT-IN PARKING BRAKE MAY NOT WORK. IF THEY OCCUR SIMULTANEOUSLY, AS BRAKE PADS WEAR, INVALID STROKE OF PARKING BRAKE LEVER WILL INCREASE, FINALLY PARKING BRAKE WILL NOT WORK EVEN THOUGH THE LEVER IS FULLY OPERATED.

Remedy

OWNERS OF ALL AFFECTED VEHICLES WILL BE NOTIFIED AND ENCOURAGED TO BRING THEIR VEHICLES IN TO CHECK AND REPAIR THE REAR BRAKE. (1) IF CALIPER BODY IS FOUND TO BE CORRODED OR SHAFT IS FOUND TO BE STUCK, THE BRAKE CALIPER BODY ASSEMBLY WILL BE REPLACED WITH A COUNTERMEASURE UNIT. OTHERWISE, THE BOOT AND LEVER WILL BE REPLACED WITH A COUNTERMEASURE UNIT. (2) THE PISTON ASSEMBLY OF THE REAR BRAKE CALIPER WILL BE REPLACED WITH A COUNTERMEASURE UNIT.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact MITSUBISHI or visit [Mitsubishi's website](#).

Recall #: SR-18-004 | FRONT WIPER LINK REPLACEMENT **Recall Date:** 2018 Feb 09

Recall Description

IN THE EVENT THAT WATER DROPS DOWN THROUGH THE BACK SIDE OF THE FRONT DECK GARNISH (THE BODY PIECE BETWEEN THE HOOD AND WINDSHIELD), THE FRONT WIPER LINK BALL JOINT MAY EXPERIENCE EXCESSIVE MOISTURE AND CORRODE. IF THIS OCCURS, THE RESIN CASE OF THE BALL JOINT WILL WEAR PREMATURELY DUE TO THE BALL JOINT CORROSION AND THE WIPER LINK MAY ULTIMATELY SEPARATE CAUSING THE WINDSHIELD WIPERS TO STOP OPERATING.

Remedy

OWNERS OF ALL AFFECTED VEHICLES WILL BE NOTIFIED AND ENCOURAGED TO BRING THEIR VEHICLES IN TO REPLACE THE ROD OF WIPER LINK WITH A COUNTERMEASURE UNIT. THE WIPER MOTOR CRANK ARM WILL ALSO BE REPLACED WITH NEW ONE. THE REPAIR WILL BE PERFORMED AT NO CHARGE TO THE VEHICLE OWNERS. OWNERS SEEKING REIMBURSEMENT FOR ANY EXPENSES ASSOCIATED WITH THIS RECALL WILL BE DIRECTED IN THE NOTIFICATION LETTER TO CONTACT THE MITSUBISHI CUSTOMER RELATIONS DEPARTMENT FOR REIMBURSEMENT CONSIDERATION.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact MITSUBISHI or visit [Mitsubishi's website](#).

Recall #: SR-20-003 | FRT CROSSMEMBER CORROSION - 14MY &15MY OUTLANDER SPORT (4A) **Recall Date:** 2020 Jul 28

Recall Description

THE INSIDE AND OUTSIDE SURFACES OF THE FRONT CROSS MEMBERS USED ON CERTAIN VEHICLES, IF EXPOSED LONG TERM TO SNOWMELT WATER AND ANTI-FREEZING AGENTS, MAY CORRODE DUE TO INSUFFICIENT PERFORMANCE OF THE RUST PROTECTION. SHOULD SIGNIFICANT CORROSION OCCUR OVER TIME, A LOWER CONTROL ARM COULD EVENTUALLY BECOME DETACHED RESULTING IN LOSS OF VEHICLE CONTROL AND A POTENTIAL COLLISION.

Remedy

OWNERS OF ALL AFFECTED VEHICLES WILL BE NOTIFIED AND ENCOURAGED TO BRING IN THEIR VEHICLES FOR INSPECTION. THE CROSS MEMBER WILL BE INSPECTED AND THE FOLLOWING ACTION WILL BE TAKEN AT NO CHARGE TO THE CUSTOMER: (1) IF NO SIGNIFICANT CORROSION IS IDENTIFIED, A SEALING/ANTI-CORROSION AGENT WILL BE SPRAYED INSIDE/OUTSIDE THE CROSS MEMBER; (2) IN THE EVENT THAT SIGNIFICANT CORROSION IS IDENTIFIED, THE CROSS MEMBER WILL BE REPLACED WITH A COUNTERMEASURE CROSS MEMBER. OWNERS SEEKING REIMBURSEMENT FOR ANY EXPENSES ASSOCIATED WITH THIS RECALL WILL BE DIRECTED IN THE NOTIFICATION LETTER TO CONTACT THE MITSUBISHI CUSTOMER RELATIONS DEPARTMENT FOR INSTRUCTIONS ON HOW TO APPLY FOR A REFUND.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact MITSUBISHI or visit [Mitsubishi's website](#).

**Stolen Vehicle Check**

This vehicle is not actively declared stolen.

**Detailed History**

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 May 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2016 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Fleet
2016 Mar 24	31,722 KM	Active Green & Ross Sarnia, Ontario, Canada	Service Record	Vehicle serviced
2016 Apr 21	34,075 KM	Active Green & Ross Sarnia, Ontario, Canada	Service Record	Vehicle serviced
2016 Jun 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Dec 8	57,878 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	
2017 May 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Sep 29		MITSUBISHI	Recall	Manufacturer Recall Issued Recall # SR-17-005
2018 Jan 26		MITSUBISHI	Recall	Manufacturer Recall Issued Recall # SR-18-002

4A4AJ3AU3FE605753

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Feb 9		MITSUBISHI	Recall	Manufacturer Recall Issued Recall # SR-18-004
2018 Jun 7		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Jun 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 May 21		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 Jul 28		MITSUBISHI	Recall	Manufacturer Recall Issued Recall # SR-20-003
2021 Aug 11	159,270 KM	Midas Auto Service Experts Keswick, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© Copyright 2005 - 2022 CARFAX Canada ULC. All rights reserved.

