

Vehicle History Report #: 56633960
Report Date: October 3, 2024 | 11:48 a.m. EDT
Report Status: Complete

2017 VOLKSWAGEN GOLF S

Hatchback | 4 Cylinders | Gas 3VW217AU5HM054545 Country of Assembly: Mexico

Last Reported Odometer: 113,671 KM







Last Registered In: Ontario (Normal)



7 Service Records Found



No U.S. History Found



2 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.


Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of October 03, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

3VW217AU5HM054545

Vehicle History Report



INCIDENT DATE	DETAILS	AMOUNT
① 2018 Apr 12	Ontario, Canada	
	Police Reported Accident: Accident reported: minor damage with another motor vehicle	
	Damage to front	
① 2023 Nov 11	Hamilton, Ontario, Canada	
	Estimate: Not Available Estimate Date: 2023 Dec 4	\$4,927.42
1 2023 Nov 12	Ontario, Canada	
	Claim: Unknown	\$4,927.00



This vehicle has been registered in the province of Ontario in Canada with Normal branding.
We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2020 Feb 22	51,398 KM	Take 5 Oil Change	Vehicle serviced
		Hamilton, Ontario, Canada	Oil and filter changed
2020 Oct 20	62,623 KM	McPhail Auto Service and Sales	Vehicle serviced
		Mount Hope, Ontario, Canada	 Maintenance inspection completed
			 Oil and filter changed
			 Vehicle washed/detailed
			 Alignment checked
			 Antifreeze/coolant flushed/changed
			Cabin air filter replaced/cleaned
2020 Dec 3	65,256 KM	McPhail Auto Service and Sales	Vehicle serviced
		Mount Hope, Ontario, Canada	Wiper(s) replaced
2020 Dec 16	66,146 KM	McPhail Auto Service and Sales	Vehicle serviced
		Mount Hope, Ontario, Canada	Tire repaired
2021 Apr 26	72,577 KM	McPhail Auto Service and Sales	Vehicle serviced
		Mount Hope, Ontario, Canada	 Maintenance inspection completed
		, , , , , , , , , , , , , , , , , , , ,	Oil and filter changed
			 Vehicle washed/detailed
			Tire(s) changed
			 Alignment checked

3VW217AU5HM054545

DATE	ODOMETER	SOURCE	DETAILS
2021 Jul 6	75,877 KM	McPhail Auto Service and Sales Mount Hope, Ontario, Canada	Vehicle serviced
2024 Sep 3	113,671 KM	Economy Lube Oil & Filter Hamilton, Ontario, Canada	Vehicle serviced • Tire condition and pressure checked



Recall #: 37L5 | MICROSWITCH Recall Date: 2018 Jul 25

Recall Description

Over time, a build-up of silicate on the shift lever micro switch contacts can make it possible to remove the key from the ignition switch without the shift lever being in the "P" Park position. This makes the vehicle noncompliant with 49 CFR 571.114 Standard No. 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in the "P" Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.

Remedy

Install an additional switch and circuit board.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit Volkswagen's website.

(https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)

Recall #: 20UF | SUCTION JET PUMP Recall Date: 2024 Feb 16

Recall Description

The suction jet pump inside the fuel tank is designed to purge fuel from the Evaporative Emissions (EVAP) system. If a specific seal inside an affected suction jet pump fails, the fuel may flow directly into the EVAP system. If this happens, fuel could accumulate in the EVAP system and may leak through the charcoal canister filter element. Leaking fuel, in the presence of an ignition source, may result in a fire.

Remedy

Replace the suction jet pump.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit Volkswagen's website.

(https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

This vehicle is not actively declared stolen.



3VW217AU5HM054545

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2023 Dec 4	108,788 KM	Insurance Records Hamilton, Ontario, Canada	Estimate Repair	Incident Date: 2023-11-11 Not Available
2024 Feb 16		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 20UF
2024 Jul 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2024 Sep 3	113,671 KM	Economy Lube Oil & Filter Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2024 Sep 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as blue



CARFAX Canada Low Kilometres™ Badge
The CARFAX Canada Low Kilometres™ badge is based on the odometer information reported to CARFAX Canada. The CARFAX Canada Low Kilometres™ badge is available for vehicles registered in Canada that have accumulated, as reported to CARFAX Canada via odometer records, less than 18,000 kilometres per year from the beginning of September in the year prior to the vehicle's model year until the date that this report was generated.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada. https://ww

© 2024 CARFAX Canada ULC. All rights reserved.

