

Vehicle History Report #: 49855175
Report Date: November 21, 2023 | 2:26 PM EST
Report Status: Complete
Reference:

2016 CHEVROLET SILVERADO K1500 LTZ

Pickup | 8 Cylinders | Gas 3GCUKSEC3GG349959 Country of Assembly: Mexico Last Reported Odometer: 95,774 KM





Last Registered In: Ontario (Normal)



1 Service Record Found







Not Actively Declared Stolen



No Import Record Found


Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of November 21, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



INCIDENT DATE	DETAILS	
1 2023 Jul 19 Thunder Bay, Ontario, Canada		
	Estimate: Total Loss Estimate Date: 2023 Jul 24	\$26,723.99
	Claim: Collision	(\$11,419.00)



Registration



This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2020 Apr 2	53,528 KM	Narvi's Auto Service Thunder Bay, Ontario, Canada	Vehicle serviced • Tire(s) balanced • Tire(s) mounted



Open Recalls

Recall #: N192220470 | Power Sliding Rear Window Defroster Failures (Canada Only) Recall Date: 2019 Jun 27

Recall Description

General Motors has approved a safety recall in Canada for certain 2014-2019 model year Chevrolet Silverado and GMC Sierra vehicles equipped with a power sliding rear window (RPO A48). In some of these vehicles, areas of high electric resistance on the rear defroster circuit, caused, in part, by mechanical stress from opening and closing the rear power window, intrusion of debris, and use of the rear defroster may, over time, generate heat which could melt the areas surrounding the circuit. In rare instances, this heat could cause a non-propagating fire, increasing the risk of property damage or injury.

Remedy

Dealers will replace the buss bar covers and the contact cover, and for certain vehicles, will reprogram the HVAC calibration to disable the rear defroster from automatically turning on at keyed start. Please note that the rear defroster will automatically turn on during remote start or by pushing the manual button and is not affected by this calibration. If the rear window or sliding glass assembly appears damaged due to an occurrence of high electrical resistance on the rear defroster circuit, they will also be replaced.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit GM's website.

Recall #: N192217410 | Reduction in Vacuum Brake Assist - Canada Only Recall Date: 2019 Jun 27

Recall Description

General Motors has approved a safety recall in Canada for certain 2017 model year Chevrolet Silverado LD, GMC Sierra LD, Cadillac Escalade, Chevrolet Suburban, Chevrolet Tahoe, and GMC Yukon vehicles, that, in some circumstances, may have a condition in which the enginemounted mechanical vacuum pump output may decrease over time, decreasing the amount of vacuum/power brake assist. If the vacuum level drops, customers may experience increased brake pedal effort, hard brake pedal, and/or potentially increased stopping distance. The Driver's Information Centre (DIC) "Service brake assist" alert will activate 2-5 minutes after the vacuum level drops, and a Diagnostic Trouble Code (DTC) will also be set. Even where this condition occurs, the hydraulic brake system remains functional. The condition is more prevalent at low speed when softly applying the brakes. Failure to follow recommended oil change intervals could contribute to this condition.

Remedy

Dealers are to reprogram the electronic brake control module (EBCM).

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit **GM's website**.



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Jul 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as black
2016 Sep 9		CHEVROLET	Recall	Manufacturer Recall Issued Recall # 2016007
2017 Aug 21		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Aug 21		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Jun 27		CHEVROLET	Recall	Manufacturer Recall Issued Recall # N192217410
2019 Jun 27		CHEVROLET	Recall	Manufacturer Recall Issued Recall # N192220470
2019 Aug 21		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 Apr 2	53,528 KM	Narvi's Auto Service Thunder Bay, Ontario, Canada	Service Record	Vehicle serviced
2021 Jan 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black
2022 Aug 21		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2023 Jul 19		Insurance Records		
		Ontario, Canada		
2023 Jul 19	95,774 KM	Insurance Records	Estimate Repair	Estimate Date: 2023-07-24
		Thunder Bay, Ontario, Canada		Total Loss
2023 Aug 15		Motor Vehicle Dept.	Canadian Renewal	New Owner reported
		Ontario, Canada		Vehicle colour noted as black
2023 Oct 10		Motor Vehicle Dept.	Canadian Renewal	New Owner reported
		Ontario, Canada		Vehicle colour noted as black



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantablity, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada. Conditions of Use and any CARFAX Canada and User License Agreements as each may be amended from time to time by CARFAX Canada. Conditions of Use

© 2023 CARFAX Canada ULC. All rights reserved.

