



Vehicle History Report #: 35418942
Report Date: September 15, 2021 | 02:29 PM EST
Report Status: Complete

2014 RAM 2500 ST

Pickup | 8 Cylinders | Gas
3C6LR4AT2EG167814
Country of Assembly: Mexico
Last Reported Odometer: 131,677 KM



No Accident/Damage Records Found




Last Registered In: Ontario (Normal)



5 Service Records Found



No U.S. History Found



5 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.
1.866.835.8612 | support.carfax.ca



This vehicle history report is based on information that was reported and available to CARFAX Canada as of September 15, 2021 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

✓ There are no accidents/damage reported on this vehicle.



Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

| DATE | ODOMETER | SOURCE | DETAILS |
|-------------|------------|---|--|
| 2014 Jan 6 | | Krown London - North London, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Undercoating/rustproofing applied |
| 2014 Mar 28 | 8,161 KM | WOODSTOCK CHRYSLER Woodstock, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Fluids checked |
| 2015 Aug 27 | 57,919 KM | WOODSTOCK CHRYSLER Woodstock, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> ABS/TCS module reprogrammed Exhaust system checked Fluids checked Oil and filter changed Outside mirror replaced/repared Running boards/tubes/steps installed |
| 2017 Jun 5 | 114,749 KM | steve's Automotive Ltd. Woodstock, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed |
| 2017 Dec 1 | 131,677 KM | WOODSTOCK CHRYSLER Woodstock, Ontario, Canada | Vehicle serviced |



Open Recalls

Recall #: U61 | REPROGRAM POWERTRAIN CONTROL MODULE Recall Date: 2018 Jun 26

Recall Description

The fault handling strategy of the Engine Control Module (ECM) or PCM software in the affected vehicles does not remove positive torque requests from the engine controller if the CAN-C bus stops communicating while the cruise control is requesting positive torque.

Remedy

Inspect the software level of the ECM/PCM and, if necessary, perform a software flash on the ECM/PCM of affected vehicles to improve the fault handling so that if the CAN-C bus does stop communicating any active torque requests will be cleared

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](#).

Recall #: T79 | BRAKE TRANSMISSION SHIFT INTERLOCK Recall Date: 2018 Jan 04

Recall Description

The Brake Transmission Shift Interlock (BTSI) locking pin may become stuck in the open position. A BTSI locking pin stuck in the open position may allow the transmission to be shifted out of PARK and to or from any gear position without depression of the brake pedal and/or without the key in the ignition, if a key is applicable.

Remedy

For 2013-2017 model year; Inspect the Brake Transmission Shift Interlock (BTSI) operation and replace if necessary. The Body Control Module (BCM) software will also be updated. For 2009-2012 model year; replace the BTSI, BCM software update not applicable.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](#).

Recall #: T25 | OCCUPANT RESTRAINT CONTROL MODULE Recall Date: 2017 Jun 22

Recall Description

THE OCCUPANT RESTRAINT CONTROL MODULE MAY ACTIVATE A DIAGNOSTIC TROUBLE CODE (DTC) DUE TO EXTERNAL STIMULUS WHICH DISABLES ITS ABILITY TO SENSE VEHICLE ROLLOVER EVENTS. WHEN THE DTC IS SET, AIRBAG AND SEAT BELT PRETENSIONER DEPLOYMENT BASED ON ROLLOVER SENSING IS DISABLED FOR THE IGNITION CYCLE IN WHICH THE DTC WAS SET.

Remedy

THE ORC MODULE ON INVOLVED VEHICLES MUST BE REPROGRAMMED WITH NEW SOFTWARE.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](#).

Recall #: R46 | FRONT SUSPENSION TRACK BAR FRAME BRACKET Recall Date: 2015 Oct 02

Recall Description

SOME OF THE VEHICLES MAY HAVE A FRONT SUSPENSION TRACK BAR FRAME BRACKET THAT WAS IMPROPERLY WELDED DURING THE MANUFACTURING PROCESS. THE FRONT SUSPENSION TRACK BAR FRAME BRACKET WELDS MAY BREAK AND ALLOW THE FRONT SUSPENSION TRACK BAR FRAME BRACKET TO SEPARATE FROM THE FRAME RAIL.

Remedy

THE FRONT SUSPENSION TRACK BAR BRACKET MUST BE INSPECTED FOR CRACKED WELDS. TRACK BAR BRACKETS WITHOUT CRACKED WELDS WILL HAVE REINFORCEMENT BRACKETS INSTALLED. HOWEVER, THE TRACK BAR REINFORCEMENT BRACKETS ARE CURRENTLY NOT AVAILABLE. FCA WILL CONTACT YOU AGAIN BY MAIL, WITH A FOLLOW-UP RECALL NOTICE, WHEN THE PARTS ARE AVAILABLE. TRACK BAR BRACKETS FOUND WITH CRACKED WELDS WILL HAVE NEW TRACK BAR BRACKETS WELDED TO THE FRAME. WELDING NEW BRACKETS TO THE FRAME WILL REMEDY THE CONDITION AND YOU WILL NOT BE CONTACTED AGAIN BY FCA REGARDING THIS ISSUE.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](#).

Recall #: R36 | STEERING WHEEL WIRING Recall Date: 2015 Sep 04

Recall Description

THE STEERING WHEEL WIRE HARNESS MAY BECOME CHAFFED BY THE DRIVER AIRBAG MODULE RETAINER SPRING ENDS.

Remedy

THE STEERING WHEEL WIRE HARNESS WILL BE INSPECTED, AND IF NEEDED REPAIRED. THE STEERING WHEEL WIRE HARNESS WILL BE REROUTED AND SECURED TO PREVENT WIRE CHAFFING AND PROTECTIVE CAPS WILL BE INSTALLED ONTO THE AIRBAG RETAINER SPRING ENDS.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](#).



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

| DATE | ODOMETER | SOURCE | RECORD TYPE | DETAILS |
|-------------|------------|---|------------------|--|
| 2014 Jan 2 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | First Owner Reported |
| 2014 Jan 2 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed |
| 2014 Jan 2 | | Motor Vehicle Dept. Ontario, Canada | Previous use | Commercial |
| 2014 Jan 6 | | Krown London - North London, Ontario, Canada | Service Record | Vehicle serviced |
| 2014 Mar 28 | 8,161 KM | WOODSTOCK CHRYSLER Woodstock, Ontario, Canada | Service Record | Vehicle serviced |
| 2014 Nov 1 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed |
| 2014 Nov 1 | | Motor Vehicle Dept. Ontario, Canada | Previous use | Commercial |
| 2015 Aug 27 | 57,919 KM | WOODSTOCK CHRYSLER Woodstock, Ontario, Canada | Service Record | Vehicle serviced |
| 2015 Sep 4 | | RAM | Recall | Manufacturer Recall Issued Recall # R36 |
| 2015 Oct 2 | | RAM | Recall | Manufacturer Recall Issued Recall # R46 |
| 2015 Nov 1 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed |
| 2015 Nov 1 | | Motor Vehicle Dept. Ontario, Canada | Previous use | Commercial |
| 2016 Nov 1 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed |
| 2016 Nov 1 | | Motor Vehicle Dept. Ontario, Canada | Previous use | Commercial |
| 2017 Jun 5 | 114,749 KM | steve's Automotive Ltd. Woodstock, Ontario, Canada | Service Record | Vehicle serviced |
| 2017 Jun 22 | | RAM | Recall | Manufacturer Recall Issued Recall # T25 |
| 2017 Nov 1 | | Motor Vehicle Dept. | Canadian Renewal | Registration Issued or |

| | | | | |
|-------------|------------|--|------------------|--|
| | | Ontario, Canada | | Renewed |
| 2017 Nov 1 | | Motor Vehicle Dept. Ontario, Canada | Previous use | Commercial |
| 2017 Dec 1 | 131,677 KM | WOODSTOCK CHRYSLER Woodstock, Ontario, Canada | Service Record | Vehicle serviced |
| 2018 Jan 4 | | RAM | Recall | Manufacturer Recall Issued Recall # T79 |
| 2018 Jun 26 | | RAM | Recall | Manufacturer Recall Issued Recall # U61 |
| 2018 Nov 1 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed |
| 2018 Nov 1 | | Motor Vehicle Dept. Ontario, Canada | Previous use | Commercial |



Questions? We're here to help.

1.866.835.8612 | support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© Copyright 2005 - 2021 CARFAX Canada ULC. All rights reserved.

