



Vehicle History Report #: 50953979
Report Date: January 25, 2024 | 4:52 PM EST
Report Status: Complete

2019 GMC SIERRA

1GTU9CED3KZ346675

Country of Assembly: n/a

Last Reported Odometer: 208,462 KM



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



10 Service Records Found



No U.S. History Found



4 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.
Visit us at support.carfax.ca





This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of January 25, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

1GTU9CED3KZ346675

INCIDENT DATE	DETAILS	AMOUNT
 2019 Dec 8	Ontario, Canada	
	Police Reported Accident: Accident reported: moderate damage with another motor vehicle Damage to left front	
 2019 Dec 9	Ontario, Canada	
	Claim: Collision	\$2,273.00



Registration

 This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2020 May 26	43,467 KM	steve's Automotive Ltd. Woodstock, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Brake pad sensor(s) replaced • Vehicle washed/detailed • Tire condition and pressure checked • Tires rotated • Brakes checked
2021 Jan 4	83,650 KM	steve's Automotive Ltd. Woodstock, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Air filter replaced • Fluids checked • Oil and filter changed • Vehicle washed/detailed
2021 Apr 14	97,950 KM	steve's Automotive Ltd. Woodstock, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed • Vehicle washed/detailed • Tire condition and pressure checked • Tires rotated
2021 Aug 19	117,991 KM	steve's Automotive Ltd. Woodstock, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed • Vehicle washed/detailed • Four wheel alignment performed • Four tires balanced • Four tires mounted • Brakes checked
2021 Dec 15	140,673 KM	steve's Automotive Ltd. Woodstock, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Serpentine belt replaced • Fluids checked • Oil and filter changed • Vehicle washed/detailed • Wiper(s) replaced

1GTU9CED3KZ346675

	ODOMETER	SOURCE	DETAILS
2022 Feb 12	152,410 KM	Take 5 Oil Change Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2022 Mar 8	153,902 KM	steve's Automotive Ltd. Woodstock, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Valve cover gasket(s) replaced Induction system checked PCV hose replaced Vehicle washed/detailed Tire condition and pressure checked Tires rotated
2022 Apr 13	161,725 KM	steve's Automotive Ltd. Woodstock, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Alternator checked Vehicle washed/detailed Battery/charging system checked
2022 May 30	174,836 KM	Jiffy Lube London, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2023 Nov 8	208,462 KM	steve's Automotive Ltd. Woodstock, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Cylinder head gasket(s) replaced Antifreeze/coolant flushed/changed



Open Recalls

Recall #: N192268090 | Brake System Malfunction Warning Recall Date: 2019 Dec 12

Recall Description

General Motors has decided that certain 2019 model year Cadillac CT6, Chevrolet Silverado 1500, and GMC Sierra 1500 vehicles may fail to conform to S5.3 of Federal Motor Vehicle Safety Standard (FMVSS) No. 126, "Electronic stability control systems for light vehicles" and S5.1 of FMVSS 135, "Light vehicle brake systems." In these vehicles, a software error can, in rare cases, disable the vehicle's electronic stability control (ESC) and antilock brake system (ABS) systems for a single ignition cycle. If this specific error occurs, the vehicle's diagnostics will not illuminate the vehicle's ESC and ABS telltale lamps, as required by S5.3 of FMVSS 126 and S5.1 of FMVSS 135.

Remedy

Dealers will reflash the EBCM.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact GMC or visit [GM's website](#).

Recall #: N192270600 | Seatbelt Pretensioner Fire Recall Date: 2019 Nov 14

Recall Description

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2019 – 2020 model-year Chevrolet Silverado and GMC Sierra 1500 vehicles and in certain 2020 model-year Chevrolet Silverado and GMC Sierra 2500/3500 vehicles built with carpet floor covering (RPO B30). In certain crashes that cause the front seatbelt pretensioners to deploy, the exhaust from the deployed pretensioner may be diverted through an opening in the pretensioner bracket and ignite cotton fibers in the carpet floor near the B-pillar. Following a crash that causes the seatbelt pretensioner to deploy, a fire may develop in the area near the B-pillar, which may increase the risk of injury.

1GTU9CED3KZ346675

Remedy

Dealers will install a feature that will close off the opening in the pretensioner bracket so that exhaust gasses vent away from carpet material as designed.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact GMC or visit [GM's website](#).

Recall #: N202314670 | Front Center Seat Belt May Not Be Attached Recall Date: 2020 Dec 17

Recall Description

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2019 – 2021 model year Chevrolet Silverado 1500 and GMC Sierra 1500 vehicles; 2020 – 2021 model year Chevrolet Silverado 2500/3500 and GMC Sierra 2500/3500 vehicles; and certain 2021 model year Chevrolet Suburban, Tahoe, and GMC Yukon XL vehicles equipped with a front-row center seating position. In these vehicles, the seat supplier may have failed to secure the seat-belt brackets to the seat frame in the front-row center seating position. If a seat-belt bracket is not secured, the seat belt may not properly restrain an occupant in the front-row center seat position, increasing the risk of occupant injury in a crash or high-speed braking event.

Remedy

Dealers will inspect left-side and right-side front-row center seat-belt bracket attachments and reassemble if necessary.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact GMC or visit [GM's website](#).

Recall #: N192273510 | Loose Alternator Cable Recall Date: 2019 Dec 12

Recall Description

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2019 – 2020 model-year Chevrolet Silverado 1500 and GMC Sierra 1500 vehicles. The B+ battery cable rings in these vehicles may have been contaminated with glue residue at the supplier. During normal vehicle operation, the glue may soften and cause the nut that attaches the B+ battery cable to the alternator to loosen over time, which could lead to an intermittent electrical connection or arcing. During the supplier's assembly process, excess glue may not have been completely removed from the B+ battery cable rings, resulting in glue contamination that could affect the joint connection between the cable ring and the alternator. An intermittent electrical connection between the B+ battery cable and the alternator could cause the vehicle to stall. The intermittent connection could also lead to arcing, which could generate sufficient heat to damage surrounding material and increase the risk of a fire.

Remedy

Dealers will inspect the vehicle with a black light for the presence of glue or other contamination at the B+ cable attachment to the alternator. If necessary, dealers will clean the connection and reattach the B+ cable connection. If arcing has damaged the cable, nut, or alternator, the dealer will replace the damaged components.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact GMC or visit [GM's website](#).

**Stolen Vehicle Check**

✓ This vehicle is not actively declared stolen.

1GTU9CED3KZ346675



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Nov 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Commercial Vehicle colour noted as gray
2019 Nov 14		GMC	Recall	Manufacturer Recall Issued Recall # N192270600
2019 Dec 8		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> • moderate damage • with another motor vehicle • Damage to left front
2019 Dec 9		Insurance Records Ontario, Canada		
2019 Dec 12		GMC	Recall	Manufacturer Recall Issued Recall # N192268090
2019 Dec 12		GMC	Recall	Manufacturer Recall Issued Recall # N192273510
2020 May 26	43,467 KM	steve's Automotive Ltd. Woodstock, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 12		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2020 Dec 17		GMC	Recall	Manufacturer Recall Issued Recall # N202314670
2021 Jan 4	83,650 KM	steve's Automotive Ltd. Woodstock, Ontario, Canada	Service Record	Vehicle serviced
2021 Apr 14	97,950 KM	steve's Automotive Ltd. Woodstock, Ontario, Canada	Service Record	Vehicle serviced
2021 Aug 19	117,991 KM	steve's Automotive Ltd. Woodstock, Ontario, Canada	Service Record	Vehicle serviced
2021 Dec 15	140,673 KM	steve's Automotive Ltd. Woodstock, Ontario, Canada	Service Record	Vehicle serviced
2022 Feb 12	152,410 KM	Take 5 Oil Change Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2022 Mar 8	153,902 KM	steve's Automotive Ltd. Woodstock, Ontario, Canada	Service Record	Vehicle serviced
2022 Apr 13	161,725 KM	steve's Automotive Ltd. Woodstock, Ontario, Canada	Service Record	Vehicle serviced
2022 May 30	174,836 KM	Jiffy Lube London, Ontario, Canada	Service Record	Vehicle serviced

1GTU9CED3KZ346675

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2023 Jan 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as gray
2023 Nov 8	208,462 KM	steve's Automotive Ltd. Woodstock, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© 2024 CARFAX Canada ULC. All rights reserved.

