

Vehicle History Report #: 44655006 Report Date: March 8, 2023 | 2:04 PM EST

Report Status: Complete

2005 HONDA PILOT EXL

Sport utility vehicle | 6 Cylinders | Gas 5FNYF18565B023427

Country of Assembly: United States Last Reported Odometer: 117,474 KM





No Accident/Damage Records Found



Last Registered In: Ontario (Normal)



16 Service Records Found



U.S. History Found



4 Open Recalls Found



Not Actively Declared Stolen



Import Record Found


Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of March 08, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report





Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

This vehicle has been registered in the state of **Michigan** in the **United States**. No major title problems were reported.

We checked for: Salvage, Junk, Rebuilt, Fire, Flood, Hail and Lemon.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2009 Sep 8	44,196 KM	Service Facility	Vehicle serviced
·		·	Oil and filter changed
			Tire condition and pressure checked
			POTENTIAL ODOMETER ROLLBACK
2010 Mar 18	46,545 KM	Service Facility	Vehicle serviced
		ŕ	Oil and filter changed
			Tire condition and pressure checked
			Brakes checked
2012 Oct 24		Cotter's Auto Shop	Vehicle serviced
		Nepean, Ontario, Canada	Undercoating/rustproofing applied
		Trepean, ontaine, canada	3 1 3 11
2016 Jul 27	85,812 KM	Hinton Automotive Limited -	Vehicle serviced
		Walgreen	 Maintenance inspection completed
		Carp, Ontario, Canada	Rear brake rotor(s) replaced
			Rear brake pads replaced Prologo coming the second replaced
			Brakes servicedFront brake pads replaced
			Tire condition and pressure checked
			Four tires balanced
			Four tires mounted
			Exhaust system checked
			Brakes checked
			POTENTIAL ODOMETER ROLLBACK
2017 Dec 2	97,433 KM	Jiffy Lube #3510	Vehicle serviced
	,	Nepean, Ontario, Canada	Maintenance inspection completed
		repearl, oritario, cariada	Oil and filter changed
			Antifreeze/coolant flushed/changed
			 Cooling system serviced
			 Fluids checked
			 Emissions system serviced
			Drivability/performance checked
			Emissions inspection performed
2018 Mar 20	99,018 KM	Service Facility	Vehicle serviced
			Power steering fluid flushed/changed
2018 Apr 28	99,799 KM	Jiffy Lube #3510	Vehicle serviced
2010 Apr 20	JJ, I JJ IXIVI	* *	Maintenance inspection completed
		Nepean, Ontario, Canada	Oil and filter changed
			Fluids checked
2018 Jun 16	100,941 KM	Jiffy Lube #3510	Vehicle serviced
3 ··· · -	,	Nepean, Ontario, Canada	Fluids checked
		repear, ortailo, cariada	Transmission fluid changed
			Fuel injection system flushed/serviced



Open Recalls

Recall #: S51 | LIGHTING SWITCH HARNESS WEAR Recall Date: 2012 Aug 31

Recall Description

HONDA IS RECALLING CERTAIN MODEL YEAR 2002 THROUGH 2004 CR-V; MODEL YEAR 2003 THROUGH 2005 PILOT; AND MODEL YEAR 2002 AND 2003 CIVIC VEHICLES. IN MARCH 2012, HONDA FILED A DEFECT REPORT TO RECALL CERTAIN MODEL YEAR 2002 THROUGH 2004 CR-V AND CERTAIN MODEL YEAR 2003 PILOT VEHICLES. IN AUGUST 2012, HONDA INFORMED THE AGENCY THAT IT WAS INCLUDING AN ADDITIONAL 820,789 VEHICLES INCLUDING CERTAIN MODEL YEAR 2004 AND 2005 PILOTS AND MODEL YEAR 2002 AND 2003 CIVICS. THE TOTAL NUMBER OF VEHICLES BEING RECALLED IS NOW 1,375,217. DUE TO TENSION FROM THE COMBINATION SWITCH WIRING HARNESS, WEAR ON THE SURFACE OF THE ELECTRICAL TERMINAL CAN OCCUR, YIELDING COPPER OXIDE, WHICH INCREASES ELECTRICAL RESISTANCE. INCREASED ELECTRICAL RESISTANCE MAY CAUSE THE TERMINAL ENDS TO MELT WITHIN THE WIRING HARNESS CONNECTOR.

Remedy

HONDA WILL NOTIFY OWNERS, AND DEALERS WILL REPAIR THE LOW BEAM TERMINAL HARNESS OR REPLACE THE LIGHTING SWITCH AS NECESSARY, FREE OF CHARGE. THE ORIGINAL RECALL BEGAN IN APRIL 2012. OWNERS OF VEHICLES INVOLVED IN THE SEPTEMBER 2012 EXPANSION WILL BE NOTIFIED IN SEPTEMBER 2012. OWNERS MAY CONTACT HONDA CUSTOMER SERVICE AT 1-800-999-1009.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed,

please contact HONDA or visit Honda's website.

Recall #: S87 | VSA MODULE GROUND FAILURE Recall Date: 2013 Mar 14

Recall Description

HONDA IS RECALLING CERTAIN MODEL YEAR 2005 PILOT VEHICLES MANUFACTURED JULY 29, 2004, THROUGH AUGUST 29, 2005; MODEL YEAR 2005-2006 ACURA MDX VEHICLES MANUFACTURED SEPTEMBER 16, 2004, THROUGH SEPTEMBER 22, 2005; AND MODEL YEAR 2005 ACURA RL VEHICLES MANUFACTURED MARCH 1, 2004, THROUGH JUNE 29, 2005. AN ELECTRICAL CAPACITOR MAY HAVE BEEN DAMAGED DURING THE MANUFACTURING OF THE VEHICLE STABILITY ASSIST (VSA) CONTROL MODULE CAUSING INTERMITTENT, AUTOMATIC, MINOR BRAKE APPLICATION. HOWEVER, IF THE DRIVER APPLIES THE BRAKES WHILE THE VSA IS MALFUNCTIONING, THE VEHICLE MAY COME TO AN ABRUPT STOP. ADDITIONALLY, DUE TO A LOOSE GROUND CONNECTION, CERTAIN MODEL YEAR 2005 PILOTS HAVE A VSA SYSTEM THAT MAY APPLY PARTIAL BRAKE FORCE, WITHOUT THE ILLUMINATION OF THE BRAKE LIGHTS, WHETHER OR NOT THE DRIVER IS USING THE BRAKES.

Remedy

OWNERS WILL BE NOTIFIED AND INSTRUCTED TO TAKE THEIR VEHICLES TO A DEALER OF THEIR RESPECTIVE BRAND. THE DEALER WILL INSTALL A PARTIAL WIRING HARNESS CONTAINING A CAPACITOR FOR THE VSA MODULATOR, FREE OF CHARGE. THE AFFECTED MODEL YEAR 2005 PILOTS WILL HAVE THEIR GROUND CONNECTION TIGHTENED. THE RECALL BEGAN ON APRIL 22, 2013. HONDA OWNERS MAY CONTACT HONDA AUTOMOBILE CUSTOMER SERVICE AT 1-888-234-2138 OR GO TO WWW.RECALLS.HONDA.COM; ACURA OWNERS MAY CONTACT 1-800-382-2238, AND SELECT OPTION 4, OR GO TO WWW.RECALLS.ACURA.COM.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HONDA or visit Honda's website.

Recall #: JR4 | PILOT DRIVER AIRBAG Recall Date: 2015 Jun 09

Recall Description

HONDA IS CONDUCTING THIS RECALL BECAUSE IT HAS DETERMINED A DEFECT MAYEXIST IN THE DRIVER'S FRONT AIRBAG INFLATOR.

Remedy

PLEASE CALL ANY AUTHORIZED HONDA DEALER AND MAKE AN APPOINTMENT TO HAVE YOUR VEHICLE REPAIRED. YOUR DEALER WILL REPLACE THE DRIVER'S FRONT AIRBAG INFLATOR WITH AN INFLATOR OF A DIFFERENT DESIGN, FREE OF CHARGE. FOR ADDITIONAL INFORMATION AND ASSISTANCE IN LOCATING A HONDA DEALER, PLEASE VISIT WWW.RECALLS.HONDA.COM OR CONTACT HONDA AUTOMOBILE CUSTOMER SERVICE AT 1-888-234-2138. HONDA'S CAMPAIGN NUMBER FOR THIS RECALL IS JR4.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HONDA or visit **Honda's website**.

Recall #: KD9 | Passenger Airbag Inflator Recall Date: 2017 Jan 11

Recall Description

AMERICAN HONDA MOTOR CO., INC. (HONDA) IS RECALLING CERTAIN MODEL YEAR 2009-2011 ELEMENT AND 2009-2013 RIDGELINE VEHICLES. THE PASSENGER FRONTAL AIRBAG INFLATOR IN YOUR VEHICLE MAY RUPTURE WHEN DEPLOYING DURING A CRASH. THE POTENTIAL FOR SUCH RUPTURES MAY OCCUR IN SOME OF THE SUBJECT AIRBAG INFLATORS AFTER SEVERAL YEARS OF EXPOSURE TO

PERSISTENT CONDITIONS OF HIGH ABSOLUTE HUMIDITY. HONDA SUGGESTS THAT YOU AVOID HAVING A PASSENGER SIT IN THE FRONT PASSENGER'S SEAT UNTIL THE RECALL REPAIR HAS BEEN PERFORMED.

Remedy

PLEASE CALL ANY AUTHORIZED HONDA DEALER AND MAKE AN APPOINTMENT TO HAVE YOUR VEHICLE REPAIRED. YOUR DEALER WILL REPLACE THE PASSENGER'S FRONT AIRBAG INFLATOR WITH AN INFLATOR OF A DIFFERENT DESIGN, FREE OF CHARGE. FOR ADDITIONAL INFORMATION AND ASSISTANCE IN LOCATING A HONDA DEALER, PLEASE VISIT WWW.RECALLS.HONDA.COM OR CONTACT HONDA AUTOMOBILE CUSTOMER SERVICE AT 1-888-234-2138. HONDA'S CAMPAIGN NUMBER FOR THIS RECALL IS GOI.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HONDA or visit **Honda's website**.



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

	DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
	2005 Mar 23		Motor Vehicle Dept.	DMV Record	Title or registration issued
			Michigan, United States	Adjustment	First Owner Reported
			-	•	Previous Use: Personal lease
2005 De	2005 Dec 22		Motor Vehicle Dept.	DMV Record	Title or registration issued
			Michigan, United States	Adjustment	
2007	2007 Jan 19		Motor Vehicle Dept.	DMV Record	Title or registration issued
			Michigan, United States	Adjustment	
2008 Jan	2008 Jan 22		Motor Vehicle Dept.	DMV Record	Title or registration issued
_			Michigan, United States	Adjustment	
	2008 Apr 22	51,285 KM	Auto Auction	Auction Announcement	Vehicle sold
	2008 May 20	51,291 KM	Auto Auction	Auction Announcement	Listed as a Dealer Vehicle Vehicle sold
	2008 May 28		Motor Vehicle Dept. RV, Canada	Registration Records	Registered/Renewed
(3)	2008 May 28		Motor Vehicle Dept.	Import Record	From: United States
			Canada		To: Canada
					This vehicle has been importe
					into Canada from the US. For
					more information than is set
					out below, please contact RIV
					(www.riv.ca).
					Imported Into Canada As:

Normal

Case/Dossier: **K107761** Import Date: **5/28/2008**

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Dec 2	97,433 KM	Jiffy Lube #3510 Nepean, Ontario, Canada	Service Record	Vehicle serviced
2018 Jan 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renew
2018 Mar 20	99,018 KM	Service Facility	Service Record	Vehicle serviced
2018 Apr 28	99,799 KM	Jiffy Lube #3510 Nepean, Ontario, Canada	Service Record	Vehicle serviced
2018 Jun 16	100,941 KM	Jiffy Lube #3510 Nepean, Ontario, Canada	Service Record	Vehicle serviced
2019 Jan 29		Jiffy Lube #3510 Nepean, Ontario, Canada	Service Record	Vehicle serviced
2019 Jun 17	108,177 KM	Jiffy Lube #3510 Nepean, Ontario, Canada	Service Record	Vehicle serviced
2019 Jun 26	108,346 KM	Pierre's Auto Care Nepean, Ontario, Canada	Service Record	Vehicle serviced
2019 Oct 2	110,498 KM	MIDAS AUTO SERVICE EXPERTS Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2020 Dec 11	114,664 KM	Meineke Car Care Center Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2021 Feb 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Rene Previous Use: Personal
2021 May 17	115,879 KM	Jiffy Lube #3510 Nepean, Ontario, Canada	Service Record	Vehicle serviced
2021 Jul 16	116,000 KM	Jiffy Lube #3510 Nepean, Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 16	117,474 KM	Speedy Auto Service Nepean, Ontario, Canada	Service Record	Vehicle serviced
2021 Dec 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Rene New Owner reported Previous Use: Personal



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information non any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report,

including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. Conditions of Use

© 2023 CARFAX Canada ULC. All rights reserved.

