



United auto repair
 55 Beverly St Unit 2
 Cambridge, ON N1R 3Z4
 (289) 689-0882
 unitedmotorz.csr@hotmail.com
 Unitedmotorz.com

Estimate #2956

Created: 02/20/2026
 Payment Term: On Receipt
 Service Writer: Randy St. John

United Motorz
 25 Sportsworld Drive
 Kitchener, ON N2P 2J5
 Mobile: (289) 788-7739
 unitedmotorz.csr@hotmail.com

2015 Hyundai Sonata Sport (Black, #3426)
 VIN: 5NPE34AF8FH254431

safety inspection				
Description			HRS	Subtotal
1 inspection			1	\$90.00
2 verify				\$45.00
			HST (13%): \$17.55	Total: \$152.55

front brakes				
Description	Price	QTY	HRS	Subtotal
1 front brakes			1	\$90.00
2 Disc Brake Pad Set (Front)	\$53.33	1		\$53.33
3 Disc Brake Rotor (Front)	\$68.06	2		\$136.12
			HST (13%): \$36.33	Total: \$315.78

rear brakes				
Description	Price	QTY	HRS	Subtotal
1 rear brakes			1	\$90.00
2 Disc Brake Pad Set (Rear)	\$58.23	1		\$58.23
3 Disc Brake Rotor (Rear)	\$37.76	2		\$75.52
			HST (13%): \$29.09	Total: \$252.84

Hood Support Strut R&R (Each)				
Description	Price	QTY	HRS	Subtotal
1 Hood Support Strut R&R (Each)			0.2	\$18.00
2 Hood Lift Support	\$22.82	2		\$45.64
			HST (13%): \$8.27	Total: \$71.91

tires per 2				
215/55/17				
Description				Subtotal
1 Tire remove and Replace 2				\$50.00
			HST (13%): \$6.50	Total: \$56.50

Oil Change



United auto repair
 55 Beverly St Unit 2
 Cambridge, ON N1R 3Z4
 (289) 689-0882
 unitedmotorz.csr@hotmail.com
 Unitedmotorz.com

Estimate #2956

Created: 02/20/2026
 Payment Term: On Receipt
 Service Writer: Randy St. John

Oil Change			
Description	Price	QTY	Subtotal
1 OIL CHANGE			\$45.00
2 Engine Oil Filter	\$3.88	1	\$3.88
HST (13%): \$6.35			Total: \$55.23

Estimates provided are an approximation of timing and charges to you for the services requested. They are based on the anticipated work to be done. It is possible for unexpected complications to cause some deviation from the original quote. You hereby authorize the repair work described in this estimate to be done along with the procurement of the necessary material(s), including permission to operate the vehicle for on-road testing or inspection. If any additional repairs are required, we will prepare a revised work order providing the cost of additional parts and labor and total revised cost. All parts are new unless specified otherwise.
 Deposits are non-refundable. No returns or refunds on special ordered items or electrical parts. There is no warranty for used parts or customer supplied parts. You agree that we are not responsible for loss or damage to your vehicle, including loss of articles left in the vehicle, including, without limitation, in case of fire, theft, or any other cause(s) beyond our control. We are not responsible for any delays caused by unavailability of parts or delays in delivery of parts by the supplier or transporter.

Labor	\$428.00
Parts	\$372.72
Subtotal	\$800.72
Shop Supplies	\$0.00
EPA	\$0.00
HST	\$104.09
Grand Total	\$904.81
Paid to Date	(\$0.00)
REMAINING BALANCE	\$904.81

You have the right to know before authorizing any additional repairs what those repairs will be and what they will cost. If required repairs exceed the authorized estimated amount, we must obtain your approval to perform the repairs. We will keep you informed and perform only repairs authorized by you.

Signature _____



United auto repair
 55 Beverly St Unit 2
 Cambridge, ON N1R 3Z4
 (289) 689-0882
 unitedmotorz.csr@hotmail.com
 Unitedmotorz.com

Estimate #2956



Created: 02/20/2026
 Payment Term: On Receipt
 Service Writer: Randy St.John

United Motorz
 25 Sportsworld Drive
 Kitchener, ON N2P 2J5
 Mobile: (289) 788-7739
 unitedmotorz.csr@hotmail.com

2015 Hyundai Sonata Sport (Black, #3426)
 VIN: 5NPE34AF8FH254431

Sold Inspection Safety

Inspected: 02/20/2026




Item	Green	Yellow	Red	N/A
1 window/ side mirror / parking brake / Horn / Wipers / seat belt / seat adjust / Ac & Heat / all electrical sytem / Lights on Dash				
Note/Recommendation:				
				
2 test drive Suspension noise / Alignment / Overheat / RPM /				
Note/Recommendation:				
3 LIghts "F & R all lights" broken/hazy lights				
Note/Recommendation:				
4 fluid Level / leaks under hood / "coolnat, brake fluid, steering"		✓		
Note/Recommendation: <i>needs new hood struts no oil comes on dip stick oil leak need to be cleaned up.Looks like it's coming from the cylinder head and the exhaust took 3 liters</i>				
				
5 Front and REAR Suspension "brakes, Tires, control arms, axles, tie rod, links, shocks, e.t.c.		✓		



United auto repair
 55 Beverly St Unit 2
 Cambridge, ON N1R 3Z4
 (289) 689-0882
 unitedmotorz.csr@hotmail.com
 Unitedmotorz.com

Estimate #2956

Created: 02/20/2026
 Payment Term: On Receipt
 Service Writer: Randy St.John

Item	Green	Yellow	Red	N/A
<p>Note/Recommendation: 2 kinds of tires fronts are cracked 215/55/17 front and rear rotors</p> <div style="display: flex; justify-content: space-around;">    </div>				
6	Exhaust system			
Note/Recommendation:				
7	Frame structure "holes" , F & R rearbars"			
Note/Recommendation:				
8	Other items			
Note/Recommendation:				
Totals	0	2	0	6