

2010 TOYOTA COROLLA BASE

Sedan | 4 Cylinders | Gas
2T1BU4EEXAC355418
Country of Assembly: Canada
Last Reported Odometer: 147,541 KM

LOW
KILOMETRES



Accident/Damage Records Found



Last Registered In: Ontario (Normal)



12 Service Records Found



No U.S. History Found



3 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of November 04, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2011 Dec 5	Ontario, Canada Police Reported Accident: Accident reported: moderate damage It hit a fence Damage to front	



Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2013 Mar 15	56,734 KM	Evoy's Service Windsor, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Emissions inspection performed
2013 Jul 17	56,885 KM	Evoy's Service Windsor, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Emissions inspection performed
2015 Jun 3	70,707 KM	Lexus of Windsor Windsor, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Maintenance inspection completedSteering/suspension checked
2017 Apr 19	88,293 KM	Protech Automotive Windsor, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Lights checkedTire(s) replacedOil and filter changedSteering/suspension checkedTwo wheel alignment performed
2017 Jun 19	89,866 KM	Protech Automotive Windsor, Ontario, Canada	Vehicle serviced
2017 Jul 12	90,493 KM	Protech Automotive Windsor, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Emissions inspection performed
2019 Apr 26	107,261 KM	Protech Automotive	Vehicle serviced

		Windsor, Ontario, Canada	<ul style="list-style-type: none"> • Oil and filter changed • Wiper(s) replaced • Heat shield removed • Windshield washer checked
2019 May 9	107,575 KM	Protech Automotive Windsor, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Lights checked
2019 Sep 25	111,276 KM	Protech Automotive Windsor, Ontario, Canada	Vehicle serviced
2021 Feb 18	121,282 KM	Protech Automotive Windsor, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oxygen sensor replaced • Drivability/performance checked • Computer(s) checked
2022 Mar 31	129,132 KM	Protech Automotive Windsor, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Engine/powertrain computer/module checked
2023 Oct 30	147,541 KM	Lexus of Windsor Windsor, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Spiral cable assembly replaced/repaired



Open Recalls

Recall #: CAN234 | 234- Remedy Notice - Certain 2006-2010 MY Corolla, Matrix, Highlander, Tacoma, RAV4, Yaris vehicles - Spiral Cable

Recall Date: 2014
Apr 09

Recall Description

The steering column assembly in the involved vehicles contains a spiral cable assembly with electrical connections to the drivers airbag module that could become damaged when the steering wheel is turned. If this occurs, the airbag warning lamp will illuminate. In addition, the drivers airbag could become deactivated, causing it to not deploy in the event of a crash. This could increase the injury to the driver.

Remedy

Toyota dealerships will replace the spiral cable assembly in the subject vehicle.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit [Toyota's website](#).

Recall #: CANR10 | R10 - Remedy Notice Certain Toyota Camry, Camry HV, RAV4, Corolla, Matrix, Tundra, Sequoia, Highlander, Yaris, Scion xB and Scion xD vehicles (2006 - 2011) Power Window Master Switch Assembly

Recall
Date: 2015
Oct 21

Recall Description

The Power Window Master Switch (located on the driver's door) in the above vehicles may have been manufactured with insufficient lubricant grease. If sufficient grease is not applied, under certain conditions the switch may develop a short circuit

that can cause the switch assembly to overheat and melt. A melting switch can produce smoke and potentially lead to a fire.

Remedy

The remedy will involve an inspection, switch disassembly, and application of a specialized grease. In a limited number of cases, the electronic circuit board in the Power Window Master Switch will be replaced.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit [Toyota's website](#).

Recall #: CANR75 | R75 - Remedy Notice - Multiple Toyota Models and Model Years - Front Passenger Airbag Inflator

Recall Date: 2019 Jan 09

Recall Description

The subject vehicles are equipped with front passenger airbag inflators produced by Takata. The propellant in these inflators may degrade after prolonged exposure to high absolute humidity and fluctuating high temperatures. Degraded propellant can cause the inflator to explode during airbag deployment. In the event of an inflator explosion, metal fragments could pass through the airbag cushion material, striking the vehicle occupants, and result in serious injury or death.

Remedy

Toyota will replace the airbag inflator or the airbag assembly.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit [Toyota's website](#).



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2010 Jun 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as gray
2011 Dec 5		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none">• moderate damage

				<ul style="list-style-type: none"> • It hit a fence • Damage to front
2012 Aug 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2013 Feb 25	56,280 KM	Auto Auction	Auction Announcement	Listed as a Dealer Vehicle Sold at auction
2013 Mar 15	56,734 KM	Evoy's Service Windsor, Ontario, Canada	Service Record	Vehicle serviced
2013 Jul 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as gray
2013 Jul 17	56,885 KM	Evoy's Service Windsor, Ontario, Canada	Service Record	Vehicle serviced
2013 Sep 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2014 Apr 9		TOYOTA	Recall	Manufacturer Recall Issued Recall # CAN234
2015 Jun 3	70,707 KM	Lexus of Windsor Windsor, Ontario, Canada	Service Record	Vehicle serviced
2015 Sep 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2015 Oct 21		TOYOTA	Recall	Manufacturer Recall Issued Recall # CANR10
2017 Apr 19	88,293 KM	Protech Automotive Windsor, Ontario, Canada	Service Record	Vehicle serviced
2017 Jun 19	89,866 KM	Protech Automotive Windsor, Ontario, Canada	Service Record	Vehicle serviced
2017 Jul 12	90,493 KM	Protech Automotive Windsor, Ontario, Canada	Service Record	Vehicle serviced

2017 Sep 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Jan 9		TOYOTA	Recall	Manufacturer Recall Issued Recall # CANR75
2019 Apr 26	107,261 KM	Protech Automotive Windsor, Ontario, Canada	Service Record	Vehicle serviced
2019 May 9	107,575 KM	Protech Automotive Windsor, Ontario, Canada	Service Record	Vehicle serviced
2019 Sep 25	111,276 KM	Protech Automotive Windsor, Ontario, Canada	Service Record	Vehicle serviced
2021 Feb 18	121,282 KM	Protech Automotive Windsor, Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as gray
2022 Mar 31	129,132 KM	Protech Automotive Windsor, Ontario, Canada	Service Record	Vehicle serviced
2023 Oct 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray
2023 Oct 30	147,541 KM	Lexus of Windsor Windsor, Ontario, Canada	Service Record	Vehicle serviced

2T1BU4EEXAC355418



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada Low Kilometres™ Badge

The CARFAX Canada Low Kilometres™ badge is based on the odometer information reported to CARFAX Canada. The CARFAX Canada Low Kilometres™ badge is available for vehicles registered in Canada that have accumulated, as reported to CARFAX Canada via odometer records, less than 18,000 kilometres per year from the beginning of September in the year prior to the vehicle's model year until the date that this report was generated.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information

about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© 2023 CARFAX Canada ULC. All rights reserved.



