Private Vehicle Inspection Report

BRITISH COLUMBIA

Decal Number:	FT09703
Decal Expiry Date:	2023-Aug-31
Inspection Number:	20206062

Inspection Result: PASS

Facility:	J. KAM AUTO REPAIR LTD. / S6203	Inspection Type:	Complete	Inspection Start Date/Time:	2022-Jul-27 03:00 PM
Inspector:	Dhaliwal, Jamail Singh / 105512	Inspection Class:	Class 1 - Light Vehicle with LGVW 5500 kg or less	Inspection Complete Date/Time:	2022-Aug-09 10:30 AM
Work Order Number:	57013	Inspection Reason:	Salvage Vehicle	Collision Repair Facility:	RED SEAL COLLISION LTD
				Collision Repair Facility Phone:	(604) 753-8571
				Collision Repair Technician:	Mahmoud Haghmohammadi 01351-AB-08

Vehicle Jurisdiction:	British Columbia	Brake Type:	Hydraulic	Owner/Lessee Name:	INLINE, INLINE MOTORS
Registration Number:	11800983	Fuel Type:	Gasoline	Address:	333 - 12 ST
VIN:	2HKRM4H46GH102488	Odometer:	118042 KM	City:	New Westminster
Plate Number:	N/A	Hub Odometer:		Province/State:	British Columbia
Licenced GVW (kg):	0	Body Style:	4 Door Stationwagon	Postal Code/ZIP:	V3M4H5
Vehicle Year:	2016	Model:		Country:	Canada
Make:	HONDA				

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Passed	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	Rplcd frnt bmpr asmbly,hd lts,fndrs,hood,rad sup,rad,a/c lft rail rprd
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Not Applicable	

Tire Tread Depth (mm)

Axles (front)	Outer Left	Inner left	Inner Right	Outer Right	Steering Axle?
1	2.3			2.3	✓
2	2.3			2.3	

Comment:

Brake Lining/Pad Measurement (mm)

Axles (front)	Lining/Pad	Left	Right
1	Pad	10	10
2	Pad	8	8

Comment:

Rotor Thickness or Drum Inside Diameter Measurement (mm)

Axles (front)	Rotor/Drum	Left	Right
1	Rotor	26.02	26.02
2	Rotor	9.84	9.84

Comment:

Inspection Comments: Repaired by Craft tech collision (604-767-1933) insp by j kam auto repair (604-591-1531)

Has this Vehicle been road tested? Yes When? Before and After Inspection Name of the person who did the road test: J Dhaliwal

Inspector Name: Dhaliwal, Jamail Singh Signature:

This Inspection Report was submitted to CVSE on 2022-Aug-09 03:09 PM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MP at the Commercial Vehicle Safety Enforcement

CVSE0013

8/9/2022 3:09:26 PM

J KAM AUTOMOTIVE
#217 12745 78AVE
SURREY, BC
604.591.1531

Customer: INLINE MOTOR
License No:
Order No.:
Date: 08/09/2022 09:20
Company:
Odometer: 118042
VIN: 2HKRM4H46GH102488
Technician:

Vehicle HONDA 2016 CR-V USA / Canada Mexico



Besides improved fuel economy, handling and safety, what do these measurements mean?

CASTER is the tilt of the axis that the wheel steers around. It affects how the vehicle tracks as you drive down the road and can affect handling.

CAMBER is the angle of the tire in relation to the road surface. It affects tire wear, and handling when turning.

TOE is a measurement of how much the wheel is turned in or out from a straight-ahead position. It affects tire wear, handling and can make your steering wheel crooked.

Your vehicle has been aligned using a precision JohnBean wheel aligner.

4.4.2,United States Domestic,US2021R2

BRITISH COLUMBIA | Ministry of Transportation and Infrastructure

Designated Inspection Facility

(DIF must issue this form for completion by an autobody technician)

Structural Integrity Declaration Report

Commercial Vehicle Safety and Enforcement Branch

☑ **PASS** All requirements met ☐ **FAIL** Requirements NOT met

Designated Inspection Facility Information

Designated Inspection Facility Number: S 6 2 0 3

Facility Name: J. Kam Auto Repair LTD

Authorized Inspector Number: 1 0 5 5 1 2

Inspector Name: Jarnail S. Dhaliwal

Inspector Signature:

Date: 09/AUG/2022 Decal No.: FT 09703

Vehicle Information

Owner: Intime Motors.

Registration #: 1800983. Plate #:

Address: 333 12th St.

VIN #: 2HKRM4H46GH102488.

City: New Westminster Prov: BC PC: V3M4H5 Make: Honda Model: CR-V. Year: 2016.

Structural Integrity Declaration Report

Repair Standard and Vehicles Dimensions

1. I confirm that the repair / rebuild process for this vehicle has met or exceeded the rebuilding standards specified by the Inter-Industry Conference On Auto Collision Repair (I-CAR) and / or the Original Equipment Manufacturer (OEM), that the unitized vehicle body repair, including engine cradle, conforms to the OEM dimension standards and that a full-framed vehicle complies with the OEM, I-CAR repair standard.

Occupant Protection and Vehicle Components

2. I confirm that the assembly of body components have been performed in a manner that provides occupant protection that is equal to or exceeding OEM or I-CAR standards.

3. I confirm that the repairable structural components of the vehicle body have been assembled and repaired in accordance with methods, procedures and standards that will return the components to its original standard, quality and properties in accordance with the OEM, I-CAR standards.

4. I confirm that the assembly joints of the vehicle body are located in places and repaired in accordance with the OEM, I-CAR procedures and standards.

Wheel Alignment

5. I confirm that a four-wheel alignment has been performed and that steering angles and wheel tolerances are within the OEM, requirements for this vehicle. A four-wheel alignment computer printout has been included as part of this declaration.

I certify that this vehicle has been repaired in accordance with OEM/I-CAR standards as noted in items 1 - 5 above.

Technician Name (please print): Mahmoud Haghmohammadi

Autobody Tech Trade Qualification #: 01351-AB-08

Autobody Tech Trade Jurisdiction: B.C 604-753-8571

Technician Signature:

Wheel alignment (all 4 wheels- attach printout) Alignment performed (facility name and address if other than above):

NAME: J. Kam Auto Repair LTD

ADDRESS: 217 12745 78 avenue

Please indicate numbers and measurements on diagram below:

From inside vehicle: Front Left		Front Right	
-0.90	Camber	Camber	-1.05
2.6	Caster	Caster	2.8
0.05	Toe	Toe	0.05
13.2	SAI	SAI	13.3
12.3	Included Angle	Included Angle	12.3
	Turning Angle	Turning Angle	
Rear Left		**Rear Right**	
-1.18	Camber	Camber	-1.70
	Caster	Caster	
0.00	Toe	Toe	0.15
	SAI	SAI	
ALIGNMENT		☑ PASS	☐ FAIL

Date Rebuilt Completed: 09/AUG/2022

Rebuilder Name (if different from technician): Craft Collision 5411

Rebuilder Address: Imperial Burnaby V5J 1E6

* The **ORIGINAL** copy of this form must be forwarded to the designated inspection facility indicated above, and **MUST** be retained by the facility.
* This form must be the authentic original version signed by the autobody technician. Any photocopied, modified, altered, or changed form is unacceptable and must be rejected.
* A photocopy must accompany the customer's copy of the Vehicle Inspection Report (CVSE0013).

CVSE0032 Revised - April 29, 2013

BRITISH COLUMBIA | Ministry of Transportation and Infrastructure

Body Integrity Inspection Report

To be completed by the Designated Inspection Facility's Authorized Vehicle Inspector

Designated Inspection Facility Information

Designated Inspection Facility Number: S 6 2 0 3

Authorized Inspector Number: 1 0 5 5 1 2

DIF Facility Name: J. Kam Auto Repair LTD.

Inspector Name: Jarnail S. Dhaliwal

Inspection Start Date (Day / Month / Year): 28 07 2022

Inspection Completion Date (Day / Month / Year): 09 08 2022

Inspector Signature: JDhaliwal

VEHICLE OWNER

Name: Imine Motors.

Address: 333 12th St

City: New Westminster Prov: BC PC: V3M4H5

Tel #: 604-767-1933.

NAME OF REBUILDER (if other than owner)

Name: Craft Collision

Address: 5911 Imperial ave

City: Burnaby Prov: BC. PC: V5J1E6,

Tel #: 604-767-1933.

Vehicle Information

TYPE OF VEHICLE: ☐ Passenger Car ☑ MPV ☐ Truck ☐ Motorhome ☐ Taxi ☐ Bus

Licence Plate: — Odometer: 118042 Year: 2016 Make: honda Model: CR-V.

Registration Number: 118000983 VIN/Serial #: 2HKRM4H46GH102488.

I am satisfied that this rebuilt motor vehicle is the same as the one described in the record of rebuilding. ☑ Yes ☐ No

Requirements of Rebuilding		Components	R	C	VIM Reference Section	Components	R	C	VIM Reference Section
Photographs prior to rebuilding clearly showing vehicle damage	☑ Yes	STRUT			8 - 4	REAR STRUT TOWER			8 - 4 (b)
		- Left		✓		- Left		✓	
Structural Integrity Declaration Report	☑ Yes	- Right		✓		- Right		✓	
		HINGE (A) PILLAR			8 - 19	BUMPERS (Front/Rear)		✓	8 - 5
4 Wheel Alignment Printout	☑ Yes	- Left		✓		CROSSMEMBER		✓	8 - 3 (c)
		- Right		✓		HOOD		✓	8 - 1
Welded and structural components that require protection have been protected as required by OEM or I-CAR standard.	☑ Yes	CENTRE (B) PILLAR			8 - 19	RAD SUPPORT		✓	
		- Left		✓		BODY		✓	8 - 2
		- Right		✓		FRAME		✓	8 - 3
		LOCK (C) PILLAR			8 - 19	BULKHEAD (cowl)		✓	
		- Left		✓		DOORS		✓	8 - 6
Vehicle meets symmetric and asymmetric specifications as indicated on the Structural Integrity Declaration Report.	☑ Yes	- Right		✓		QUARTER PANELS			8 - 2 (c)
		ROCKER PANEL			8 - 19	- Left		✓	
		- Left		✓		- Right		✓	
		- Right		✓		FLOOR PAN		✓	8 - 4 (a)

Replaced left rear door, RR lens, fenders, HWD door shell, door, RTC, LF door detail

"R" marked when item rejected

"C" marked when item corrected

I certify that this rebuilt vehicle meets all Structural Integrity requirements as defined in the Motor Vehicle Act Regulations and the BC Vehicle Inspection Manual.

Authorized Inspector Name (print): Jarnail S. Dhaliwal Signature: JDhaliwal

CVSE0031 (May 27, 2013)