Vehicle History Report #: 36556780

Report Date: November 20, 2021 | 08:13 AM EST

Report Status: Complete

2014 CHEVROLET SILVERADO K1500 LTZ

Pickup | 8 Cylinders | Gas 3GCUKSEC4EG463661 Country of Assembly: Mexico Last Reported Odometer: 169,087 KM

NO REPORTED



No Accident/Damage Records Found



Last Registered In: New Brunswick (Normal)



11 Service Records Found



No U.S. History Found



2 Open Recalls Found




Not Actively Declared Stolen




No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca





DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Jun 10	THE PERSON NAMED OF THE PE	Motor Vehicle Dept. New Brunswick, Canada	Canadian Renewal	First Owner Reported
2014 Jun 10		Motor Vehicle Dept. New Brunswick, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Jun 11	And the second s	Motor Vehicle Dept, New Brunswick, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Mar 30	35,061 KM	Corey Ford Woodstock, New Brunswick, Canada	Service Record	Vehicle serviced
2015 Apr 28	35,499 KM	Corey Ford Woodstock, New Brunswick, Canada	Service Record	Vehicle serviced
2015 Jul 7		Motor Vehicle Dept. New Brunswick, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Feb 12	59,985 KM	CYV Chevrolet Buick GMC Woodstock, New Brunswick, Canada	Service Record	Vehicle serviced
2016 May 26		Motor Vehlcle Dept. New Brunswick, Canada	Canadian Renewal	Registration Issued or Renewed
2016 May 27	70,302 KM	Independent Source Fredericton, New Brunswick, Canada	Odometer reading	
2016 Jun 1		CYV Chevrolet Bulck GMC Woodstock, New Brunswick, Canada	Service Record	Vehicle serviced
2016 Jun 30	71,365 KM	CYV Chevrolet Bulck GMC Woodstock, New Brunswick, Canada	Service Record	Vehicle serviced
2016 Jul 20	73,005 KM	CYV Chevrolet Bulck GMC Woodstock, New Brunswick, Canada	Service Record	Vehicle serviced
2016 Oct 22	81,405 KM	CYV Chevrolet Bulck GMC Woodstock, New Brunswick, Canada	Service Record	Vehicle serviced
2017 May 20	101,303 KM	CYV Chevrolet Bulck GMC Woodstock, New Brunswick, Canada	Service Record	Vehicle serviced
2017 Jun 12		Motor Vehicle Dept. New Brunswick, Canada	Canadian Renewal	Registration Issued or Renew

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Jun 20	103,777 KM	CYV Chevrolet Bulck GMC Woodstock, New Brunswick, Canada	Service Record	Vehicle serviced
2018 Jun 11	136,488 KM	CYV Chevrolet Bulck GMC Woodstock, New Brunswick, Canada	Service Record	Vehicle serviced
2018 Jun 12		Motor Vehicle Dept. New Brunswick, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Jun 12		Motor Vehicle Dept. New Brunswick, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Aug 6	169,087 KM	CYV Chevrolet Bulck GMC Woodstock, New Brunswick, Canada	Service Record	Vehicle serviced
2019 Oct 24		CHEVROLET	Recall	Manufacturer Recall Issued Recall # N192261050
2019 Nov 8	and the same	CHEVROLET	Recall	Manufacturer Recall Issued Recall # N192270330
2020 Jun 1		Motor Vehicle Dept. New Brunswick, Canada	Canadian Renewal	Registration Issued or Renewed
2021 May 24		Motor Vehicle Dept. New Brunswick, Canada	Canadian Renewal	Registration Issued or Renewed



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada No Reported Accidents** Dadge

The CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and viere not, at the Limit this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information, on any one vehicle. For example, there may be other thile, brands, registrations, declarations, accident information, service exceeds, recall information, owners executed, recall information, service executed by CARFAX Canada, its source data providers of its agents for any errors, inaccuractes or emistions. The reports are provider sixtify on an as-insyndered plastit, and CARFAX Canada and its source data providers for executed by CARFAX Canada, its source data providers or inspired in the information contained value of the executed providers and inspired plastit, and CARFAX Canada and its source data providers or inspired plastit, and CARFAX Canada sold is source data providers express or implicit, including any exercances of implicit plastit, and CARFAX Canada and its source data providers express or implicit, including any exercances of implicit plastit, and CARFAX Canada and its source data providers express or implicit, including any exercances of implicit providers are providers for any including any exercances of implicit plastit, including any exercances of implicit providers are providers for any including the extraory thereof or any delay or express or implicit plants and including the control of any delay or express or implicit plants and including the control of any delay or express or implicit plants and including any exercances of implicit plants and including the control of any delay or express of implicit plants and including any exercances of implicit plants are providers. The providers are providers for including the control of including the control of including the control of including any exercances. The providers are providers fo

CARFAX

Vehicle History Report



Accident/Damage

There are no accidents/damage reported on this vehicle.



Registration

This vehicle has been registered in the province of New Brunswick in Canada with Normal branding. We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

Service Records

DATE	ODOMETER	SOURCE	DETAILS	
2015 Mar 30	35,061 KM	Corey Ford Woodstock, New Brunswick, Canada	Vehicle serviced	
2015 Apr 28	35,499 KM	Corey Ford Woodstock, New Brunswick, Canada	Vehicle serviced	
2016 Feb 12	59,985 KM	CYV Chevrolet Bulck GMC Woodstock, New Brunswick, Canada	Vehicle serviced Air fliter replaced Cabin air fliter replaced/cleaned Oil and fliter changed	
2016 Jun 1		CYV Chevrolet Buick GMC Woodstock, New Brunswick, Canada	Vehicle serviced • Maintenance inspection completed • Cabin air filter replaced/cleaned • Oil and filter changed • Engine cleaned	
2016 Jun 30	71,365 KM	CYV Chevrolet Bulck GMC, Woodstock, New Brunswick, Canada	Vehicle serviced • Exterior trim checked	
2016 Jul 20	73,005 KM	CYV Chevrolet Bulck GMC Woodstock, New Brunswick, Canada	Vehicle serviced	
2016 Oct 22	81,405 KM	CYV Chevrolet Bulck GMC Woodstock, New Brunswick, Canada	Vehicle serviced	
2017 May 20	101,303 KM	CYV Chevrolet Bulck GMC Woodstock, New Brunswick, Canada	Vehicle serviced	
2017 Jun 20	103,777 KM	CYV Chevrolet Bulck GMC Woodstock, New Brunswick, Canada	Vehicle serviced • Alignment checked • Brakes serviced	
2018 Jun 11	136,488 KM	CYV Chevrolet Bulck GMC Woodstock, New Brunswick, Canada	Vehicle serviced	

DATE	ODOMETER	SOURCE	DETAILS
2019 Aug 6	169,087 KM	CYV Chevrolet Bulck GMC Woodstock, New Brunswick, Canada	Vehicle serviced
10			The state of the s



Open Recalls

Recall #: N192270330 | Rear Window Defroster Thermal Events - Canada Only Recall Date: 2019 Nov 08

Recall Description

Certain 2014-2019 model year Chevrolet Silverado and GMC Sierra vehicles equipped with a power sliding rear window (RPO A48) had safety recall #N192220470 performed. This field action restores the rear window defrost function.

Remedy

Dealers will replace the buss bar covers and the contact cover, and for certain vehicles, will reprogram the HVAC calibration to disable the rear defroster from automatically turning on at keyed start. Please note that the rear defroster will automatically turn on during remote start or by pushing the manual button and is not affected by this calibration. If the rear window or sliding glass assembly appears damaged due to an occurrence of high electrical resistance on the rear defroster circuit, they will also be replaced. Dealers will also install the rear defroster fuse that was previously removed in field action # N192220470.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit GM's website,

Recall #: N192261050 | Unexpected Pull To One Side Recall Date: 2019 Oct 24

Recall Description

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2014 – 2018 model year Chevrolet Silverado and GMC Sierra 1500 vehicles equipped with four-wheel drive, a 5.3-liter engine, and a 3.08-ratio rear axie, and certain 2015 – 2020 model year Chevrolet Suburban, Chevrolet Tahoe, and GMC Yukon equipped with four-wheel drive, a 5.3-liter engine, and a 3.08-ratio rear axle. If a wheel-speed sensor falls in these vehicles, a software error in the vehicle's electronic-brake control module (EBCM) can cause the vehicle's driveline-protection system to activate when (i) the vehicle's electronic transfer case is set to four-wheel drive or automatic mode, and (ii) the vehicle is driven between the speeds of 41 and 60 MPH. If the driveline-protection system activates, the driver will experience unintended braking on the wheel on the opposite side of the falled sensor.

Remedy

Dealers will reprogram the electronic brake control module (EBCM).

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit GM's website.



Stolen Vehicle Check