

Vehicle History Report #: 51132081 Report Date: February 2, 2024 | 2:27 PM EST

Report Status: Complete

2007 TOYOTA YARIS

Hatchback | 4 Cylinders | Gas JTDKT923475101230 Country of Assembly: Japan Last Reported Odometer: 75,613 KM





No Accident/Damage Records Found



Last Registered In: Ontario (Normal)



0 Service Records Found



No U.S. History Found



4 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of February 02, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

JTDKT923475101230

Vehicle History Report



Accident/Damage

There are no accidents/damage reported on this vehicle.



Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Open Recalls

Recall #: CAN177 | 177 - Remedy Notice - Certain 2007-2009 MY Yaris, RAV4, Tundra, Camry/HV, Sequoia, Recall Date: Highlander/HV, Corolla, Matrix vehicles - Power Window Master Switch 2012 Oct 10

Recall Description

The Power Master Switch (PWMS), located on the drivers door, controls the windows for the driver and passengers. Over time, the sliding electrical contact module in the drivers side PWMS may experience a notchy or sticking feeling during operation due to uneven application of a grease lubricant to certain switch components.

Remedy

Any Toyota dealership will inspect the PWMS and apply a specialized grease. The electrical circuit board for the PWMS may be replaced if your dealership determines it requires replacement during the inspection.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit Toyota's website.

Recall #: CAN234 | 234- Remedy Notice - Certain 2006-2010 MY Corolla, Matrix. Highlander, Tacoma, Recall Date: 2014 RAV4, Yaris vehicles - Spiral Cable Apr 09

Recall Description

The steering column assembly in the involved vehicles contains a spiral cable assembly with electrical connections to the drivers airbag module that could become damaged when the steering wheel is turned. If this occurs, the airbag warning lamp will illuminate. In addition, the drivers airbag could become deactivated, causing it to not deploy in the event of a crash. This could increase the injury to the driver.

Remedy

Toyota dealerships will replace the spiral cable assembly in the subject vehicle.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit **Toyota's website**.

ITDKT923475101230

Recall #: CAN233 | 233- Remedy Notice - Certain 2006 -2010 Model Year Yaris, Scion xD vehicles - Driver Side Seat Track Assembly and Passenger Seat Track Assembly on 3-Door Yaris Hatchback only

Recall Date: 2014 Apr 09

Recall Description

In the seat rail of the driver seat of the subject vehicles, the springs used for the mechanism which locks the seat rail in its adjusting positions could break. This can happen if the seat is adjusted forward and/or rearward with high frequency. If a seat rail spring breaks, the seat may not lock into the adjusted position. If the vehicle is operated with a broken seat rail spring, the seat could move in the event of a crash, increasing the risk of injury to the occupant.

Remedy

Toyota dealerships will replace the front driver inner and outer seat track

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit **Toyota's website**.

Recall #: CANR31 | Campaign R31 - Certain 2006-2008 model year Yaris Hatchback and certain 2007-2008 Recall Date: model year Yaris Sedan vehicles - Front Passenger Airbag Inflator Module 2017 Jan 09

Recall Description

The subject vehicles are equipped with front passenger airbag inflators produced by Takata. The propellant in these inflators may degrade after prolonged exposure to high absolute humidity and fluctuating high temperatures. Degraded propellant can cause inflator rupture during airbag deployment.

Remedy

Any authorized Toyota dealer will replace the airbag inflator.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit Toyota's website.



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2007 May 31		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as blue
2007 Nov 7	6,002 KM	Toyota Niagara Falls, Ontario, Canada	Service Record	
2008 Mar 5	10,886 KM	Toyota Niagara Falls, Ontario, Canada	Service Record	

JTDKT923475101230

JTDKT923475101230

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2020 Sep 19		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or
		Ontario, Canada		Renewed
				Previous Use: Personal
2021 Apr 28		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or
		Ontario, Canada		Renewed
				Previous Use: Personal
				Vehicle colour noted as
				blue
2022 Aug 29		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or
		Ontario, Canada		Renewed
				Previous Use: Personal
				Vehicle colour noted as
				blue



CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and and information from external sources believed to be reliable to reading by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantability, merchantability, or information. On the information on the information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about tyour next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. Conditions of Use

© 2024 CARFAX Canada ULC. All rights reserved.

