

Vehicle History Report #: 49222406
Report Date: October 20, 2023 | 6:06 PM EDT
Report Status: Complete
Reference:

2021 FORD EXPLORER ST

Sport utility vehicle | 6 Cylinders | Gas 1FM5K8GC6MGB19405 Country of Assembly: United States Last Reported Odometer: 30,694 KM





Last Registered In: Ontario (Normal)



1 Service Record Found



No U.S. History Found



3 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found


Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of October 20, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



INCIDENT DATE	DETAILS	AMOUNT
① 2023 Feb 3	Barrie, Ontario, Canada	
	Police Reported Accident: Accident reported: minor damage	
	Involving front or side impact	
	with another motor vehicle	
	Damage to right side	
	Damage to roof	
	Estimate: Not Available Estimate Date: 2023 Feb 7	\$24,030.39
	Estimate: Not Available Estimate Date: 2023 Feb 15	\$24,860.54
	Claim: Unknown	\$32,445.00



Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2021 Mar 23		Service Facility Alliston, Ontario, Canada	Vehicle serviced • Pre-delivery inspection completed



Open Recalls

Recall #: 23S55 | REAR AXLE BOLT FRACTURES Recall Date: 2023 Oct 09

Recall Description

AFFECTED VEHICLES WERE BUILT WITH A 3-POINT MOUNTED AXLE DESIGN. ON SOME UNITS THE REAR AXLE HORIZONTAL MOUNTING BOLT MAY FRACTURE. POWERTRAIN TORQUE THROUGH THE DRIVELINE CAUSES AXLE ROTATION OF THE PINION ANGLED TOWARDS THE SUBFRAME, WHICH EXERTS A BENDING FORCE ON THE REAR AXLE BOLT. PEAK TORQUE IS NORMALLY EXPERIENCED DURING A LAUNCH EVENT. AFTER NUMEROUS PEAK TORQUE EVENTS ARE EXPERIENCED, THE BOLT MAY SUFFER A FATIGUE FAILURE, WHICH WILL LEAD TO THE AXLE HOUSING MOVING OUT OF POSITION, RESULTING IN A CONDITION DESCRIBED BY CUSTOMERS AND DEALER TECHNICIANS VARIABLY AS LOUD, GRINDING, BINDING, OR CLUNKING NOISES.

Remedy

THE REMEDY BUSHING PART NUMBER L1MW-4B425-BB HAS BEEN MODIFIED TO INCREASE THE FASTENER ENGAGEMENT LENGTH IN ORDER TO AVOID MATERIAL DEFORMATION.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit Ford's website.

Recall #: 22S27 | EXPLORER REAR AXLE BOLT FRACTURE Recall Date: 2022 Apr 19

Recall Description

CERTAIN 2020-2022 MODEL YEAR EXPLORER VEHICLES REAR AXLE BOLT FRACTURES

Remedy

DO NOT DEMONSTRATE OR DELIVER ANY NEW IN-STOCK VEHICLES INVOLVED IN THIS SAFETY RECALL. POLICE UNITS VIN POSITIONS 5-7 ARE K8A PART AVAILABILITY O NOTE POLICE UNITS WILL ONLY HAVE A PHYSICAL PART REPAIR. O PARTS ARE NOW AVAILABLE TO PERFORM ALL THE REPAIRS ON AFFECTED POLICE UNITS. NON-POLICE UNITS - BEFORE DEMONSTRATING OR DELIVERING ANY NEW IN-STOCK VEHICLES INVOLVED IN THIS RECALL, DEALERS ARE TO REPROGRAM THE POWERTRAIN CONTROL MODULE PCM TO THE LATEST LEVEL. THIS PCM UPDATE WILL ENGAGE THE ELECTRONIC PARKING BRAKE EVERY TIME THE VEHICLE IS SHIFTED INTO PARK P. AN ENGAGED PARKING BRAKE WILL NOT ALLOW THE VEHICLE TO ROLL. THIS SERVICE MUST BE PERFORMED ON ALL AFFECTED VEHICLES AT NO CHARGE TO THE VEHICLE OWNER. O NOTE ALL PCM CALIBRATIONS ARE NOW AVAILABLE. NOTE NON-POLICE UNITS ARE PROVIDED WITH A ONE-TIME REPAIR OF THE REAR AXLE BOLTS AND HOUSING IF NEEDED UNDER CUSTOMER SATISFACTION PROGRAM 22NO6.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit Ford's website.

Recall #: 23S23 | INOPERATIVE REAR 360 DEGREE CAMERA WITH A BLUE SCREEN Recall Date: 2023 May 16

Recall Description

YOU MAY INTERMITTENTLY EXPERIENCE A REAR CAMERA BLUE OR BLACK IMAGE ON THE SYNC SCREEN WHEN THE VEHICLE IS PLACED IN REVERSE OR WHEN THE 360 DEGREE VIEW IS SELECTED AND AVAILABLE DURING LOW-SPEED OPERATION. ONCE DISPLAYED, THE REAR CAMERA BLUE OR BLACK IMAGE MAY PERSIST FOR THE REMAINDER OF THE IGNITION ON CYCLE. ONCE PRESENT, THE ISSUE IS LIKELY TO REOCCUR ON SUBSEQUENT KEY CYCLES.

Remedy

FORD MOTOR COMPANY IS WORKING TO RELEASE A REPAIR FOR THE BLUE OR BLACK IMAGE ON THE SYNC SCREEN. WHEN A REPAIR BECOMES AVAILABLE, FORD MOTOR COMPANY WILL NOTIFY YOU VIA MAIL TO SCHEDULE A SERVICE APPOINTMENT WITH YOUR DEALER FOR REPAIRS TO BE COMPLETED FREE OF CHARGE PARTS AND LABOR.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit Ford's website.



Stolen Vehicle Check





Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Mar 23		Service Facility Alliston, Ontario, Canada	Service Record	Vehicle serviced
2021 Mar 24		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
				Previous Use: Personal
2021 Nov 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2022 Apr 19		FORD	Recall	Manufacturer Recall Issued Recall # 22S27
2022 Sep 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2023 Feb 3		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: minor damage Involving front or side impact with another motor vehicle Damage to right side Damage to roof
2023 Feb 3			Unknown	
		Ontario, Canada		
2023 Feb 3	30,691 KM	Insurance Records Barrie, Ontario, Canada	Estimate Repair	Estimate Date: 2023-02-07 Not Available
2023 Feb 3	30,694 KM	Insurance Records Barrie, Ontario, Canada	Estimate Repair	Estimate Date: 2023-02-15 Not Available
2023 May 16		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2023 May 16		FORD	Recall	Manufacturer Recall Issued Recall # 23S23
2023 Jun 7		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2023 Oct 9		FORD	Recall	Manufacturer Recall Issued Recall # 23S55



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers service receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantability, merchantability, merchantability, merchantability, merchantability and particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada. Conditions of Use

© 2023 CARFAX Canada ULC. All rights reserved.

