



Vehicle History Report #: 47500054
Report Date: July 28, 2023 | 3:54 PM EDT
Report Status: Complete

2010 MITSUBISHI OUTLANDER XLS

Sport utility vehicle | 6 Cylinders | Gas
JA4JT3AX5AZ608015
Country of Assembly: Japan
Last Reported Odometer: 116,660 KM



Accident/Damage Records Found



Last Registered In: Ontario (Normal)



10 Service Records Found



No U.S. History Found



2 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.
Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of July 28, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

JA4JT3AX5AZ608015

| INCIDENT DATE | DETAILS | AMOUNT |
|---------------|---------------------|----------|
| ! 2011 May 21 | Ontario, Canada | |
| | Claim: Other Damage | \$938.00 |



Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

| DATE | ODOMETER | SOURCE | DETAILS |
|-------------|------------|---|--|
| 2012 Dec 7 | 42,578 KM | VICTORIA PARK AUTOPRO Scarborough, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Recommended maintenance performed Maintenance inspection completed Oil and filter changed |
| 2014 Mar 31 | 67,950 KM | Service Facility Richmond Hill, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Air filter checked Fluids checked Oil and filter changed Maintenance reminder reset Tire condition and pressure checked |
| 2015 Sep 22 | 77,200 KM | Service Facility Richmond Hill, Ontario, Canada | Vehicle serviced |
| 2016 Sep 17 | | Krown Toronto North York, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Undercoating/rustproofing applied |
| 2016 Oct 5 | 82,506 KM | MID TORONTO MITSUBISHI York, Ontario, Canada | Vehicle serviced |
| 2018 Nov 2 | | Krown Toronto North York, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Undercoating/rustproofing applied |
| 2020 Nov 20 | 113,641 KM | Jerry's Automedic Ltd North York, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Rear brake pads replaced Brake pads replaced Brake rotor(s) replaced Brakes replaced Rear brake rotor(s) replaced Front brake pads replaced |
| 2021 May 26 | 116,660 KM | Jerry's Automedic Ltd North York, Ontario, Canada | Vehicle serviced |
| 2021 May 29 | | Active Green & Ross Toronto, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Tire(s) replaced Four tires balanced Four tires mounted |
| 2023 Apr 15 | | Active Green & Ross Toronto, Ontario, Canada | Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed |

JA4JT3AX5AZ608015

| ODOMETER | SOURCE | DETAILS |
|----------|--------|--|
| | | <ul style="list-style-type: none"> Air filter replaced Oil and filter changed Cabin air filter replaced/cleaned |



Open Recalls

Recall #: SR-16-009 | 2007-2013 OUTLANDER -REPLACE WIPER LINK (PERFORM AT SAME TIME AS

Recall Date: 2016 Oct 26

Recall Description

IN THE EVENT THAT WATER DROPS DOWN THROUGH THE BACK SIDE OF THE FRONT DECK GARNISH (THE BODY PIECE BETWEEN THE HOOD AND WINDSHIELD), THE FRONT WIPER LINK BALL JOINT MAY EXPERIENCE EXCESSIVE MOISTURE AND CORRODE. IF THIS OCCURS, THE RESIN CASE OF THE BALL JOINT WILL WEAR PREMATURELY DUE TO THE BALL JOINT CORROSION AND THE WIPER LINK MAY ULTIMATELY SEPARATE CAUSING THE WINDSHIELD WIPERS TO STOP OPERATING.

Remedy

OWNERS OF ALL AFFECTED VEHICLES WILL BE NOTIFIED AND ENCOURAGED TO BRING IN THEIR VEHICLES FOR THE REPAIR. AT NO CHARGE TO THE CUSTOMER, THE RUBBER BOOT WHICH COVERS THE BALL JOINT WILL BE REPLACED WITH A COUNTERMEASURE ONE TO PREVENT WATER INTRUSION. THE WIPER MOTOR CRANK ARM WILL ALSO BE INSPECTED AND REPLACED AS NECESSARY IN CASE OF EXCESSIVE FREE PLAY ON THE LINK.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact MITSUBISHI or visit [Mitsubishi's website](#).

Recall #: SR-17-003 | 2007-2013MY OUTLANDER -REPLACE WIPER MOTOR (PERFORM AT SAME TIME

Recall Date: 2017 Jul 20

Recall Description

WATER CAN POTENTIALLY DROP DOWN ONTO THE FRONT WIPER MOTOR THROUGH A GAP BETWEEN THE FRONT DECK GARNISH (THE BODY PIECE BETWEEN THE HOOD AND WINDSHIELD) AND THE FRONT WINDSHIELD. IF THIS OCCURS, WATER COULD POTENTIALLY COLLECT IN THE AREA OF THE WIPER MOTOR BREATHING HOLE. IF THE WIPER MOTOR IS NOT OPERATING, THIS WATER CAN THEN POTENTIALLY ENTER THE WIPER MOTOR THROUGH THE BREATHING HOLE. IF THIS OCCURS, SUCH WATER INTRUSION OVER TIME MAY CAUSE INTERNAL CORROSION AND/OR ELECTRICAL CONDUCTION FAILURE RESULTING IN NON-OPERATION OF THE WINDSHIELD WIPER MOTOR.

Remedy

OWNERS OF ALL AFFECTED VEHICLES WILL BE NOTIFIED AND ENCOURAGED TO BRING IN THEIR VEHICLES FOR REPAIR. AT NO CHARGE TO THE CUSTOMER, THE WIPER MOTOR WILL BE REPLACED WITH AN UPGRADED WIPER MOTOR THAT WILL PREVENT WATER INTRUSION.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact MITSUBISHI or visit [Mitsubishi's website](#).



Stolen Vehicle Check

JA4JT3AX5AZ608015

✔ This vehicle is not actively declared stolen.



Detailed History

| DATE | ODOMETER | SOURCE | RECORD TYPE | DETAILS |
|-------------|-----------|--|------------------|--|
| 2010 Aug 25 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed First Owner Reported Previous Use: Personal |
| 2011 May 21 | | Insurance Records Ontario, Canada | | |
| 2011 Jul 10 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2012 Aug 14 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2012 Dec 7 | 42,578 KM | VICTORIA PARK AUTOPRO Scarborough, Ontario, Canada | Service Record | Vehicle serviced |
| 2014 Mar 31 | 67,950 KM | Service Facility Richmond Hill, Ontario, Canada | Service Record | Vehicle serviced |
| 2014 Sep 16 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2015 Sep 22 | 77,200 KM | Service Facility Richmond Hill, Ontario, Canada | Service Record | Vehicle serviced |
| 2016 Mar 22 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed New Owner reported Previous Use: Personal |
| 2016 Jul 10 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2016 Sep 17 | | Krown Toronto North York, Ontario, Canada | Service Record | Vehicle serviced |
| 2016 Oct 5 | 82,506 KM | MID TORONTO MITSUBISHI York, Ontario, Canada | Service Record | Vehicle serviced |
| 2016 Oct 26 | | MITSUBISHI | Recall | Manufacturer Recall Issued Recall # SR-16-009 |

JA4JT3AX5AZ608015

| | ODOMETER | SOURCE | RECORD TYPE | DETAILS |
|-------------|------------|---|------------------|---|
| 2017 Jul 10 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2017 Jul 20 | | MITSUBISHI | Recall | Manufacturer Recall Issued Recall # SR-17-003 |
| 2018 Nov 2 | | Krown Toronto North York, Ontario, Canada | Service Record | Vehicle serviced |
| 2019 Jul 10 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2020 Nov 20 | 113,641 KM | Jerry's Automec Ltd North York, Ontario, Canada | Service Record | Vehicle serviced |
| 2021 May 26 | 116,660 KM | Jerry's Automec Ltd North York, Ontario, Canada | Service Record | Vehicle serviced |
| 2021 May 29 | | Active Green & Ross Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2021 Jul 10 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2023 Apr 15 | | Active Green & Ross Toronto, Ontario, Canada | Service Record | Vehicle serviced |
| 2023 Jul 10 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | Registration Issued or Renewed Previous Use: Personal |
| 2023 Jul 21 | | Motor Vehicle Dept. Ontario, Canada | Canadian Renewal | New Owner Reported |



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© 2023 CARFAX Canada ULC. All rights reserved.



JA4JT3AX5AZ608015