

StreetXtreme Auto Gallery

5829 Hwy #7 East
 Markham, Ontario. L3P 1A5
 Phone: 905-554-8628 Fax: 905-554-8629

INVOICE

6222

Org. Est. # 006665

INVOICE

Printed Date: 11/18/2022

Work Completed: 11/18/2022

STREETXTREME - SALES
 5829 HIGHWAY 7 EAST
 MARKHAM, ONTARIO L3P 1A5
 Home 905-554-8628

2002 Honda - Civic DX - 1.7L, In-Line4 (102CI) VIN(ES1)
 Lic # : Odometer In : 195119
 VIN # : 2HGES1644 **2H907964**

| Part Description | Number | Qty | Sale | Ext | Labor Description | Ext |
|----------------------------------------------|--------|------|-------|-------|-----------------------------------------------------------------------------------------------------------------------------|--------|
| Window Wiper Blade-Front Left 21" 40 521 | | 1.00 | 9.21 | 9.21 | SAFETY SAFETY CERTIFICATE | 150.00 |
| Window Wiper Blade-Front Right 19" 40 519 | | 1.00 | 8.43 | 8.43 | WINDSHIELD REPLACEMENT | 325.00 |
| Expansion Tank Cap - Bagged 54227 | | 1.00 | 7.00 | 7.00 | CONTROL ARM - Remove & Replace - Lower,Both - [DOES NOT include alignment.] | 231.00 |
| Control Arm-Front Left Lower 2703-65842 | | 1.00 | 97.07 | 97.07 | BALL JOINT - Remove & Replace - Lower,Each - [Serviced in Steering Knuckle Assembly.] - [DOES NOT include alignment.] | 136.50 |
| Control Arm-Front Right Lower 2703-65841 | | 1.00 | 97.07 | 97.07 | WHEEL CYLINDER - Replace One | 157.50 |
| Ball Joint-Front Lower 2700-65822 | | 1.00 | 15.86 | 15.86 | (Combination) - BRAKE SYSTEM - Bleed w/ABS | 42.00 |
| Wheel Cylinder-Rear Right 1475-37657 | | 1.00 | 18.50 | 18.50 | TWO WHEEL ALIGNMENT - Adjustment - Front Axle - [DOES NOT include straightening or replacement of components.] | 60.00 |
| Pennzoil Synthetic Oil Penn | | 5.00 | 8.00 | 40.00 | SYN OIL CHANGE & FILTER REPLACED NEW ENGINE OIL UP TO 5L AND OIL FILTER | 28.00 |
| Oil Filter OF | | 1.00 | 12.00 | 12.00 | Oil Filter Disposal Fee | 0.25 |
| Hood Release Cable 74130-S5D-A01ZA | | 1.00 | 18.78 | 18.78 | HOOD LATCH RELEASE CABLE - Remove & Replace | 105.00 |

Org. Estimate 1,761.86 Revisions 0.00 Current Estimate 1,761.86

| | |
|------------------|-------------------|
| Labor: | 910.00 |
| Parts: | 323.92 |
| Sublet: | 325.25 |
| SubTotal: | 1,559.17 |
| Tax: | 202.69 |
| Total: | 1,761.86 |
| Bal Due: | \$1,761.86 |

[Payments -]

Vehicle Received: 2022-11-18

Customer Number : 5

I (customer), hereby certify that they have the legal right to authorize repairs for the above listed vehicle, either through legal ownership, lease rights, or written authorization from the vehicle's owner. I authorize StreetXtreme Auto Gallery to take the steps necessary to perform the repairs listed in this contract, including any necessary on-road vehicle testing. The Consumer Protection Act 2002 provides you with the right in relation to having a motor vehicle repaired/ Among other things, you have a right to a written estimate. A repairer may not charge an amount that is more than ten per cent (10%) above that of the maximum amount that you will pay for the repairs. the repairer may not charge more than the maximum amount you authorized, if you have concerns about the work or repairs performed by the repairer or about your rights or duties under the Consumer Protection Act 2002, you should contact the Ministry of Consumer and Business Services. Upon notification of completed repairs, the customer agrees to retrieve and satisfy the balance owed with 3 days. If the vehicle and invoice has not been settled within 3 days, a storage fee of \$80/day will be incurred.

Signature _____ Date _____

Visit us on the web: www.streetxtreme.ca

Email Address: info@streetxtreme.ca