

2019 FORD F150 SUPERCREW

Pickup | 6 Cylinders | Gas
1FTFW1E49KFB31468
Country of Assembly: United States
Last Reported Odometer: n/a



Accident/Damage Records Found



Last Registered In:
Ontario (Salvage)



1 Service Record Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.
[1.866.835.8612](tel:18668358612) | [Customer Support Portal](#)

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2019 Nov 30	Ontario, Canada	
	Police Reported Accident: Accident reported: severe damage with another motor vehicle Damage to front Vehicle damaged in multiple places Vehicle towed	n/a
	Damage Detail: Accident reported: severe damage with another motor vehicle Damage to front Vehicle damaged in multiple places Vehicle towed	n/a

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2020 Jan 7	Ontario, Canada	
	Registration Event: Salvage	n/a



Registration

This vehicle has been registered in the following locations in **Canada** (listed oldest to newest):

- In the province of **Ontario** with **Normal** branding.
- In the province of **Ontario** with **Salvage** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
------	----------	--------	---------

DATE	ODOMETER	SOURCE	DETAILS
2019 Apr 18	n/a	Blackstock Ford Lincoln Sales Ltd. Orangeville, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Paint protection applied Wheel locks installed Nitrogen fill tires



Open Recalls

Recall #: 20C03 | DAYTIME RUNNING LAMP FUNCTION Recall Date: 2020 Feb 24

Recall Description

ON THESE VEHICLES, WHEN THE DAYTIME RUNNING LAMPS (DRL) ARE ILLUMINATED AND THE MASTER LIGHTING SWITCH IS MANUALLY ROTATED FROM THE AUTOLAMP POSITION TO THE HEADLAMP ON (LOW BEAM) POSITION, THE DRLS REMAIN ACTIVATED INSTEAD OF DIMMING TO PON THESE VEHICLES, WHEN THE DAYTIME RUNNING LAMPS (DRL) ARE ILLUMINATED AND THE MASTER LIGHTING SWITCH IS MANUALLY ROTATED FROM THE AUTOLAMP POSITION TO THE HEADLAMP ON (LOW BEAM) POSITION, THE DRLS REMAIN ACTIVATED INSTEAD OF DIMMING TO PARKING LAMPS AS REQUIRED BY FMVSS 108, EXCEEDING THE PHOTOMETRIC OUTPUT ALLOWED BY FMVSS 108.

Remedy

OWNERS WILL BE NOTIFIED BY MAIL AND INSTRUCTED TO TAKE THEIR VEHICLE TO A FORD OR LINCOLN DEALER TO HAVE THE BODY CONTROL MODULE (BCM) SOFTWARE CONFIGURATION UPDATED. THERE WILL BE NO CHARGE FOR THIS SERVICE

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit [Ford's website](#).



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Apr 18	n/a	Blackstock Ford Lincoln Sales Ltd. Orangeville, Ontario, Canada	Service Record	Vehicle serviced
2019 Oct 2	n/a	Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	First Owner Reported

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Oct 2	n/a	Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Nov 30	n/a	Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> • severe damage • with another motor vehicle • Damage to front • Vehicle damaged in multiple places • Vehicle towed
2019 Nov 30	n/a	Ontario, Canada	Damage Event	Accident Reported: <ul style="list-style-type: none"> • severe damage • with another motor vehicle • Damage to front • Vehicle damaged in multiple places • Vehicle towed
2020 Jan 7	n/a	Ontario, Canada	Registration Event	Salvage
2020 Feb 24	n/a	FORD	Recall	Manufacturer Recall Issued Recall # 20C03
2020 Sep 29	n/a	Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported



Questions? We're here to help.

[1.866.835.8612](tel:18668358612) | [Customer Support Portal](#) | [FAQ & Glossary](#)

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© Copyright 2005 - 2020 CARFAX Canada ULC. All rights reserved.

