



Vehicle History Report #: 61127408
Report Date: May 1, 2025 | 10:19 a.m. EDT
Report Status: Complete

2015 RAM 1500 ST

Pickup | 8 Cylinders | Gas

1C6RR7FT3FS637556

Country of Assembly: United States

Last Reported Odometer: 257,254 KM



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



9 Service Records Found



No U.S. History Found



4 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of May 01, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

1C6RR7FT3FS637556

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
🚨 2016 Mar 19	Ontario, Canada	
	Police Reported Accident: Accident reported: minor damage It hit a building Damage to front	



Registration



This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2017 Jun 28	99,028 KM	D-Tech Automotive Inc Perth, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Alignment performedTires rotated
2018 Jan 5	116,605 KM	Great Canadian Oil Change Oshawa, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Fluids checkedOil and filter changed
2020 Jun 20		Jiffy Lube Ottawa, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Maintenance inspection completedAir filter checkedDifferential fluid flushed/changedFluids checkedFront differential fluid flushed/changedOil and filter changedRear differential fluid flushed/changedRear differential servicedTransfer case servicedTransmission fluid changed
2023 Nov 7	221,999 KM	Southbank Dodge Chrysler Ottawa, Ontario, Canada	Vehicle serviced
2023 Nov 17		Southbank Dodge Chrysler Ottawa, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Vehicle washed/detailed
2024 Jan 4		Southbank Dodge Chrysler Ottawa, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Vehicle washed/detailed
2024 Sep 30		Southbank Dodge Chrysler Ottawa, Ontario, Canada	Vehicle serviced

	ODOMETER	SOURCE	DETAILS
2024 Oct 31	222,001 KM	Southbank Dodge Chrysler Ottawa, Ontario, Canada	Vehicle serviced
2025 Apr 12	257,254 KM	Southbank Dodge Chrysler Ottawa, Ontario, Canada	Vehicle serviced



Open Recalls

Recall #: T25 | OCCUPANT RESTRAINT CONTROL MODULE Recall Date: 2017 Jun 22

Recall Description

THE OCCUPANT RESTRAINT CONTROL MODULE MAY ACTIVATE A DIAGNOSTIC TROUBLE CODE (DTC) DUE TO EXTERNAL STIMULUS WHICH DISABLES ITS ABILITY TO SENSE VEHICLE ROLLOVER EVENTS. WHEN THE DTC IS SET, AIRBAG AND SEAT BELT PRETENSIONER DEPLOYMENT BASED ON ROLLOVER SENSING IS DISABLED FOR THE IGNITION CYCLE IN WHICH THE DTC WAS SET.

Remedy

THE ORC MODULE ON INVOLVED VEHICLES MUST BE REPROGRAMMED WITH NEW SOFTWARE.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](https://www.mopar.com/en-ca/my-vehicle/recalls/search.html). (https://www.mopar.com/en-ca/my-vehicle/recalls/search.html)

Recall #: T79 | BRAKE TRANSMISSION SHIFT INTERLOCK Recall Date: 2018 Jan 04

Recall Description

The Brake Transmission Shift Interlock (BTSI) locking pin may become stuck in the open position. A BTSI locking pin stuck in the open position may allow the transmission to be shifted out of PARK and to or from any gear position without depression of the brake pedal and/or without the key in the ignition, if a key is applicable.

Remedy

For 2013-2017 model year; Inspect the Brake Transmission Shift Interlock (BTSI) operation and replace if necessary. The Body Control Module (BCM) software will also be updated. For 2009-2012 model year; replace the BTSI, BCM software update not applicable.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](https://www.mopar.com/en-ca/my-vehicle/recalls/search.html). (https://www.mopar.com/en-ca/my-vehicle/recalls/search.html)

Recall #: U61 | REPROGRAM POWERTRAIN CONTROL MODULE Recall Date: 2018 Jun 26

Recall Description

The fault handling strategy of the Engine Control Module (ECM) or PCM software in the affected vehicles does not remove positive torque requests from the engine controller if the CAN-C bus stops communicating while the cruise control is requesting positive torque.

Remedy

Inspect the software level of the ECM/PCM and, if necessary, perform a software flash on the ECM/PCM of affected vehicles to improve the

fault handling so that if the CAN-C bus does stop communicating any active torque requests will be cleared

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](https://www.mopar.com/en-ca/my-vehicle/recalls/search.html). (https://www.mopar.com/en-ca/my-vehicle/recalls/search.html)

Recall #: U74 | 2015 - 2017 TAILGATE LATCH Recall Date: 2018 Aug 03

Recall Description

The tailgate actuator limiter tab within the power lock actuator control assembly may fracture allowing the lock rod control bracket to over-travel which may pull the lock rods and release the latches, potentially resulting in the tailgate inadvertently falling open at any time

Remedy

The remedy for this item will limit the locking actuator travel and not allow the pivot arm from overtraveling and pulling on the locking/unlocking rods

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](https://www.mopar.com/en-ca/my-vehicle/recalls/search.html). (https://www.mopar.com/en-ca/my-vehicle/recalls/search.html)



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Jun 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as black
2015 Sep 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Mar 19		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none">• minor damage• It hit a building• Damage to front
2016 Sep 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Mar 3		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Jun 22		RAM	Recall	Manufacturer Recall Issued Recall # T25
2017 Jun 28	99,028 KM	D-Tech Automotive Inc Perth, Ontario, Canada	Service Record	Vehicle serviced

1C6RR7FT3FS637556

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Sep 28		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Jan 4		RAM	Recall	Manufacturer Recall Issued Recall # T79
2018 Jan 5	116,605 KM	Great Canadian Oil Change Oshawa, Ontario, Canada	Service Record	Vehicle serviced
2018 Jan 31		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2018 Jun 26		RAM	Recall	Manufacturer Recall Issued Recall # U61
2018 Aug 3		RAM	Recall	Manufacturer Recall Issued Recall # U74
2019 Feb 28		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jun 20		Jiffy Lube Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2023 Oct 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black
2023 Nov 7	221,999 KM	Southbank Dodge Chrysler Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2023 Nov 17		Southbank Dodge Chrysler Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2024 Jan 4		Southbank Dodge Chrysler Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2024 Sep 30		Southbank Dodge Chrysler Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2024 Oct 31	222,001 KM	Southbank Dodge Chrysler Ottawa, Ontario, Canada	Service Record	Vehicle serviced
2025 Apr 12	257,254 KM	Southbank Dodge Chrysler Ottawa, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.

