

Report Date: January 18, 2023 | 04:48 PM EST Report Status: Complete

2015 CHEVROLET COLORADO

Pickup | 4 Cylinders | Gas 1GCHSAEA6F1205183 Country of Assembly: United States Last Reported Odometer: 102,293 KM



Accident/Damage Records Found



Last Registered In: **British Columbia (Normal)**



13 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of January 18, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report (BC)



Accident/Damage

INCIDENT DATE	DETAILS	40	AMOUNT
① 2019 Jun 19	British Columbia, Canada		1
	Estimate: COLLISION Estimate Date: n/a		\$0.00
	Claim: COLLISION	*.	\$0.00



Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.


We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS .
2015 Jun 26		Dueck GM Richmond Richmond, British Columbia, Canada	Vehicle serviced Pre-delivery inspection completed
2016 Jan 15	6,877 KM	Dueck Downtown Vancouver, British Columbia, Canada	Vehicle serviced Oil and filter changed Computer reprogrammed
2018 Nov 21	56,588 KM	Kal Tire 075 Coquitlam, British Columbia, Canada	Vehicle serviced Maintenance inspection completed Oil and filter changed Maintenance reminder reset
2019 Mar 31	62,536 KM	Kal Tire 075 Coquitlam, British Columbia, Canada	Vehicle serviced One tire mounted One tire balanced
2019 Jun 25	67,044 KM	Kal Tire 075 Coquitlam, British Columbia, Canada	Vehicle serviced Maintenance inspection completed Oil and filter changed Maintenance reminder reset
2020 Jan 29	76,734 KM	Kal Tire 075 Coquitlam, British Columbia, Canada	Vehicle serviced Maintenance inspection completed Brakes serviced Oil and filter changed
2020 Jun 9	82,629 KM	Kal Tire	Vehicle serviced

		Delta, British Columbia, Canada	
2020 Sep 29	85,831 KM	Kal Tire - New Westminster New Westminster, British Columbia, Canada	Vehicle serviced Oil and filter changed Maintenance reminder reset
2022 Mar 18	95,305 KM	Kal Tire 59 Burnaby, British Columbia, Canada	 Vehicle serviced Oil and filter changed Maintenance reminder reset
2022 Apr 25	96,300 KM	Kal Tire 59 Burnaby, British Columbia, Canada	Vehicle serviced • Engine checked
2022 May 4		Kal Tire 59 Burnaby, British Columbia, Canada	Vehicle serviced • Four wheel alignment performed • Headlight bulb(s) replaced • Headlight(s) replaced • Brakes serviced
2022 Sep 6	100,277 KM	Kal Tire 59 Burnaby, British Columbia, Canada	Vehicle serviced Oil and filter changed Maintenance reminder reset
2022 Dec 2	102,293 KM	Kal Tire 075 Coquitlam, British Columbia, Canada	Vehicle serviced Oil and filter changed Maintenance reminder reset



Recall #: N202325410 | Loss of Power Steering Assist Recall Date: 2021 Mar 25

Recall Description

General Motors has decided that a defect, which relates to motor vehicle safety, exists in 2015 model year Chevrolet Colorado and GMC Canyon vehicles. These vehicles may experience loss of power steering assist at startup or while driving due to the potential for a poor electrical connection within the steering gear assembly. A poor electrical connection in the affected steering gear assemblies may be caused by corrosion of certain connectors within the assemblies, or by damage to these connectors that occurred during the supplier's manufacturing process. If loss of connection occurs, power steering assist is lost (i.e., the vehicle reverts to manual steer), a malfunction indicator light displays on the instrument panel and a chime sounds to inform the driver.

Remedy

Dealers are to replace the steering gear torque sensor cover assembly.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit GM's website.



Stolen Vehicle Check

This vehicle is not actively declared stolen.

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
015 Jun 13		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2015 Jun 26		Dueck GM Richmond Richmond, British Columbia, Canada	Service Record	Vehicle serviced
2016 Jan 15	6,877 KM	Dueck Downtown Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2016 Feb 27		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Feb 25		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Mar 4		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Nov 21	56,588 KM	Kal Tire 075 Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2019 Feb 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Mar 31	62,536 KM	Kal Tire 075 Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2019 Jun 19		Insurance Records British Columbia, Canada	COLLISION	
2019 Jun 19		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a COLLISION
2019 Jun 25	67,044 KM	Kal Tire 075 Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2020 Jan 29	76,734 KM	Kal Tire 075 Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2020 Mar 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jun 9	82,629 KM	Kal Tire	Service Record	Vehicle serviced

		Delta, British Columbia, Canada		
2020 Sep 29	85,831 KM	Kal Tire - New Westminster New Westminster, British Columbia, Canada	Service Record	Vehicle serviced
2021 Feb 14		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Mar 25		CHEVROLET	Recall	Manufacturer Recall Issued Recall # N202325410
2022 Feb 6		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2022 Mar 18	95,305 KM	Kal Tire 59 Burnaby, British Columbia, Canada	Service Record	Vehicle serviced
2022 Apr 25	96,300 KM	Kal Tire 59 Burnaby, British Columbia, Canada	Service Record	Vehicle serviced
2022 May 4		Kal Tire 59 Burnaby, British Columbia, Canada	Service Record	Vehicle serviced
2022 Sep 6	100,277 KM	Kal Tire 59 Burnaby, British Columbia, Canada	Service Record	Vehicle serviced
2022 Dec 2	102,293 KM	Kal Tire 075 Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history, Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at http://apps.lcbc.com/registration/ychr/t.imitation.html.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

CARFAX Canada One Owner™ Badge

The CARFAX Canada One Owner[™] badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title,

1GCHSAEA6F1205183

brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantability or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, so that the providers further expenses or damages in connection with any report or any information about the vehicle that is the subject matter of this vehicle history report, so the providers further expenses or damages in connection with any report or any information about the vehicle that is the subject matter of this vehicle history report, so the providers further expenses or damages in connection with any report or any information about the vehicle that is the subject matter of this vehicle history report, so the providers further expenses or damages in connection with any report or any information.

© 2023 CARFAX Canada ULC. All rights reserved.







Exhaust System / Shocks & Struts

UNIT #8 - 20071 1138 AVENUE MAPLE RIDGE, BC V2X 0Z2

0: 604 460 7142

C: 604 721 1432

RIDGEMOTORSAUTOREPAIR@GMAIL.COM

CYPROSS MULTI-POINT	INSPECTION
Name: <u>AのBloto</u> Year/Make/Model: <u></u>	5 CHEUY COBERDO KMs: 1025
RO#: 3518 VIN: 16CHSAEA 6	
CHECKED AND OK FUTURE ATTEN	
INTERIOR/EXTERIOR	TIRES
NOTE ANY EXISTING BODY DAMAGE	TREAD DEPTH
	7/32" or greater 3/32" to 6/32" 2/32" or less LF 3/32" RF 3/32" LR 3/32" RR 3/32"
	Wear Pattern/ Damage LF
Lights (Head, Brake, Turn, Parking)	RF LF Alignment Balance
Windshield / Glass	LR RF 72 Retation
Wipers Horn / Interior Lights	RR RR 72 32 New Tire
BATTERY	BRAKES
The state of the s	
The second secon	BRAKE PADS / SHOES Over 5 mm (Disk) or 2 mm (Drum) 3-5 mm (Disk) or 1 01-2 mm (Drum)
UNDERHOOD	Over 5 mm (Disk) or 2 mm (Drum) 3-5 mm (Disk) or 1.01-2 mm (Drum) Less than 3 mm (Disk)
- September 200	Over 5 mm (Disk) or 2 mm (Drum) 3-5 mm (Disk) or 1.01-2 mm (Drum)
Oil Condition Transmission Fluid	Over 5 mm (Disk) or 2 mm (Drum) 3-5 mm (Disk) or 1.01-2 mm (Drum) Less than 3 mm (Disk)
Oil Condition Transmission Fluid Power Steering / Brake Fluid	Over 5 mm (Disk) or 2 mm (Drum) 3-5 mm (Disk) or 1.01-2 mm (Drum) Less than 3 mm (Disk)
Oil Condition Transmission Fluid Power Steering / Brake Fluid Coolant / Antifreeze	Over 5 mm (Disk) or 2 mm (Drum) 3-5 mm (Disk) or 1.01-2 mm (Drum) Less than 3 mm (Disk) or 1 mm (Drum) LF
Oil Condition Transmission Fluid Power Steering / Brake Fluid Coolant / Antifreeze Air Filter	Over 5 mm (Disk) or 2 mm (Drum) 3-5 mm (Disk) or 1.01-2 mm (Drum) Less than 3 mm (Disk) or 1 mm (Drum) LF RF
Oil Condition Transmission Fluid Power Steering / Brake Fluid Coolant / Antifreeze Air Filter Cabin Filter	Over 5 mm (Disk) or 2 mm (Drum) 3-5 mm (Disk) or 1.01-2 mm (Drum) Less than 3 mm (Disk) or 1 mm (Drum) LF RF LR
Oil Condition Transmission Fluid Power Steering / Brake Fluid Coolant / Antifreeze Air Filter	Over 5 mm (Disk) or 2 mm (Drum) 3-5 mm (Disk) or 1.01-2 mm (Drum) Less than 3 mm (Disk) or 1 mm (Drum) LF RF RR RR
UNDERHOOD Oil Condition Transmission Fluid Power Steering / Brake Fluid Coolant / Antifreeze Air Filter Cabin Filter Belts UNDER VEHICLE	Over 5 mm (Disk) or 2 mm (Drum) 3-5 mm (Disk) or 1.01-2 mm (Drum) Less than 3 mm (Disk) or 1 mm (Drum) LF RF LR
Oil Condition Transmission Fluid Power Steering / Brake Fluid Coolant / Antifreeze Air Filter Cabin Filter Belts	Over 5 mm (Disk) or 2 mm (Drum) 3-5 mm (Disk) or 1.01-2 mm (Drum) Less than 3 mm (Disk) or 1 mm (Drum) LF RF RR RR
Oil Condition Transmission Fluid Power Steering / Brake Fluid Coolant / Antifreeze Air Filter Cabin Filter Belts UNDER VEHICLE Brake Lines / Brake Hoses /	Over 5 mm (Disk) or 2 mm (Drum) 3-5 mm (Disk) or 1.01-2 mm (Drum) Less than 3 mm (Disk) or 1 mm (Drum) LF RF RR COMMENTS
UNDERHOOD Oil Condition Transmission Fluid Power Steering / Brake Fluid Coolant / Antifreeze Air Filter Cabin Filter Belts UNDER VEHICLE Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	Over 5 mm (Disk) or 2 mm (Drum) 3-5 mm (Disk) or 1.01-2 mm (Drum) Less than 3 mm (Disk) or 1 mm (Drum) LF RF RR COMMENTS

Ridge Motors Auto Repair and Tires Unit 8 - 20071 113B Avenue Maple Ridge, BC V2X 0Z2 (604) 460-7142

GST/HST N	1-
(351/H51 F	JO.

758148118

Date	Invoice #
2/6/2023	3518

Invoice

Invoice To	
Cypress Auto Brokers 1919 Maple Meadowa Way	l,
Maple Ridge BC	
/2X3M7	
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

Vehicle Description					
2015 Che	vy Colorado				
			i		

ODO IN	ODO OUT	Plate	VIN
102535		1 2 1 = 1	1gchsaea6f1205183

		per Start		100	
Quantity	Item	Description	Price Each	Amount	Tax
	I_Inspection_Gen	GST on sales	80.00 5.00%	80.00 4.00	G
	" "			* *	
			wier e	× ai	
		⊈t → Almen i til			
		1 450 A 1 T		+ (*)	
			v e ty		
	\.				
			Sales Tax Total	\$4.00	
		1. 168 × 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.			
			Total	\$84.00	

I herby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I herby authorize you and your employees to operate the vehicle listed above in connect with the repair work, including operation for the purposes of testing, inspection or delivery. I HERBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized herby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work.

By signing below I acknowledge and agree to the terms and conditions above

Customer	Signature			