

Vehicle History Report (BC) #: 52952420 Report Date: April 27, 2024 | 4:12 PM EDT

Report Status: Complete

Reference:

### 2007 GMC NEW SIERRA C3500

Cab chassis | 8 Cylinders | Gas 1GDJC39K77E556364

Country of Assembly: United States Last Reported Odometer: 157,418 KM



No Accident/Damage Records Found



Last Registered In: British Columbia (Normal)



18 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of April 27, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# **Vehicle History Report (BC)**



# Accident/Damage

There are no accidents/damage reported on this vehicle.



### Registration

This vehicle has been registered in the province of British Columbia in Canada with Normal branding. We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



### Service Records

DATE	ODOMETER	SOURCE	DETAILS				
2007 Jun 21 Carter GM Northshore North Vancouver, British Columbia, Canada		North Vancouver, British Columbia,	Vehicle serviced				
2007 Sep 6		Carter GM Northshore North Vancouver, British Columbia, Canada	Vehicle serviced • Engine oil/fluid leak checked				
2008 Mar 28		Carter GM Northshore North Vancouver, British Columbia, Canada	Vehicle serviced  Fluids checked  Oil and filter changed  Tire condition and pressure checked  Brakes checked  Engine oil/fluid leak checked				
2008 Oct 17		Carter GM Northshore North Vancouver, British Columbia, Canada	Vehicle serviced     Fluids checked     Oil and filter changed     Tire condition and pressure checked     Doors checked				
2009 Jun 12		Carter GM Northshore North Vancouver, British Columbia, Canada	Vehicle serviced  Recommended maintenance performed Fluids checked Oil and filter changed Tire condition and pressure checked Brakes checked				
2009 Dec 8		Carter GM Northshore North Vancouver, British Columbia, Canada	Vehicle serviced  Recommended maintenance performed Fluids checked Oil and filter changed Tire condition and pressure checked				

2010 Jun 25	Carter GM Northshore North Vancouver, British Columbia, Canada	Vehicle serviced
2011 May 9	Carter GM Northshore North Vancouver, British Columbia, Canada	Vehicle serviced  Recommended maintenance performed Fluids checked Oil and filter changed Tire condition and pressure checked
2011 Dec 5	Carter GM Northshore North Vancouver, British Columbia, Canada	Vehicle serviced  Recommended maintenance performed Fluids checked Oil and filter changed Tire condition and pressure checked
2012 Feb 21	Carter GM Northshore North Vancouver, British Columbia, Canada	Vehicle serviced
2012 Sep 24	Carter GM Northshore North Vancouver, British Columbia, Canada	Vehicle serviced  Recommended maintenance performed Brakes checked Fluids checked Oil and filter changed Tire condition and pressure checked Air filter replaced Tires rotated
2013 May 4	Carter GM Northshore North Vancouver, British Columbia, Canada	Vehicle serviced  • Battery replaced
2014 Jan 23	Carter GM Northshore North Vancouver, British Columbia, Canada	Vehicle serviced     Fluids checked     Oil and filter changed     Tire condition and pressure checked
2014 Dec 17	Carter GM Northshore North Vancouver, British Columbia, Canada	Vehicle serviced
2015 Dec 7	Carter GM Northshore North Vancouver, British Columbia, Canada	Vehicle serviced  Fuel injection system checked  Oil and filter changed  Headlight(s) replaced  Antifreeze/coolant flushed/changed  Transmission fluid flushed
2017 May 26 58,987 KM	Carter GM Northshore North Vancouver, British Columbia, Canada	Vehicle serviced
2018 Apr 4 61,865 KM	Carter GM Northshore North Vancouver, British Columbia, Canada	Vehicle serviced  • Maintenance inspection completed  • Oil and filter changed

2023 Jul 20 157,418 KM	Team Auto Repair & Electrical Ltd. Surrey, British Columbia, Canada

#### Vehicle serviced

- · Differential fluid flushed/changed
- · Rear differential serviced
- · Differential serviced
- · Rear differential fluid flushed/changed
- Parking brake shoes/pads replaced
- · Rear wheel bearing seal replaced
- Rear wheel bearing(s)/hub seal(s) replaced
- Serpentine belt replaced
- Drive belt(s) replaced



### **Open Recalls**

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact GMC or visit GM's website.



### Stolen Vehicle Check

This vehicle is not actively declared stolen.



### **Detailed History**

DATE ODOMETER	SOURCE	RECORD TYPE	DETAILS	
2007 Jun 12	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or	
	British Columbia, Canada		Renewed	
			First Owner Reported	
2007 Jun 21	Carter GM Northshore	Service Record	Vehicle serviced	
	North Vancouver, British			
	Columbia, Canada			
007 Sep 6	Carter GM Northshore	Service Record	Vehicle serviced	
	North Vancouver, British			
	Columbia, Canada			
2008 Mar 28	Carter GM Northshore	Service Record	Vehicle serviced	
	North Vancouver, British			
	Columbia, Canada			
2008 Jun 14	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or	
	British Columbia, Canada		Renewed	
2008 Oct 17	Carter GM Northshore	Service Record	Vehicle serviced	
	North Vancouver, British			
	Columbia, Canada			
2009 Jun 12	Carter GM Northshore	Service Record	Vehicle serviced	

	North Vancouver, British Columbia, Canada		
2009 Jun 13	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2009 Oct 19	GMC	Recall	Manufacturer Recall Issued Recall # N090270
2009 Dec 8	Carter GM Northshore North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2010 Jun 19	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2010 Jun 25	Carter GM Northshore North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2011 May 9	Carter GM Northshore North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2011 Jun 18	11 Jun 18 Motor Vehicle Dept. British Columbia, Canada		Registration Issued or Renewed
2011 Dec 5	Carter GM Northshore North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2012 Feb 21	Carter GM Northshore North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2012 Jun 16	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Sep 24	Carter GM Northshore North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2013 May 4	Carter GM Northshore North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2013 Jun 1	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Jan 23	Carter GM Northshore North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2014 Jun 14	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed



### CC Auto Repair

#170 - 20170 Stewart Crescent Maple Ridge, BC V2X0T4

604-460-6506

#### Invoice

Bill To Cypress Auto Brokers Brokers, Cypress Auto 11919 Maple Meadows Way Maple Ridge, B.C. V2X 3M7 Canada

Home (604) 719-7615 Arin Email

Invoice # 1232 Work Order # 1859 Service Advisor Matt Preston Technician Braydon

Plate BC GMS07

Description 2007 GMC Sierra 3500 HD SLE V8 6.0L 5967C0

364CID VIN K

VIN 1GDJC39K77E556364

Odometer 167,167

Invoice Date 5/13/2024 12:57 PM Appointment 5/7/2024 10:30 AM Promised 5/7/2024 5:00 PM

Concern

Check Engine Light On

Concern // P0300 Multiple cylinder misfire detected // P0573 Brake Switch circuit 1 high voltage // P2270 H02S Signal stuck lean

bank 1 sensor 2 // P0307 Cylinder 7 misfire detected

0 Hour

\$0.00 \*GP

Sub \$0.00

Inspection

[AS1] WGAT Courtesy Check

Labor

0 Hour

\$0.00 \*GP

\$0.00 Sub

Service

Diagnose / Scan Computer Engine Controls Concern

Initial diagnosis, testing and inspection of the specific vehicle system as required. Perform road test where applicable. Report test result(s), system fault(s), component(s) failure and required repair(s). Additional diagnosis and testing time may be required at additional charges.

Labor

0.5 Hour

\$75.00 \*GP

Discount Sub

(\$75.00)\$0.00

Lube, Oil & Filter Service - General

Drain and refill engine oil, change engine oil filter and lubricate chassis grease fittings and friction points as required. Check and top off fluid levels, additional charges may apply where fluids are required. Complete a complementary visual vehicle inspection.

5W30 Semi Synthetic

5.7 Unit

\$8.59 / Unit

\$48.96 GP

Fram - Engine Oil Filter

1 Unit

\$14.70 / Unit

\$14.70 GP

Labor

0.5 Hour

Discount

\$37.50 \*GP

(\$3.75)

Sub \$97.41

**Power Steering Hose** 

Remove and Replace components as required to access and install materials, and/or perform needed service. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Power Steering Pressure Line Hose Assembly

1 Unit

\$51.18 / Unit

\$51.18 GP

Labor

1 Hour

\$150.00 \*GP

Discount Sub (\$15.00)\$186.18

Shock Assembly, Front

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Suspension Shock Absorber

2 Unit

\$90.73 / Unit

\$181.46 GP

Labor

1 Hour

\$150.00 \*GP

Discount (\$29.52)Sub \$301.94

#### Shock Absorber, Rear

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Monroe Gas-Magnum Rear Shock Absorber

2 Unit

\$107.14 / Unit

\$214.28 GP

Labor

1 Hour

\$150.00 \*GP (\$15.00)

**Discount** Sub

\$349.28

#### Serpentine Belt(s)

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Retest and verify repair as required. Perform final road test where applicable.

Serpentine Belt

1 Unit

\$95.66 / Unit

\$95.66 GP

Labor

0.4 Hour

\$60.00 \*GP

Discount Sub

(\$13.65)\$142.01

#### Spark Plug(s)

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Cpan	as required.	CHOITH	milai	oud t	COL WITCH	c applica
Spa	ark Plug					
Spa	ark Plug Wire	Set				

8 Unit \$10.02 / Unit 1 Unit \$154.29 / Unit 1 Unit

\$80.16 GP \$154.29 GP

Ignition Coil Labor

1.5 Hour

\$61.10 / Unit

Sub

\$61.10 GP \$225.00 \*GP

Discount

(\$46.14)\$474.41

4		
Total Parts Total Labor		\$855.98 \$695.25
Total Before Taxes & Miscellaneous Charges		\$1,551.23
(*) Shop Supplies, Enviro Fees, Cleaners, Grease, Lubricant, Small Parts, Fasteners and any other items too small to Invoice	5 %	\$34.76 PG
(G) Canadian Goods and Services Tax (GST) (P) BC Provincial Sales Tax (PST)*	5 %	\$79.30 \$0.00
Exemption #: 1014-2701  Grand Total		\$1,665,29

Total discounts applied is \$198.06

Cypress Auto Brokers paid \$1,665.29 by Visa

5/13/2024 12:58 PM Card #: XXXXXXXXXXXXXXXX7313 Entry Method: Chip Type: Sale Amount: 1665.29 Terminal: 84208 Transaction: fb50aa5a-7d68-41d1-87f0-9e93cf722cf9 Authorization: 02661l Result: Approved AID: A000000031010 TC: ARQC: 0266A39E4205DE6A TVR: 0080008000 TSI: E800

Buyer agrees to pay total amount above according to cardholder's agreement with issuer.

-			_		
Than	ks f	or th	e B	usin	ess

I acknowledge receipt of the vehicle and the indebtedness indicated herein.

Customer Signature:			
Gustoniei Siunature.			

# Cypress Auto Brokers - GMS07 BC - 2007 GMC Sierra 3500 HD SLE [1GDJC39K77E556364] [AS1] WGAT Courtesy Check

[AS1] WGAT Courtesy Check	0	S	M	R	
Inside vehicle and test drive					CEL is on - engine runs real rough / CEL is flashing *Diagnosed
CEL					misfire due to plugs and injector - fixed while at shop*
ABS/TRAC/EST					
Cooling system	u = l				
Oil change					
Charging					
Outside Vehicle		l T		1 19	
Headlights				- 11	
Front signal light			8 = 1	iv N	
Wiper/arm		7.			
Brake light					
Rear signal light					
Tail light					
License light					
Under Hood					
Accessory/drive belts		1	1		Belt is worn out - deep grooves // *Repaired by replacing belt*
Transmission fluid					
Power steering fluid					Power steering high pressure line is leaking - recommend replacement // *Fixed line at shop - no more power steering leak*
Coolant	All Districts			4113	Coolant Temperature -45
Radiator and hoses					
Heater hoses/clamps					
Air conditioning lines and hoses					
Engine oil					
Brake fluid					
Engine air filter					
Tune up components				6 4 1	
Battery and terminals					
Battery/cables/clamps					
Under Vehicle			L. 72 1	1	
Under Vehicle	4	117			
Steering components					
Front suspension components	3				
Rack and pinion pump, hoses, fluids				115	
Front axle shafts & boots / U-Joint					
Front struts/shocks	District	9 3	4- 1		Original Equipment - Recommend Replacing front shocks due to mileage/age // *Replaced front shocks at shop*
Check for engine oil leaks					
Check for transmission fluid leaks			L.	7,41	
Rear axle shafts & boots / U-Joint		Maria		W	
Rear shocks/struts					Original Equipment - Recommend Replacing front shocks due to mileage/age // *Replaced rear shocks at shop*
Rear differential					
Muffler, exhaust pipes & hangers					
Brakes					
Front brakes					
Front rotors			1		
Front brake hydraulic system			1 19		

[AS1] WGAT Courtesy Check	0	S	M	R	
Front brake lines/hoses					
Rear brake pads/shoes		d s			
Rear brake rotors					
Rear brake hydraulic system					
Rear brake lines/hoses					
Tires				52.11	
Front tire condition				le l	8/32
Front tire pressure					55PSI
Rotation and balance check					
Rear tire condition					10/32
Rear tire pressure					80PSI



Canadian Tire Associate Store 0481 KIMBERLEY J. MAK HOLDINGS INC. 11969 - 200TH STREET

Maple Ridge, BC V2X 3M7

Phone: 604-460-4664 Fax: 604-460-4665

e-mail:

DATE: May 15 24

INVOICE

20048100093451

GST REG#: 778156117 PST REG#: 1107-5287

SOLD TO: 9104864.0481 CYPRESS AUTO BROKERS 11919 MAPLE MEADOWS WAY

MAPLE RIDGE BC V2X 3M7

2505521817- AMARDEEP

MOBILE : 604 780-4270 HOME: 604 465-3313

PAGE:

BUSINESS: 604 465-3313 FAX:

EMAIL

COLOUR	VEHICLE DESCI	RIPTION		PLATE	JNIT# TAG		ODO IN	
ILVER/BLACK	2007 GMC TRUCK	SIERRA 3500 PICKUP V8-364 6.0L		ИМИМИМИМИ			167616	
IN	VEHICLE OPTIO	EHICLE OPTIONS				ADV	ODO AUTH	
GDJC39K77E556364	× ×	2 1 × 20 × 20 × 20 × 20 × 20 × 20 × 20 ×				IM01	167616	
IME IN	PROMISED	TERMS	GST EXE	MPT#	P.O.		ODO OUT	
30 PM		Cash	The state of the		1.0.		167616	
QTY	ITEM	DESCRIPTION		WARR	NE	т		
				WANN	INC		EXT.PRICE	
2 2089163  R SRTC  R SRTC		PST Exemption 10142701 NOTE - DRIVERS REAR TAIL LI IS/WAS BROKEN PRIOR TO SERV REPLACE TWO FRONT TIRES TIRES ORDERD FROM NORTH COU 13TH-MARKED IN SHOP Cooper Tires LT215/85R16 11 LT215/85R16 115/112R DISCOV (90000008305) LT215/85R16 1 DOT Number(1): DOT Number(2): Reminder: Seasonal Tire Cha 12 24 A reminder will be sent to date above Reminder: Seasonal Tire Cha 15 24 A reminder will be sent to date above SAVE OLD SCRAP OLD WW/IN WHEEL LOCK KEY? TPMS LIGHT RECOMMEND WHEEL ALIGNMENT W PURCHASE English: Visit canadiantire.ca/en/automotic ls/tire-registration.html t your new tire's DOT codes French: Enregistrez les code www.canadiantire.ca/fr/automotic TIRE REPLACEMENT ADVANTAGE ENPEUS DE REMPLACEMENT AVANT Free spare tire change serv first year after purchase will Replacement Advantage purch. (Service gratuit de emplacement advantage purch) Call Roadside Assistance if après l'achat lors d'une inspress l'achat lors	INTRY ON MAY  5/112R  ERER HT3 15R  Ingeover Oct  you on the  MW/OUT ON.  ITH TIRE  ve/tires-whee o register  es DOT sur mobile/pneushtml  * TAGE* ice for the hen Tire ased. ment d'un mière année scription au  you require stance			237.99	475.98	

I hereby authorize you and your employees to carry out the repairmork described above and to purchase on my account any parts and materials necessary to carry out the repairmork subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connection with the repairmork, including operation for the purposes of testing, hispection or delivery. I HEREBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES IMAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. Tacknowledge that, upon the completion of the repairmork authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repairmork. By signing below Lacknowledge and agree to the terms and conditions above and to those printed on the reverse side of this form.

Customer Signature:

PARTS:
LABOUR:
OTHER:
SUB-TOTAL:
GST/HST:

PST:

TOTAL: Cont'd



Canadian Tire Associate Store 0481 KIMBERLEY J. MAK HOLDINGS INC. 11969 - 200TH STREET

Maple Ridge, BC V2X 3M7

Phone: 604-460-4664 Fax: 604-460-4665

e-mail:

DATE: May 15 24

INVOICE

PAGE:

20048100093451

GST REG#: 778156117 PST REG#: 1107-5287

TOTAL:

Cont'd

SOLD TO: 9104864.0481 **CYPRESS AUTO BROKERS** 11919 MAPLE MEADOWS WAY

MAPLE RIDGE BC V2X 3M7

2505521817- AMARDEEP

MOBILE : 604 780-4270 HOME: 604 465-3313

BUSINESS: 604 465-3313 FAX:

EMAIL :

COLOUR		VEHICLE DES	CRIPTIO	N		PLATE	UNIT	#	TAG	ODO IN
SILVER/BLACK		2007 GMC TRUCK SIERRA 3500 PICKUP V8-364 6.0L NMNMNMNMN								167616
/IN		VEHICLE OPT	IONS						ADV	ODO AUTH
GDJC39K77	7E556364								IM01	167616
TIME IN 2:30 PM		PROMISED		TERMS GST EX		GST EXEMPT#		P.O.		ODO OUT 167616
2 2989327 NTTRK R SRTC		ADVA Truc Rem: 06 2 A re date VEH: DECI		800-444-4597 VANCE DISPOSAL FEE uck Tire Balancing 80 May 15 24 minder: Seasonal Tire Changeover Oct				6.50 35.99		13.0
1	SS		Au THANK FEEL QUEST	Supplies  thorized on: May 15 2024  YOU FOR YOUR PATRONAGE FREE TO CONTACT US WITH IONS OR CONCERNS-GREAT CE=HAPPY PEOPLE	. PLEASE ANY				N/C	N/C
J J C W	T1: See S *** Globa Installed Canadian Warranty / 5500 km	not available applies to	er for dessage anties a ive Ser e for (	details  ***  applicable only when produ  rvice Centre, otherwise wa  commercial use. A minimum  led parts unless otherwise	rranties may labour warrar	vary.	days d			
t * C m r c r r C r INVOICE	***Wheel Canadian manufactu tetorqued can happe teturn to	Retorque*** Tire checks rer's recomm after drivi n from conti this locati	every tended to ng for nuous con for	completion date shown on for cash & carry parts was tire after installation and values. It is recommended a short distance to account act with the road. For a free wheel retorque after the complete of the complete contact with the road.	rranties.  d retorques to have your nt for any se added protecer driving you	to the wheels the trion, kind our vehicle	ly	er i State en		
ehicle listed al ELEASE AND AMAGE TO C EYOND YOU pplicable repa re vehicle for r	bove inconne D FOREVER [ OR LOSS OF I IR CONTROL air and storage non-payment o	ction with the repair VISCHARGE YOU A MY VEHICLE ANDA I acknowledge that Lien legislation and	work, includ ND EACH ( OR ANY ITE , upon the c that you may I for such re	epairwork described above and to purchase described above. I hereby authorize you aring operation for the purposes of testing, ins PYOUR BMPLOYEES FROM ANY LOSSEMS CONTAINED THEREIN THAT ARE CARD CARD CONTAINED THEREIN THAT ARE CARD CONTAINED THE PROPERTY OF THE CARD CONTAINED THE CARD CARD CONTAINED THE CARD CONTAINED T	id your employees to pection or delivery. I h 33 I MAY SUFFER RI USED BY CIRCUMS by, you will have a lie	operate the HEREBY ELATING TO TANCES n pursuant to		LAE OT SUB-TC	ARTS: BOUR: CHER: CHST: PST:	



Canadian Tire Associate Store 0481 KIMBERLEY J. MAK HOLDINGS INC.

11969 - 200TH STREET

Maple Ridge, BC V2X 3M7

Phone: 604-460-4664 Fax: 604-460-4665

e-mail:

DATE: May 15 24

INVOICE

20048100093451

GST REG#: 778156117 PST REG#: 1107-5287

SOLD TO: 9104864.0481 CYPRESS AUTO BROKERS 11919 MAPLE MEADOWS WAY

MAPLE RIDGE BC V2X 3M7

2505521817- AMARDEEP

MOBILE : 604 780-4270 HOME: 604 465-3313

PAGE:

BUSINESS: 604 465-3313

COLOUR	VEHICLE DESCRIPT	T# TA	AG ODO IN		
ILVER/BLACK	2007 GMC TRUCK SIER		167616		
'IN	VEHICLE OPTIONS	A	OV ODO AUTH		
GDJC39K77E556364	The state of the s			IMO	01 167616
IME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT
:30 PM	I I STATE THE STATE OF	Cash			167616
QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
***PRIVE Canadian service provided informat services Please v not wish Corporat https:// ***Tire Storage Tires wi customer reason, responsi 30 days obligati	providers ("CTC" d by you to fulfil tion to administer s, and loyalty provisit www.canadian for your informate Customer Relatifus. ("Cont Storage Terms *** term: (applicable till be stored up to requests to have at which point the ble for unclaimed of term expiration."	p. Limited, its affiliates, Ass or "our") collect and use the lathis contract. CTC may also the delivery of and market was grams to you, and to analyze y tire.ca for details on CTC's pation to be kept in our databas ons at 1-866-846-5841 or via eactUs/.  only to customers who have pure of a maximum of 8 months from Interest removed from the storage storage term will end. Canadatires at expiration of storagen date will be disposed of with ayment for Tire Storage is deepended.	personal information collect and use your rranties, products our relationship with us. rivacy policy. If you do e, please contact CTC's mail at  rchased tire storage) nvoice date OR until e location for any ian Tire is not e term. Tires left beyond hout any liability or		

necessary to carry out the repairwork subject to the estimate described above. Thereby authorize you and your employees to operate the vehicle listed above in connection with the repairwork, including operation for the purposes of testing, inspection or delivery. I HEREBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR BMPLOYEES FROM ANY LOSSES IMAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITBMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repairwork authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repairwork. By signing below I acknowledge and agree to the terms and conditions above and to those printed on the reverse side of this form. Customer Signature:

LABOUR: 71.98 OTHER: 13.00 SUB-TOTAL: 560.96 GST/HST: 28.05 PST: N/C 589.01 TOTAL: