



# Private Vehicle Inspection Report

Decal Number: FS21834  
Decal Expiry Date: 2023-Apr-30  
Inspection Number: 20064012

Inspection Result: **PASS**

Facility: ABBOTSFORD TUNE-UP CENTER / S5838  
Inspector: GANDA, KARAMJIT SINGH / 108183  
Work Order Number: 15691

Inspection Type: Complete  
Inspection Class: Class 1 - Light Vehicle with LGVW 5500 kg or less  
Inspection Reason: Salvage Vehicle

Inspection Start Date/Time: 2022-Mar-20 10:30 AM  
Inspection Complete Date/Time: 2022-Apr-04 12:00 PM  
Collision Repair Facility: AMC AUTO  
Collision Repair Facility Phone: (778) 317-1840  
Collision Repair Technician: ARIS

Vehicle Jurisdiction: British Columbia

Brake Type: Hydraulic

Owner/Lessee Name: INLINE MOTORS, INLINE MOTORS

Registration Number: 12922259

Fuel Type: Gasoline

Address: 333 TWELFTH STREET

VIN: 1FTEW1E59JKF38653

Odometer: 50288 KM

City: New Westminster

Plate Number:

Hub Odometer:

Province/State: British Columbia

Licensed GVW (kg): 3203

Body Style: Crewcab

Postal Code/ZIP: V3MHS

Vehicle Year: 2018

Model: F150

Country: Canada

Make: FORD

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Passed	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

### Tire Tread Depth (mm)

Axles (front)	Outer Left	Inner left	Inner Right	Outer Right	Steering Axle?
1	8			8	
2	8			8	✓
Comment:					

### Brake Lining/Pad Measurement (mm)

Axles (front)	Lining/Pad	Left	Right
1	Pad	8	8
2	Pad	9	9
Comment:			

### Rotor Thickness or Drum Inside Diameter Measurement (mm)

Axles (front)	Rotor/Drum	Left	Right
1	Rotor	34.00	34.00
2	Rotor	22.00	22.00
Comment:			

### Inspection Comments:

Has this Vehicle been road tested? Yes  When? After Inspection

Name of the person who did the road test: KARAMJIT

Inspector Name: GANDA, KARAMJIT SINGH

Signature: Kjanda

This Inspection Report was submitted to CVSE on 2022-Apr-07 02:53 PM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

### NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MIP at the Commercial Vehicle Safety Enforcement

CVSE0013

4/7/2022 2:53:16 PM



# Body Integrity Inspection Report

To be completed by the Designated Inspection Facility's Authorized Vehicle Inspector

### Designated Inspection Facility Information

Designated Inspection Facility Number

5 5 8 3 8

Authorized Inspector Number

1 0 8 1 8 3

DIF Facility Name ABBOTSFORD TUNE UP CENTRE LTD.

Inspector Name K. GANDA

Inspection Start Date

Inspection Completion Date

20 03 2022 04 09 2022

Inspector Signature

### VEHICLE OWNER

Name

Truone Motors

Address

333 twelfth st

City

New west Prov BC PC V3H4K5

Tel #

604 767 1933

### NAME OF REBUILDER (if other than owner)

Name

AMC AUTO GROUP LTD.

Address

#3 - 11435 132 A STREET

SURREY

Prov BC

PC V3R7S2

Tel #

7783171840

### Vehicle Information

TYPE OF VEHICLE:

Passenger Car

MPV

Truck

Motorhome

Taxi

Bus

Licence Plate N/A

Odometer

50281

Year

2018

Make

FORD

Model

F150

Registration Number

12922259

VIN/Serial #

1FTBW1E54TKA386513

I am satisfied that this rebuilt motor vehicle is the same as the one described in the record of rebuilding.

Yes

No

Requirements of Rebuilding		Components		R	C	VIM Reference Section	Components		R	C	VIM Reference Section
Photographs prior to rebuilding clearly showing vehicle damage	<input checked="" type="checkbox"/> Yes	STRUT			8 - 4	REAR STRUT TOWER					8 - 4 (b)
		- Left				- Left					
Structural Integrity Declaration Report	<input checked="" type="checkbox"/> Yes	- Right				- Right					
		HINGE (A) PILLAR			8 - 19	BUMPERS (Front/Rear)					8 - 5
4 Wheel Alignment Printout	<input checked="" type="checkbox"/> Yes	- Left				CROSSMEMBER					
		- Right			HOOD						8 - 1
Welded and structural components that require protection have been protected as required by OEM or I-CAR standard.	<input type="checkbox"/> Yes	CENTRE (B) PILLAR			8 - 19	RAD SUPPORT					
		- Left				BODY					
		- Right			FRAME						8 - 3
		LOCK (C) PILLAR			8 - 19	BULKHEAD (cowl)					
- Left			DOORS							8 - 6	
Vehicle meets symmetric and asymmetric specifications as indicated on the Structural Integrity Declaration Report.	<input checked="" type="checkbox"/> Yes	- Right			QUARTER PANELS						8 - 2 (c)
		ROCKER PANEL			8 - 19	- Left					
		- Left				- Right					
		- Right			FLOOR PAN						8 - 4 (a)

Front bumper, hood, headlight assembly, fenders, support fenders

"R" marked when item rejected

"C" marked when item corrected

I certify that this rebuilt vehicle meets all Structural Integrity requirements as defined in the Motor Vehicle Act Regulations and the BC Vehicle Inspection Manual.

Authorized Inspector Name (print)

Amir Yusef

Signature

[Signature]

# DYNAMIC AUTO CENTRE LTD.

1 UNIT #105 - 3918 HOLT RD  
SURREY, BC

Phone Number: 604-501-9780  
Fax Number: 604-501-9791

Customer: inline motors	Date: 3/25/2022 4:25:47 PM
Company:	VIN: 1ftewle59jki38653
License No:	Technician: aris
Odometer: 50281	Order No.:

## VEHICLE ALIGNMENT REPORT

FORD TRUCKS L. 2018, F150 PICKUP 4WD Crew Cab Heavy Duty 157-in Wheelbase 5.0L

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	3.2°	2.4°	4.4°	3.2°
		Right	3.7°	2.8°	4.8°	3.7°
	Camber	Left	-0.7°	-0.9°	0.7°	-0.7°
		Right	-0.1°	-0.9°	0.7°	-0.1°
	Toe	Left	2.05°	0.00°	0.20°	2.05°
		Right	-2.20°	0.00°	0.20°	-2.20°
Total		-0.15°	0.00°	0.40°	-0.15°	
Rear	Camber	Left	-0.4°	-----	-----	-0.4°
		Right	0.7°	-----	-----	0.7°
	Toe	Left	-0.20°	-----	-----	-0.20°
		Right	0.25°	-----	-----	0.25°
		Total	0.05°	-----	-----	0.05°
Thrust Angle		0.5°	-0.5°	0.5°	0.5°	
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left	14.3°	-----	-----	-----	14.3°
	Right	14.6°	-----	-----	-----	14.6°
Adjusted Angle	Left	13.5°	-----	-----	-----	13.5°
	Right	11.5°	-----	-----	-----	11.5°
Toe Out On Turns	Left	-----	0.0°	0.0°	-----	-----
	Right	-----	0.0°	0.0°	-----	-----
Maximum Turns	Left	-----	-----	-----	-----	-----
	Right	-----	-----	-----	-----	-----
Toe Curve Change	Left	-----	-----	-----	-----	-----
	Right	-----	-----	-----	-----	-----
Serback	Front	0.4°	-----	-----	-----	0.4°
	Rear	-0.2°	-----	-----	-----	-0.2°
Track Width Diff.		-----	-0.3°	-----	-----	-0.3°
Wheel Base Diff.		-----	0.0°	-----	-----	0.0°
Front Ride Height	Left	-----	-----	4.4°	5.4°	-----
	Right	-----	-----	4.4°	5.4°	-----
Rear Ride Height	Left	-----	-----	6.6°	7.5°	-----
	Right	-----	-----	6.6°	7.5°	-----
Frame Angle		-----	-----	-----	-----	-----

WE APPRECIATE YOU FOR YOUR SERVICE



BRITISH COLUMBIA

Ministry of Transportation and Infrastructure

Designated Inspection Facility

(DIF must issue this form for completion by an autobody technician)

Structural Integrity Declaration Report

Commercial Vehicle Safety and Enforcement Branch

Print Form

[X] PASS All requirements met

[ ] FAIL Requirements NOT met

Designated Inspection Facility Information

Designated Inspection Facility Number: 5 5 8 3 8

Facility Name: ABBOTSFORD TUNE UP CENTRE LTD.

Authorized Inspector Number: 1 0 8 1 8 3

Inspector Name: K. GANDA

Inspector Signature:

Date: 04/04/2022 Decal No.: PS21834

Vehicle Information

Owner: Fume Motors

Registration # 12922259 Plate # N/A

Address: 333 Swallow St

VIN # 1FTEW1E59JKF38658

City: New West Prov: BC PC V3M4W5 Make: FORD Model: F150 Year: 2018

Structural Integrity Declaration Report

Repair Standard and Vehicles Dimensions

1. I confirm that the repair / rebuild process for this vehicle has met or exceeded the rebuilding standards specified by the Inter-Industry Conference On Auto Collision Repair (I-CAR) and / or the Original Equipment Manufacturer (OEM), that the unitized vehicle body repair, including engine cradle, conforms to the OEM dimension standards and that a full-framed vehicle complies with the OEM, I-CAR repair standard.

Wheel alignment (all 4 wheels- attach printout) Alignment performed (facility name and address if other than above): NAME:

ADDRESS: copy Attached

Please indicate numbers and measurements on diagram below:

Table with columns for Front Left, Front Right, Rear Left, Rear Right and rows for Camber, Caster, Toe, SAI, Included Angle, Turning Angle.

Occupant Protection and Vehicle Components

2. I confirm that the assembly of body components have been performed in a manner that provides occupant protection that is equal to or exceeding OEM or I-CAR standards.

3. I confirm that the repairable structural components of the vehicle body have been assembled and repaired in accordance with methods, procedures and standards that will return the components to its original standard, quality and properties in accordance with the OEM, I-CAR standards.

4. I confirm that the assembly joints of the vehicle body are located in places and repaired in accordance with the OEM, I-CAR procedures and standards.

Wheel Alignment

5. I confirm that a four-wheel alignment has been performed and that steering angles and wheel tolerances are within the OEM, requirements for this vehicle. A four-wheel alignment computer printout has been included as part of this declaration.

I certify that this vehicle has been repaired in accordance with OEM/I-CAR standards as noted in items 1 - 5 above.

Technician Name: ARIS YUSOF

ALIGNMENT [X] PASS [ ] FAIL

Autobody Tech Trade Qualification # 00014-AB-19

Date Rebuilt Completed: 04/04/2022

Autobody Tech Trade Jurisdiction: BC

Rebuilder Name: AMC AUTO GROUP

Technician Signature: [Signature]

Rebuilder Address #3 - 11435 132A STREET

\* The ORIGINAL copy of this form must be forwarded to the designated inspection facility indicated above, and MUST be retained by the facility. \* This form must be the authentic original version signed by the autobody technician. Any photocopied, modified, altered, or changed form is unacceptable and must be rejected. \* A photocopy must accompany the customer's copy of the Vehicle Inspection Report (CVSE0013).