



Private Vehicle Inspection Report

Decal Number: FV14142
Decal Expiry Date: 2023-Oct-31
Inspection Number: 20291987

Inspection Result:
PASS

Facility:	ABBOTSFORD TUNE-UP CENTER / S5838	Inspection Type:	Complete	Inspection Start Date/Time:	2022-Oct-21 01:00 PM
Inspector:	MOHAMMAD YUSOF, MOHAMMAD ARIS / 203635	Inspection Class:	Class 1 - Light Vehicle with LGWV 5500 kg or less	Inspection Complete Date/Time:	2022-Oct-22 11:00 AM
Work Order Number:	16066	Inspection Reason:	Salvage Vehicle	Collision Repair Facility:	AMC AUTO
				Collision Repair Facility Phone:	(778) 317-1840
				Collision Repair Technician:	ARIS YUSOF

Vehicle Jurisdiction:	British Columbia	Brake Type:	Hydraulic	Owner/Lessee Name:	INLINE MOTORS, INLINE MOTORS
Registration Number:	11407582	Fuel Type:	Gasoline	Address:	333 TWELFTH STREET
VIN:	1FADP3K22EL352585	Odometer:	10700 KM	City:	New Westminster
Plate Number:		Hub Odometer:		Province/State:	British Columbia
Licensed GVW (kg):	0	Body Style:	Hatchback	Postal Code/ZIP:	V3M4H5
Vehicle Year:	2014	Model:		Country:	Canada
Make:	FORD				

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Passed	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Passed	

Tire Tread Depth (mm)

Axles (front)	Outer Left	Inner left	Inner Right	Outer Right	Steering Axle?
1	8			8	✓
2	8			8	

Comment:

Brake Lining/Pad Measurement (mm)

Axles (front)	Lining/Pad	Left	Right
1	Pad	8	8
2	Lining (Shoe)	4	4

Comment:

Rotor Thickness or Drum Inside Diameter Measurement (mm)

Axles (front)	Rotor/Drum	Left	Right
1	Rotor	26.00	26.23
2	Drum	228.00	228.00

Comment:

Inspection Comments:

Has this Vehicle been road tested? Yes When? After Inspection

Name of the person who did the road test: ARIS

Inspector Name: MOHAMMAD YUSOF, MOHAMMAD ARIS

Signature: 

This Inspection Report was submitted to CVSE on 2022-Oct-23 09:59 PM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MIP at the Commercial Vehicle Safety Enforcement

CVSE0013

10/23/2022 9:59:57 PM



Body Integrity Inspection Report

To be completed by the Designated Inspection Facility's Authorized Vehicle Inspector

Designated Inspection Facility Information

Designated Inspection Facility Number 5 5 8 3 8

Authorized Inspector Number 2 0 3 6 3 5

DIF Facility Name ABBOTSFORD TUNE UP CENTRE

Inspector Name ARIS YUSOF

Inspection Start Date 20/10/2022, Inspection Completion Date 21/10/2022

Inspector Signature [Signature]

VEHICLE OWNER

Name F.M.M. Motors, Address 333 Tweeddale St, City New West Prov BC, Tel # 6045498222

NAME OF REBUILDER (if other than owner)

Name AMC AUTO, Address #3-11435 132A STREET, SURREY Prov BC, Tel # 7783171840

Vehicle Information

TYPE OF VEHICLE: [X] Passenger Car, [] MPV, [] Truck, [] Motorhome, [] Taxi, [] Bus

Licence Plate N/A, Odometer 10700, Year 2014, Make FORD, Model Focus

Registration Number 11407592, VIN/Serial # 1FADP8K22A2359585

I am satisfied that this rebuilt motor vehicle is the same as the one described in the record of rebuilding. [X] Yes [] No

Table with columns: Requirements of Rebuilding, Components, R, C, VIM Reference Section, Components, R, C, VIM Reference Section. Rows include Strut, Hinge (A) Pillar, Centre (B) Pillar, Lock (C) Pillar, Rocker Panel, Rear Strut Tower, Bumpers, Hood, Rad Support, Body, Frame, Bulkhead, Doors, Quarter Panels, Floor Pan.

front bumper assembly, headlight, rad support. "R" marked when item rejected, "C" marked when item corrected

I certify that this rebuilt vehicle meets all Structural Integrity requirements as defined in the Motor Vehicle Act Regulations and the BC Vehicle Inspection Manual.

Authorized Inspector Name (print) ARIS YUSOF

Signature [Signature]