# Private Vehicle Inspection Report

BRITISH COLUMBIA

**Decal Number:** FT86285
**Decal Expiry Date:** 2023-Sep-30
**Inspection Number:** 20253968

**Inspection Result:** PASS

| | | | | | |
|---|---|---|---|---|---|
| **Facility:** | ABBOTSFORD TUNE-UP CENTER / S5838 | **Inspection Type:** | Complete | **Inspection Start Date/Time:** | 2022-Sep-21 12:00 PM |
| **Inspector:** | MOHAMMAD YUSOF, MOHAMMAD ARIS / 203635 | **Inspection Class:** | Class 1 - Light Vehicle with LGVW 5500 kg or less | **Inspection Complete Date/Time:** | 2022-Sep-21 01:30 PM |
| **Work Order Number:** | 15999 | **Inspection Reason:** | Salvage Vehicle | **Collision Repair Facility:** | AMC AUTO |
| | | | | **Collision Repair Facility Phone:** | (778) 317-1840 |
| | | | | **Collision Repair Technician:** | ARIS YUSOF |

| | | | | | |
|---|---|---|---|---|---|
| **Vehicle Jurisdiction:** | British Columbia | **Brake Type:** | Hydraulic | **Owner/Lessee Name:** | INLINE MOTORS LTD., INLINE MOTORS LTD. |
| **Registration Number:** | 12362419 | **Fuel Type:** | Gasoline | **Address:** | 333 TWELFTH STREET |
| **VIN:** | 2HGFC2F51HH027703 | **Odometer:** | 99730 KM | **City:** | New Westminster |
| **Plate Number:** | | **Hub Odometer:** | | **Province/State:** | British Columbia |
| **Licenced GVW (kg):** | 0 | **Body Style:** | 4 Door Sedan | **Postal Code/ZIP:** | V3M4H5 |
| **Vehicle Year:** | 2017 | **Model:** | | **Country:** | Canada |
| **Make:** | HONDA | | | | |

| | Result | Comment |
|---|---|---|
| Vehicle Identification (VIN) | Passed | |
| Section 1 - Power Train | Passed | |
| Section 2 - Suspension | Passed | |
| Section 3 - Brake System | Passed | |
| Section 3H - Hydraulic Brakes | Passed | |
| Section 4 - Steering | Passed | |
| Section 5 - Instruments and Auxiliary Equipment | Passed | |
| Section 6 - Lamps | Passed | |
| Section 7 - Electrical System | Passed | |
| Section 8 - Frame and Body | Passed | |
| Section 9A - Tires | Passed | |
| Section 9B - Wheels | Passed | |
| Section 10 - Coupling Devices | Not Applicable | |
| Section 11 - Other Vehicle Components | Passed | |

**Tire Tread Depth (mm)**

| Axles (front) | Outer Left | Inner left | Inner Right | Outer Right | Steering Axle? |
|---|---|---|---|---|---|
| 1 | 6 | | | 6 | ✓ |
| 2 | 6 | | | 6 | |

Comment:

**Brake Lining/Pad Measurement (mm)**

| Axles (front) | Lining/Pad | Left | Right |
|---|---|---|---|
| 1 | Pad | 6 | 6 |
| 2 | Pad | 7 | 7 |

Comment:

**Rotor Thickness or Drum Inside Diameter Measurement (mm)**

| Axles (front) | Rotor/Drum | Left | Right |
|---|---|---|---|
| 1 | Rotor | 22.62 | 22.88 |
| 2 | Rotor | 9.09 | 9.12 |

Comment:

**Inspection Comments:**

**Has this Vehicle been road tested?** Yes **When?** After Inspection **Name of the person who did the road test:** ARIS

**Inspector Name:** MOHAMMAD YUSOF, MOHAMMAD ARIS **Signature:**

This Inspection Report was submitted to CVSE on 2022-Sep-22 10:57 AM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0013

9/22/2022 10:57:34 AM

BRITISH COLUMBIA | Ministry of Transportation and Infrastructure

Print Form

# Body Integrity Inspection Report

*To be completed by the Designated Inspection Facility's Authorized Vehicle Inspector*

## Designated Inspection Facility Information

Designated Inspection Facility Number: S 5 8 3 8

Authorized Inspector Number: 2 0 3 6 3 5

DIF Facility Name: ABBOTSFORD TUNE UP

Inspector Name: ARIS YUSOF

Inspection Start Date: 21 (Day) 09 (Month) 2022 (Year)

Inspection Completion Date: 21 (Day) 09 (Month) 2022 (Year)

Inspector Signature: [signature]

## VEHICLE OWNER

Name: Facire Motors

Address: 333 Fraser St

City: New West Prov: BC PC: V3M4H5

Tel #: 604 767 1933

## NAME OF REBUILDER (if other than owner)

Name: ANC AUTO GROUP LTD.

Address: #3 - 11435 132A STREET

City: SURREY Prov: BC PC: V3R7S2

Tel #: 7783171840

## Vehicle Information

TYPE OF VEHICLE: ☒ Passenger Car ☐ MPV ☐ Truck ☐ Motorhome ☐ Taxi ☐ Bus

Licence Plate: N/A Odometer: 99730 Year: 2017 Make: Honda Model: Civic

Registration Number: 12362414 VIN/Serial #: 2HGFC2A51HH027703

*I am satisfied that this rebuilt motor vehicle is the same as the one described in the record of rebuilding.* ☒ Yes ☐ No

| Requirements of Rebuilding | |
|---|---|
| Photographs prior to rebuilding clearly showing vehicle damage | ☒ Yes |
| Structural Integrity Declaration Report | ☒ Yes |
| 4 Wheel Alignment Printout | ☒ Yes |
| Welded and structural components that require protection have been protected as required by OEM or I-CAR standard. | ☒ Yes |
| Vehicle meets symmetric and asymmetric specifications as indicated on the Structural Integrity Declaration Report. | ☒ Yes |

| Components | R | C | VIM Reference Section |
|---|---|---|---|
| STRUT | | | 8 - 4 |
| - Left | | | |
| - Right | | | |
| HINGE (A) PILLAR | | | 8 - 19 |
| - Left | | | |
| - Right | | | |
| CENTRE (B) PILLAR | | | 8 - 19 |
| - Left | | | |
| - Right | | | |
| LOCK (C) PILLAR | | | 8 - 19 |
| - Left | | | |
| - Right | | | |
| ROCKER PANEL | | | 8 - 19 |
| - Left | | | |
| - Right | | | |

| Components | R | C | VIM Reference Section |
|---|---|---|---|
| REAR STRUT TOWER | | | 8 - 4 (b) |
| - Left | | | |
| - Right | | | |
| BUMPERS (Front/Rear) | | ✓ | 8 - 5 |
| CROSSMEMBER | | | 8 - 3 (c) |
| HOOD | | ✓ | 8 - 1 |
| RAD SUPPORT | | ✓ | |
| BODY | | ✓ | 8 - 2 |
| FRAME | | | 8 - 3 |
| BULKHEAD (cowl) | | | |
| DOORS | | | 8 - 6 |
| QUARTER PANELS | | | 8 - 2 (c) |
| - Left | | | |
| - Right | | | |
| FLOOR PAN | | | 8 - 4 (a) |

Front bumper, hood, headlight, cooling, fenders, rad support.

"R" marked when item rejected

"C" marked when item corrected

*I certify that this rebuilt vehicle meets all Structural Integrity requirements as defined in the Motor Vehicle Act Regulations and the BC Vehicle Inspection Manual.*

Authorized Inspector Name (print): ARIS YUSOF Signature: [signature]

CVSE0031 (May 27, 2013)

# DYNAMIC AUTO CENTRE LTD.

UNIT #105 - [illegible]
[illegible]

Phone Number: 604-[illegible]
Fax Number: 604-[illegible]

| | | | |
|---|---|---|---|
| Customer: | [illegible] MOTORS | Date: | 9/21/2022 6:30:55 PM |
| Company: | | VIN: | 2HGFC2F51HH027703 |
| License No: | | Technician: | ARIS |
| Odometer: | [illegible] | [illegible] | |

## VEHICLE ALIGNMENT REPORT

HONDA, 2016, CIVIC [illegible]

| Primary Angles | | | Initial | Specifications Min. | Specifications Max. | Final |
|---|---|---|---|---|---|---|
| [illegible] | Caster | Left | [illegible] | [illegible] | 5.9° | [illegible] |
| | | Right | [illegible] | [illegible] | 5.9° | [illegible] |
| | Camber | Left | [illegible] | [illegible] | 0.2° | [illegible] |
| | | Right | [illegible] | -0.8° | 0.2° | -0.2° |
| | Toe | Left | [illegible] | -0.10° | 0.10° | 0.00° |
| | | Right | [illegible] | [illegible] | 0.10° | 0.05° |
| | | Total | [illegible] | [illegible] | 0.15° | 0.05° |
| Rear | Camber | Left | [illegible] | [illegible] | -0.5° | [illegible] |
| | | Right | [illegible] | [illegible] | -0.5° | [illegible] |
| | Toe | Left | [illegible] | [illegible] | 0.15° | 0.10° |
| | | Right | [illegible] | 0.05° | 0.15° | 0.05° |
| | | Total | [illegible] | [illegible] | 0.30° | 0.15° |
| | Thrust Angle | | [illegible] | ------ | ------ | 0.0° |

| Secondary Angles | | Initial | Specifications Min. | Specifications Max. | Final |
|---|---|---|---|---|---|
| [illegible] | Left | 15.0° | ------ | ------ | 15.0° |
| | Right | [illegible] | ------ | ------ | 15.1° |
| Included Angle | Left | [illegible] | ------ | ------ | 14.9° |
| | Right | [illegible] | ------ | ------ | 14.9° |
| Toe Out On Turns | Left | ------ | 0.0° | 0.0° | ------ |
| | Right | ------ | 0.0° | 0.0° | ------ |
| Maximum Turns | Left | ------ | 38.1° | 42.1° | ------ |
| | Right | ------ | 38.1° | 42.1° | ------ |
| Toe Curve Change | Left | ------ | ------ | ------ | ------ |
| | Right | ------ | ------ | ------ | ------ |
| [illegible] | Front | [illegible] | ------ | ------ | 0.1° |
| | Rear | [illegible] | ------ | ------ | 0.1° |
| Track Width Diff | | [illegible] | | | -0.4° |
| Wheel Base Diff | | [illegible] | | | 0.0° |
| Front Ride Height | Left | ------ | ------ | ------ | ------ |
| | Right | ------ | ------ | ------ | ------ |
| Rear Ride Height | Left | ------ | ------ | ------ | ------ |
| | Right | ------ | ------ | ------ | ------ |
| [illegible] | | | | | ------ |

[illegible]dynamicautocen [illegible] FOR [illegible] SERVICE

BRITISH COLUMBIA | Ministry of Transportation and Infrastructure

Print Form

# Designated Inspection Facility

*(DIF must issue this form for completion by an autobody technician)*

# Structural Integrity Declaration Report

Commercial Vehicle Safety and Enforcement Branch

☑ **PASS** All requirements met ☐ **FAIL** Requirements NOT met

## Designated Inspection Facility Information

Designated Inspection Facility Number: S 5 8 3 8

Facility Name: ABBOTSFORD TUNE UP CENTER

Authorized Inspector Number: 2 0 3 6 3 5

Inspector Name: ARIS YUSOF

Inspector Signature:

Date: 21/09/2022 Decal No.: FT86285

## Vehicle Information

Owner: Enline Motors

Registration #: 1236241/9 Plate #: N/A

Address: 333 Fenwick St

VIN #: 2HGFC2F57HH027705

City: New West Prov: BC PC: V3M1G9

Make: Honda Model: Civic Year: 2016

## Structural Integrity Declaration Report

**Repair Standard and Vehicles Dimensions**

1. I confirm that the repair / rebuild process for this vehicle has met or exceeded the rebuilding standards specified by the Inter-Industry Conference On Auto Collision Repair (I-CAR) and / or the Original Equipment Manufacturer (OEM), that the unitized vehicle body repair, including engine cradle, conforms to the OEM dimension standards and that a full-framed vehicle complies with the OEM, I-CAR repair standard.

**Occupant Protection and Vehicle Components**

2. I confirm that the assembly of body components have been performed in a manner that provides occupant protection that is equal to or exceeding OEM or I-CAR standards.

3. I confirm that the repairable structural components of the vehicle body have been assembled and repaired in accordance with methods, procedures and standards that will return the components to its original standard, quality and properties in accordance with the OEM, I-CAR standards.

4. I confirm that the assembly joints of the vehicle body are located in places and repaired in accordance with the OEM, I-CAR procedures and standards.

**Wheel Alignment**

5. I confirm that a four-wheel alignment has been performed and that steering angles and wheel tolerances are within the OEM, requirements for this vehicle. A four-wheel alignment computer printout has been included as part of this declaration.

*I certify that this vehicle has been repaired in accordance with OEM/I-CAR standards as noted in items 1 - 5 above.*

Technician Name (please print): ARIS YUSOF

Autobody Tech Trade Qualification #: 0014-AB-19

Autobody Tech Trade Jurisdiction: BC

Technician Signature:

Wheel alignment (all 4 wheels- attach printout) Alignment performed (facility name and address if other than above):

NAME: AMC Auto.

ADDRESS:

*Please indicate numbers and measurements on diagram below:*

From inside vehicle:

| | Front Left | Front Right | |
|---|---|---|---|
| | Camber | Camber | |
| | Caster | Caster | |
| | Toe | Toe | |
| | SAI | SAI | |
| | Included Angle | Included Angle | |
| | Turning Angle | Turning Angle | |
| | **Rear Left** | **Rear Right** | |
| | Camber | Camber | |
| | Caster | Caster | |
| | Toe | Toe | |
| | SAI | SAI | |
| | | | |
| | | | |
| ALIGNMENT | | ☒ PASS | ☐ FAIL |

Date Rebuilt Completed: 21/09/2022

Rebuilder Name (if different from technician): AMC AUTO

Rebuilder Address: #3 - 11455 132A STREET

* The **ORIGINAL** copy of this form must be forwarded to the designated inspection facility indicated above, and **MUST** be retained by the facility.
* This form must be the authentic original version signed by the autobody technician. Any photocopied, modified, altered, or changed form is unacceptable and must be rejected.
* A photocopy must accompany the customer's copy of the Vehicle Inspection Report (CVSE0013).

CVSE0032

Revised - April 29, 2013