



# Private Vehicle Inspection Report

Decal Number: FV14158  
Decal Expiry Date: 2023-Oct-31  
Inspection Number: 20300607

Inspection Result:  
**PASS**

Facility: ABBOTSFORD TUNE-UP CENTER / S5838  
Inspector: MOHAMMAD YUSOF, MOHAMMAD ARIS / 203635  
Work Order Number: 16075  
Inspection Type: Complete  
Inspection Class: Class 1 - Light Vehicle with LGVW 5500 kg or less  
Inspection Reason: Salvage Vehicle  
Inspection Start Date/Time: 2022-Oct-17 04:30 PM  
Inspection Complete Date/Time: 2022-Oct-28 05:00 PM  
Collision Repair Facility: AMC AUTO  
Collision Repair Facility Phone: (778) 317-1840  
Collision Repair Technician: ARIS YUSOF

Vehicle Jurisdiction: British Columbia  
Registration Number: 12270359  
VIN: 3CZR5G35HM102325  
Plate Number:  
Licenced GVW (kg): 0  
Vehicle Year: 2017  
Make: HONDA  
Brake Type: Hydraulic  
Fuel Type: Gasoline  
Odometer: 69642 KM  
Hub Odometer:  
Body Style: 4 Door Stationwagon  
Model:  
Owner/Lessee Name: INLINE MOTORS LTD., INLINE MOTORS LTD.  
Address: 333 TWELFTH STREET  
City: New Westminster  
Province/State: British Columbia  
Postal Code/ZIP: V3M4H5  
Country: Canada

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Passed	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Passed	

## Tire Tread Depth (mm)

Axles (front)	Outer Left	Inner Left	Inner Right	Outer Right	Steering Axle?
1	8			8	✓
2	8.5			8.5	

Comment:

## Brake Lining/Pad Measurement (mm)

Axles (front)	Lining/Pad	Left	Right
1	Pad	8	8
2	Pad	7	7

Comment:

## Rotor Thickness or Drum Inside Diameter Measurement (mm)

Axles (front)	Rotor/Drum	Left	Right
1	Rotor	25.57	25.81
2	Rotor	10.02	10.69

Comment:

## Inspection Comments:

Has this Vehicle been road tested? Yes When? After Inspection

Name of the person who did the road test: ARIS

Inspector Name: MOHAMMAD YUSOF, MOHAMMAD ARIS

Signature:

This Inspection Report was submitted to CVSE on 2022-Oct-28 11:53 PM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MIP at the Commercial Vehicle Safety Enforcement.

CVSE0013

10/28/2022 11:53:35 PM



**BRITISH COLUMBIA**

Ministry of Transportation  
and Infrastructure

Print Form

# Body Integrity Inspection Report

To be completed by the Designated Inspection Facility's Authorized Vehicle Inspector

Designated Inspection Facility Information

Designated Inspection Facility Number

S 5 8 3 8

DIF Facility Name ABBOTSFORD TUNE UP CENTRE

Authorized Inspector Number

2 0 3 6 3 5

Inspection Start Date

17 10 2022

Inspection Completion Date

28 10 2022

Inspector Name ARIS YUSOF

Inspector Signature

*[Signature]*

VEHICLE OWNER

Name

Taline Motors

Address

333 Fourth St

City

New West

Prov B.C. PC

V3H448

Tel #

604 767 1933

Name

AMC AUTO

Address

#3-11435 132A STREET

City

SURREY

Prov BC

PC V3R752

Tel #

7783171840

Vehicle Information

TYPE OF VEHICLE:

☒ Passenger Car

☐ MPV

☐ Truck

☐ Motorhome

☐ Taxi

☐ Bus

Licence Plate N/A

Odometer

69642

Year

2017

Make

Honda

Model

HR-V

Registration Number

12970 359

VIN/Serial #

3CZRU5G35AM102325

I am satisfied that this rebuilt motor vehicle is the same as the one described in the record of rebuilding.

☒ Yes

☐ No

Requirements of Rebuilding		Components		R	C	VIM Reference Section	Components		R	C	VIM Reference Section
Photographs prior to rebuilding clearly showing vehicle damage	<input checked="" type="checkbox"/> Yes	STRUT				8-4	REAR STRUT TOWER				8-4 (b)
Structural Integrity Declaration Report	<input checked="" type="checkbox"/> Yes	- Left					- Left				
4 Wheel Alignment Printout	<input checked="" type="checkbox"/> Yes	- Right					- Right				
Welded and structural components that require protection have been protected as required by OEM or I-CAR standard.	<input checked="" type="checkbox"/> Yes	HINGE (A) PILLAR				8-19	BUMPERS (Front/Rear)			<input checked="" type="checkbox"/>	8-5
		- Left					CROSSMEMBER			<input checked="" type="checkbox"/>	
		- Right					HOOD			<input checked="" type="checkbox"/>	
		CENTRE (B) PILLAR				8-19	RAD SUPPORT			<input checked="" type="checkbox"/>	8-1
		- Left					BODY			<input checked="" type="checkbox"/>	
		- Right					FRAME			<input checked="" type="checkbox"/>	
Vehicle meets symmetric and asymmetric specifications as indicated on the Structural Integrity Declaration Report.	<input checked="" type="checkbox"/> Yes	LOCK (C) PILLAR				8-19	BULKHEAD (cowl)				8-3
		- Left					DOORS				
		- Right					QUARTER PANELS				
		ROCKER PANEL				8-19	- Left				8-2 (c)
		- Left					- Right				
		- Right					FLOOR PAN				

Front bumper Assembly hood  
headlight Chasing Assembly  
Needed for support Air bags.

"R" marked when item rejected  
"C" marked when item corrected

I certify that this rebuilt vehicle meets all Structural Integrity requirements as defined in the Motor Vehicle Act Regulations and the BC Vehicle Inspection Manual.

Authorized Inspector Name (print) ARIS YUSOF

Signature

*[Signature]*

CVSE0031 (May 27, 2013)





BRITISH  
COLUMBIA

Ministry of Transportation  
and Infrastructure

# Designated Inspection Facility

(DIF must issue this form for completion by an autobody technician)

## Structural Integrity Declaration Report

Commercial Vehicle Safety and Enforcement Branch

Print Form

☒ **PASS** All requirements met

☐ **FAIL** Requirements NOT met

Designated Inspection Facility Information

Designated Inspection Facility Number: **5 5 8 3 8**

Facility Name: **ABBOTSFORD TUNE UP CENTRE**

Authorized Inspector Number: **2 0 3 6 3 5**

Inspector Name: **ARIS YUSOF**

Inspector Signature:

Date: **28/10/2022** Decal No.: **FV141158**

Vehicle Information

Owner: **Tacine Motors** Registration # **12270359** Plate # **N/A**  
Address: **333 12th St** VIN # **3C2RU535HM102325**  
City: **New West** Prov **BC** PC **V3M448** Make **Honda** Model **HR-V** Year **2017**

### Structural Integrity Declaration Report

#### Repair Standard and Vehicles Dimensions

1. I confirm that the repair / rebuild process for this vehicle has met or exceeded the rebuilding standards specified by the Inter-Industry Conference On Auto Collision Repair (I-CAR) and / or the Original Equipment Manufacturer (OEM), that the unitized vehicle body repair, including engine cradle, conforms to the OEM dimension standards and that a full-framed vehicle complies with the OEM, I-CAR repair standard.

#### Occupant Protection and Vehicle Components

2. I confirm that the assembly of body components have been performed in a manner that provides occupant protection that is equal to or exceeding OEM or I-CAR standards.

3. I confirm that the repairable structural components of the vehicle body have been assembled and repaired in accordance with methods, procedures and standards that will return the components to its original standard, quality and properties in accordance with the OEM, I-CAR standards.

4. I confirm that the assembly joints of the vehicle body are located in places and repaired in accordance with the OEM, I-CAR procedures and standards.

#### Wheel Alignment

5. I confirm that a four-wheel alignment has been performed and that steering angles and wheel tolerances are within the OEM, requirements for this vehicle. A four-wheel alignment computer printout has been included as part of this declaration.

I certify that this vehicle has been repaired in accordance with OEM/I-CAR standards as noted in Items 1 - 5 above.

Technician Name  
please print **ARIS YUSOF**

Autobody Tech Trade Qualification # **0014-AB-19**

Autobody Tech Trade Jurisdiction **BC**

Technician Signature:

Wheel alignment (all 4 wheels- attach printout) Alignment performed (facility name and address if other than above):  
NAME: **AMC Auto**

ADDRESS:

Please indicate numbers and measurements on diagram below:

From inside vehicle:	Front Left	Front Right
-1.1	Camber	Camber -0.3
4.4	Caster	Caster 5.0
0.05	Toe	Toe 0.05
	SAI	SAI
	Included Angle	Included Angle
	Turning Angle	Turning Angle
Rear Left		Rear Right
-1.6	Camber	Camber -1.4
	Caster	Caster
12.10	Toe	Toe 0.30
	SAI	SAI

ALIGNMENT

☒ **PASS**

☐ **FAIL**

Date Rebuilt Completed **28/10/2022**

Rebuilder Name  
(if different from technician) **AMC AUTO**

Rebuilder Address #3 - 11435 132A STREET

- \* The ORIGINAL copy of this form must be forwarded to the designated inspection facility indicated above, and MUST be retained by the facility.
- \* This form must be the authentic original version signed by the autobody technician. Any photocopied, modified, altered, or changed form is unacceptable and must be rejected.
- \* A photocopy must accompany the customer's copy of the Vehicle Inspection Report (CVSE0013).