



Private Vehicle Inspection Report

Decal Number: **FW42718**
Decal Expiry Date: **2023-Dec-31**
Inspection Number: **20342827**

Inspection Result:
PASS

Facility:	ABBOTSFORD TUNE-UP CENTER / S5838	Inspection Type:	Complete	Inspection Start Date/Time:	2022-Dec-05 09:00 AM
Inspector:	MOHAMMAD YUSOF, MOHAMMAD ARIS / 203635	Inspection Class:	Class 1 - Light Vehicle with LGVW 5500 kg or less	Inspection Complete Date/Time:	2022-Dec-06 07:00 PM
Work Order Number:	16131	Inspection Reason:	Salvage Vehicle	Collision Repair Facility:	AMC AUTO
				Collision Repair Phone:	(778) 317-1840
				Collision Repair Technician:	ARIS YUSOF

Vehicle Jurisdiction:	British Columbia	Brake Type:	Hydraulic	Owner/Lessee Name:	ANI ENTERPRISE LTD., ANI ENTERPRISE LTD.
Registration Number:	13802071	Fuel Type:	Gasoline	Address:	333 TWELFTH STREET
VIN:	KNDJ33AU4M7753929	Odometer:	48676 KM	City:	New Westminster
Plate Number:		Hub Odometer:		Province/State:	British Columbia
Licensed GVW (kg):	0	Body Style:	4 Door Stationwagon	Postal Code/ZIP:	V3M4H5
Vehicle Year:	2021	Model:		Country:	Canada
Make:	KIA				

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Passed	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Passed	

Tire Tread Depth (mm)					
Axles (front)	Outer Left	Inner left	Inner Right	Outer Right	Steering Axle?
1	6			6	✓
2	5			5	
Comment:					

Brake Lining/Pad Measurement (mm)				Rotor Thickness or Drum Inside Diameter Measurement (mm)			
Axles (front)	Lining/Pad	Left	Right	Axles (front)	Rotor/Drum	Left	Right
1	Pad	6	6	1	Rotor	24.00	24.15
2	Pad	6	6	2	Rotor	11.11	11.02
Comment:				Comment:			

Inspection Comments:

Has this Vehicle been road tested? Yes When? Before and After Inspection Name of the person who did the road test: ARIS

Inspector Name: MOHAMMAD YUSOF, MOHAMMAD ARIS Signature:

This Inspection Report was submitted to CVSE on 2022-Dec-06 10:05 PM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MP at the Commercial Vehicle Safety Enforcement

CVSE0013

12/6/2022 10:05:50 PM



Body Integrity Inspection Report

To be completed by the Designated Inspection Facility's Authorized Vehicle Inspector

Designated Inspection Facility Information

Designated Inspection Facility Number

5 5 8 3 8

DIF Facility Name ABBOTSFORD TUNE UP

Authorized Inspector Number

203635

Inspector Name

Asa Wilson

Inspector Signature

[Signature]

Inspection Start Date

Inspection Completion Date

05 19 2022

06 19 2022

VEHICLE OWNER

Name

Audi Enterprise

Address

333 Tweed Ave.

City

New West Prov BC PC V3M4H8

Tel #

604 767 1933

NAME OF REBUILDER (if other than owner)

Name

AMC AUTO

Address

11435 132A STREET

City

SURREY

Prov BC

PC V3R7S2

Tel #

7783171840

Vehicle Information

TYPE OF VEHICLE:

Passenger Car

MPV

Truck

Motorhome

Taxi

Bus

Licence Plate N/A

Odometer

48670

Year

2021

Make

Kia

Model

Soul

Registration Number

13802071

VIN/Serial #

XNDJ3JAK4M7753929

I am satisfied that this rebuilt motor vehicle is the same as the one described in the record of rebuilding.

Yes

No

Requirements of Rebuilding		Components			R	C	VIM Reference Section	Components			R	C	VIM Reference Section
Photographs prior to rebuilding clearly showing vehicle damage	<input checked="" type="checkbox"/> Yes	STRUT				8-4	REAR STRUT TOWER					8-4 (b)	
		- Left			- Left								
Structural Integrity Declaration Report	<input checked="" type="checkbox"/> Yes	HINGE (A) PILLAR				8-19	BUMPERS (Front/Rear)					8-5	
		- Left			- Right								
4 Wheel Alignment Printout	<input checked="" type="checkbox"/> Yes	CENTRE (B) PILLAR				8-19	CROSSMEMBER					8-3 (c)	
		- Left			- Right								
Welded and structural components that require protection have been protected as required by OEM or I-CAR standard.	<input checked="" type="checkbox"/> Yes	LOCK (C) PILLAR				8-19	HOOD					8-1	
		- Left			- Right								
Vehicle meets symmetric and asymmetric specifications as indicated on the Structural Integrity Declaration Report.	<input checked="" type="checkbox"/> Yes	ROCKER PANEL				8-19	RAD SUPPORT					8-2	
		- Left			- Right								
						8-19	FRAME					8-3	
							BULKHEAD (cowl)						8-6
						8-19	DOORS					8-2 (c)	
							QUARTER PANELS						8-4 (a)
						8-19	- Left					8-4 (a)	
							- Right						
						8-19	FLOOR PAN					8-4 (a)	

sun + bumper hood, fenders, headlight

"R" marked when item rejected
"C" marked when item corrected

I certify that this rebuilt vehicle meets all Structural Integrity requirements as defined in the Motor Vehicle Act Regulations and the BC Vehicle Inspection Manual.

Authorized Inspector Name (print)

Asa Wilson

Signature

[Signature]

DYNAMIC AUTO CENTRE LTD.

UNIT #105 - 8918 HOLT RD
SURREY, BC

Phone Number: 604-591-9700
Fax Number: 604-591-9701

Customer: inline	Date: 12/6/2022 3:27:53 PM
Company:	VIN: kn dj53au4m7753929
License No:	Technician: mik
kilometer: 48670	Order #: 1

VEHICLE ALIGNMENT REPORT

KIA, 2020, SOUL (SK3) 2.0MPI

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	2.2°	3°	3.8°	2.2°
		Right	4.2°	3.3°	4.8°	4.2°
	Camber	Left	-0.8°	-1.0°	0.0°	-0.8°
		Right	-0.3°	-1.0°	0.0°	-0.3°
	Toe	Left	-0.60°	-0.05°	0.15°	-0.05°
		Right	0.58°	-0.05°	0.15°	0.00°
Total		-0.02°	-0.10°	0.30°	0.00°	
Rear	Camber	Left	-1.1°	-1.7°	-0.7°	-1.1°
		Right	-1.1°	-1.7°	-0.7°	-1.1°
	Toe	Left	0.30°	0.00°	0.30°	0.00°
		Right	0.30°	0.00°	0.30°	0.25°
		Total	0.28°	0.00°	0.60°	0.25°
	Thrust Angle			0.0°	-----	-----
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
Caster	Left		13.8°	13.3°	14.3°	13.8°
	Right		13.7°	13.3°	14.3°	13.7°
Crowned Angle	Left		13.2°	-----	-----	13.2°
	Right		13.4°	-----	-----	13.4°
Toe Out On Turns	Left		-----	0.0°	0.0°	-----
	Right		-----	0.0°	0.0°	-----
Maximum Turns	Left		-----	37.0°	39.0°	-----
	Right		-----	37.0°	39.0°	-----
Steer Curve Change	Left		-----	-----	-----	-----
	Right		-----	-----	-----	-----
Squatback	Front		-0.1°	-----	-----	0.0°
	Rear		0.0°	-----	-----	0.0°
Track Width Diff.			-0.1°	-----	-----	-0.1°
Wheelbase Diff.			-0.1°	-----	-----	0.0°
Front knee Height	Left		-----	15.2°	16.0°	-----
	Right		-----	15.2°	16.0°	-----
Rear knee Height	Left		-----	15.3°	16.1°	-----
	Right		-----	15.3°	16.1°	-----
Transverse						



Private Vehicle Inspection Report

Decal Number: FW42718
 Decal Expiry Date: 2023-Dec-31
 Inspection Number: 20342827

Inspection Result:
PASS

Facility: ABBOTSFORD TUNE-UP CENTER / S5838
 Inspector: MOHAMMAD YUSOF, MOHAMMAD ARIS / 203635
 Work Order Number: 16131

Inspection Type: Complete
 Inspection Class: Class 1 - Light Vehicle with LGVW 5500 kg or less
 Inspection Reason: Salvage Vehicle

Inspection Start Date/Time: 2022-Dec-05 09:00 AM
 Inspection Complete Date/Time: 2022-Dec-06 07:00 PM
 Collision Repair Facility: AMC AUTO
 Collision Repair Facility Phone: (778) 317-1840
 Collision Repair Technician: ARIS YUSOF

Vehicle Jurisdiction: British Columbia
 Registration Number: 13802071
 VIN: KNDJ33AU4M7753929
 Plate Number:
 Licenced GVW (kg): 0
 Vehicle Year: 2021
 Make: KIA

Brake Type: Hydraulic
 Fuel Type: Gasoline
 Odometer: 48676 KM
 Hub Odometer:
 Body Style: 4 Door Stationwagon
 Model:

Owner/Lessee Name: ANI ENTERPRISE LTD., ANI ENTERPRISE LTD.
 Address: 333 TWELFTH STREET
 City: New Westminster
 Province/State: British Columbia
 Postal Code/ZIP: V3M4H5
 Country: Canada

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Passed	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Passed	

Tire Tread Depth (mm)

Axles (front)	Outer Left	Inner Left	Inner Right	Outer Right	Steering Axle?
1	6			6	✓
2	5			5	
Comment:					

Brake Lining/Pad Measurement (mm)

Axles (front)	Lining/Pad	Left	Right
1	Pad	6	6
2	Pad	6	6
Comment:			

Rotor Thickness or Drum Inside Diameter Measurement (mm)

Axles (front)	Rotor/Drum	Left	Right
1	Rotor	24.00	24.16
2	Rotor	11.11	11.02
Comment:			

Inspection Comments:

Has this Vehicle been road tested? Yes When? Before and After Inspection

Inspector Name: MOHAMMAD YUSOF, MOHAMMAD ARIS

Name of the person who did the road test: ARIS

Signature: 

This Inspection Report was submitted to CVSE on 2022-Dec-06 10:05 PM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MP at the Commercial Vehicle Safety Enforcement

CVSE0013

12/6/2022 10:05:50 PM



Body Integrity Inspection Report

To be completed by the Designated Inspection Facility's Authorized Vehicle Inspector

Designated Inspection Facility Information

Designated Inspection Facility Number

5 5 8 3 8

Authorized Inspector Number

203635

DIF Facility Name ABBOTSFORD TUNE UP

Inspector Name

Andrus

Inspection Start Date

05 / 19 / 2022

Inspection Completion Date

06 / 19 / 2022

Inspector Signature

[Signature]

VEHICLE OWNER

Name

Ami Entapose

NAME OF REBUILDER (if other than owner)

Name AMC AUTO

Address

333 Tweed Ave

Address

11435 132A STREET

City

New West BC V3M4H5

SURREY

Prov BC

PC V3R7S2

Tel #

604 767 1933

Tel #

7783171840

Vehicle Information

TYPE OF VEHICLE:



Passenger Car



MPV



Truck



Motorhome



Taxi



Bus

Licence Plate N/A

Odometer

48670

Year

2021

Make

Kia

Model

Soul

Registration Number

13802071

VIN/Serial #

KM0733AKXK7753929

I am satisfied that this rebuilt motor vehicle is the same as the one described in the record of rebuilding.

Yes

No

Requirements of Rebuilding		Components			R	C	VIM Reference Section	Components			R	C	VIM Reference Section
Photographs prior to rebuilding clearly showing vehicle damage	<input checked="" type="checkbox"/> Yes	STRUT				8-4	REAR STRUT TOWER					8-4 (b)	
		- Left			- Left								
Structural Integrity Declaration Report	<input checked="" type="checkbox"/> Yes	HINGE (A) PILLAR				8-19	BUMPERS (Front/Rear)					8-5	
		- Left			- Right								
4 Wheel Alignment Printout	<input checked="" type="checkbox"/> Yes	CENTRE (B) PILLAR				8-19	CROSSMEMBER					8-3 (c)	
		- Left			- Right								
Welded and structural components that require protection have been protected as required by OEM or I-CAR standard.	<input checked="" type="checkbox"/> Yes	LOCK (C) PILLAR				8-19	HOOD					8-1	
		- Left			- Right								
Vehicle meets symmetric and asymmetric specifications as indicated on the Structural Integrity Declaration Report.	<input checked="" type="checkbox"/> Yes	ROCKER PANEL				8-19	RAD SUPPORT					8-2	
		- Left			- Right								
		BULKHEAD (cowl)				8-19	FRAME					8-3	
		DOORS					QUARTER PANELS						8-6
		DOORS				8-19	FLOOR PAN					8-2 (c)	
		ROCKER PANEL					QUARTER PANELS						8-4 (a)
		- Left				- Left					8-4 (a)		
		- Right				- Right							

Front bumper, hood, fender, headlight

"R" marked when item rejected
"C" marked when item corrected

I certify that this rebuilt vehicle meets all Structural Integrity requirements as defined in the Motor Vehicle Act Regulations and the BC Vehicle Inspection Manual.

Authorized Inspector Name (print)

Andrus

Signature

[Signature]

DYNAMIC AUTO CENTRE LTD.

UNIT #105 - 8918 HOLT RD
SURREY, BC

Phone Number: 604-501-9700
Tax Number: 604-501-9704

Customer: inline	Date: 12/6/2022 3:27:53 PM
Vehicle: VEN	kmvj53au4m7753929
License No:	Technician: inline
Odometer: 48679	Order No.:

VEHICLE ALIGNMENT REPORT

KIA, 2020, SOUL (SK3) 2.0MPi

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	1.9°	1.9°	1.5°	1.9°
		Right	1.8°	2.8°	4.8°	4.3°
	Camber	Left	0.8°	-1.0°	0.3°	-0.6°
		Right	-0.3°	-1.0°	0.0°	-0.3°
	Toe	Left	-0.60°	-0.05°	0.15°	-0.05°
		Right	0.50°	-0.05°	0.15°	0.00°
Total		-1.00°	-0.10°	0.30°	-0.00°	
Rear	Camber	Left	-1.7°	-1.7°	-0.7°	-1.7°
		Right	-1.1°	-1.7°	-0.7°	-1.1°
	Toe	Left	0.30°	0.30°	0.30°	0.30°
		Right	0.25°	0.00°	0.30°	0.25°
	Total		0.25°	0.00°	0.60°	0.20°
	Thrust Angle		0.1°	-----	-----	0.1°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
Steering Axis	Left		13.8°	13.3°	14.3°	13.8°
	Right		13.7°	13.3°	14.3°	13.7°
Steered Angle	Left		13.2°	-----	-----	13.2°
	Right		13.2°	-----	-----	13.2°
Toe Out On Turns	Left		-----	0.0°	0.0°	-----
	Right		-----	0.0°	0.0°	-----
Maximum Turns	Left		-----	37.0°	39.0°	-----
	Right		-----	37.0°	39.0°	-----
Steer Curve Change	Left		-----	-----	-----	-----
	Right		-----	-----	-----	-----
Dive/Rebound	Front		-0.1°	-----	-----	0.0°
	Rear		0.0°	-----	-----	0.0°
Track Width Diff.			-0.1°	-----	-----	-0.1°
Wheel base Diff.			0.1°	-----	-----	0.0°
Front Wheel Height	Left		-----	15.2°	16.0°	-----
	Right		-----	15.2°	16.0°	-----
Rear Wheel Height	Left		-----	15.3°	16.1°	-----
	Right		-----	15.3°	16.1°	-----
Frame Angle			-----	-----	-----	-----



BRITISH COLUMBIA

Ministry of Transportation and Infrastructure

Designated Inspection Facility

(DIF must issue this form for completion by an autobody technician)

Structural Integrity Declaration Report

Commercial Vehicle Safety and Enforcement Branch

Print Form

PASS All requirements met

FAIL Requirements NOT met

Designated Inspection Facility Information

Designated Inspection Facility Number: 55838

Facility Name: ABBOTSFORD TUNE UP

Authorized Inspector Number: 203635

Inspector Name: Aris Yusof

Inspector Signature: [Signature]

Date: 06/12/2022 Decal No.: FW42718

Vehicle Information

Owner: Aris Enterprise

Registration # 13802071 Plate # N/A

Address: 333 Taylor Avenue

VIN # KNDB33AULM7753929

City: NW West Prov BC PC 13000

Make: Kia Model: Soul Year: 2013

Structural Integrity Declaration Report

Repair Standard and Vehicles Dimensions
1. I confirm that the repair / rebuild process for this vehicle has met or exceeded the rebuilding standards specified by the Inter-Industry Conference On Auto Collision Repair (I-CAR) and / or the Original Equipment Manufacturer (OEM), that the unitized vehicle body repair, including engine cradle, conforms to the OEM dimension standards and that a full-framed vehicle complies with the OEM, I-CAR repair standard.

Occupant Protection and Vehicle Components
2. I confirm that the assembly of body components have been performed in a manner that provides occupant protection that is equal to or exceeding OEM or I-CAR standards.
3. I confirm that the repairable structural components of the vehicle body have been assembled and repaired in accordance with methods, procedures and standards that will return the components to its original standard, quality and properties in accordance with the OEM, I-CAR standards.
4. I confirm that the assembly joints of the vehicle body are located in places and repaired in accordance with the OEM, I-CAR procedures and standards.

Wheel Alignment
5. I confirm that a four-wheel alignment has been performed and that steering angles and wheel tolerances are within the OEM, requirements for this vehicle. A four-wheel alignment computer printout has been included as part of this declaration.
I certify that this vehicle has been repaired in accordance with OEM/I-CAR standards as noted in items 1 - 5 above.

Wheel alignment (all 4 wheels- attach printout) Alignment performed (facility name and address if other than above): NAME: Dynamic Auto ADDRESS:

Table with wheel alignment measurements: Front Left, Front Right, Rear Left, Rear Right. Columns include Camber, Caster, Toe, SAI, Included Angle, Turning Angle. Values: Front Left (-0.6, 4.3, -2.05), Front Right (-0.3, 4.4, 0.00), Rear Left (-1.1), Rear Right (-1.1, 0.25).

Technician Name: ARIS YUSOF
Autobody Tech Trade Qualification #: 0014-AB-19
Autobody Tech Trade Jurisdiction: BC
Technician Signature: [Signature]

ALIGNMENT: [X] PASS [] FAIL
Date Rebuilt Completed: 06/12/2022
Rebuilder Name: Aris Auto
Rebuilder Address: 19616 729 Avenue

* The ORIGINAL copy of this form must be forwarded to the designated inspection facility indicated above, and MUST be retained by the facility.
* This form must be the authentic original version signed by the autobody technician. Any photocopied, modified, altered, or changed form is unacceptable and must be rejected.
* A photocopy must accompany the customer's copy of the Vehicle Inspection Report (CVSE0013).