



Private Vehicle Inspection Report

Decal Number: FW22101
 Decal Expiry Date: 2023-Dec-31
 Inspection Number: 20354472

Inspection Result: **PASS**

Facility: SURREY INSPECTION & REPAIR / S4168
 Inspector: Sandhu, Parmvir Singh / 108201
 Work Order Number:

Inspection Type: Complete
 Inspection Class: Class 1 - Light Vehicle with LGVW 5500 kg or less
 Inspection Reason: Salvage Vehicle

Inspection Start Date/Time: 2022-Dec-13 07:00 PM
 Inspection Complete Date/Time: 2022-Dec-17 12:00 PM
 Collision Repair Facility: ANDI'S AUTO BODY
 Collision Repair Facility Phone: (604) 430-0570
 Collision Repair Technician: MAKHAN SANDHU

Vehicle Jurisdiction: British Columbia
 Registration Number: 11427792
 VIN: 2C4RDGBG3FR666105
 Plate Number:
 Licenced GVW (kg): 0
 Vehicle Year: 2015
 Make: DODGE

Brake Type: Hydraulic
 Fuel Type: Gasoline
 Odometer: 82739 KM
 Hub Odometer:
 Body Style: 4 Door Stationwagon
 Model: GCRVN

Owner/Lessee Name: PACIFIC, PACIFIC AUTOGEM AUTO SALES LTD
 Address: #1-11435 132AST
 City: Surrey
 Province/State: British Columbia
 Postal Code/ZIP: V3R7S2
 Country: Canada

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Passed	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Not Applicable	

Tire Tread Depth (mm)

Axles (front)	Outer Left	Inner left	Inner Right	Outer Right	Steering Axle?
1	8			8	✓
2	8			8	

Comment:

Brake Lining/Pad Measurement (mm)

Axles (front)	Lining/Pad	Left	Right
1	Pad	6	6
2	Pad	10	10

Comment:

Rotor Thickness or Drum Inside Diameter Measurement (mm)

Axles (front)	Rotor/Drum	Left	Right
1	Rotor	28.19	28.15
2	Rotor	12.30	12.18

Comment:

Inspection Comments:

Has this Vehicle been road tested? Yes When? Before and After Inspection

Name of the person who did the road test: PARMVIR

Inspector Name: Sandhu, Parmvir Singh

Signature: 

This Inspection Report was submitted to CVSE on 2022-Dec-17 01:56 PM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCMP at the Commercial Vehicle Safety Enforcement

CVSE0013

12/17/2022 1:56:22 PM

THIS INSPECTION SHOULD NOT BE USED AS A CRITERION FOR PURCHASE, A BUYER SHOULD GET AN INDEPENDENT MECHANICAL APPRAISAL BEFORE PURCHASE



BRITISH COLUMBIA

Ministry of Transportation and Infrastructure

Designated Inspection Facility

(DIF must issue this form for completion by an autobody technician)

Structural Integrity Declaration Report

Commercial Vehicle Safety and Enforcement Branch

Print Form

PASS All requirements met

FAIL Requirements NOT met

Designated Inspection Facility Information

Designated Inspection Facility Number: 54168

Facility Name: SURREY INSPECTION & REPAIR CTR LTD

Authorized Inspector Number: 108201

Inspector Name: PAMVIR SAN

Inspector Signature: [Signature]

Date: 17 Dec 2022 Decal No.: FW22101

Vehicle Information

Owner PACIFIC AUTO GEM AUTOSALES LTD

Registration # 11427792

Plate #

Address 1 -11435 -132A ST

VIN # 2C4RDGBG3FR666105

City SURREY

Prov BC

PC V3R 7S2

Make DODGE

Model GRAND

Year 2015

Structural Integrity Declaration Report

Repair Standard and Vehicles Dimensions

1. I confirm that the repair / rebuild process for this vehicle has met or exceeded the rebuilding standards specified by the Inter-Industry Conference On Auto Collision Repair (I-CAR) and / or the Original Equipment Manufacturer (OEM), that the unitized vehicle body repair, including engine cradle, conforms to the OEM dimension standards and that a full-framed vehicle complies with the OEM, I-CAR repair standard.

Wheel alignment (all 4 wheels- attach printout) Alignment performed (facility name and address if other than above): NAME: Surrey Inspection & Repair ADDRESS: 10944-124 St Surrey

Occupant Protection and Vehicle Components

2. I confirm that the assembly of body components have been performed in a manner that provides occupant protection that is equal to or exceeding OEM or I-CAR standards.

3. I confirm that the repairable structural components of the vehicle body have been assembled and repaired in accordance with methods, procedures and standards that will return the components to its original standard, quality and properties in accordance with the OEM, I-CAR standards.

4. I confirm that the assembly joints of the vehicle body are located in places and repaired in accordance with the OEM, I-CAR procedures and standards.

Table with alignment data: Front Left, Front Right, Rear Left, Rear Right. Includes Camber, Caster, Toe, SAI, Included Angle, Turning Angle.

Wheel Alignment

5. I confirm that a four-wheel alignment has been performed and that steering angles and wheel tolerances are within the OEM, requirements for this vehicle. A four-wheel alignment computer printout has been included as part of this declaration.

I certify that this vehicle has been repaired in accordance with OEM/I-CAR standards as noted in items 1 - 5 above.

Technician Name: MAKHAN S please print
Autobody Tech Trade Qualification #: 0357 - AB - 97
Autobody Tech Trade Jurisdiction: BRITISH COLUMBIA
Technician Signature: [Signature]

Summary table for alignment: Front Left, Front Right, Rear Left, Rear Right. Includes checkboxes for PASS and FAIL.

Date Rebuilt Completed: 20 Dec 2022
Rebuilder Name: ANDIS AUTO BODY & REPAIRS
Rebuilder Address: 6971 PALM AVE BURNABY BC V5J 4M1

* The ORIGINAL copy of this form must be forwarded to the designated inspection facility indicated above, and MUST be retained by the facility.
* This form must be the authentic original version signed by the autobody technician. Any photocopied, modified, altered, or changed form is unacceptable and must be rejected.
* A photocopy must accompany the customer's copy of the Vehicle Inspection Report (CVSE0013).

SURREY INSPECTION & REPAIR

Customer: MARK

License No:

Order No.:

Date: 12/17/2022 10:22

Company:

Odometer: 82739KM


VIN:

Technician: DAWINDER

2C4RDGBG3FR666105

SINGH

Vehicle DODGE 2015 GRAND CARAVAN RM 16" & 17" Wheels



CASTER is the tilt of the axis that the wheel steers around. It affects how the vehicle tracks as you drive down the road and can affect handling.

CAMBER is the angle of the tire in relation to the road surface. It affects tire wear, and handling when turning.

TOE is a measurement of how much the wheel is turned in or out from a straight-ahead position. It affects tire wear, handling and can make your steering wheel crooked.

Your vehicle has been aligned using a precision **JohnBean** wheel aligner.



Body Integrity Inspection Report

To be completed by the Designated Inspection Facility's Authorized Vehicle Inspector

Designated Inspection Facility Information

Designated Inspection Facility Number S 4 1 6 8

Authorized Inspector Number 1 0 8 2 0 1

DIF Facility Name SURREY INSPECTION & REPAIR CTR LTD

Inspector Name PARMVIR S

Inspection Start Date 1 3 1 2 2 0 2 2
Inspection Completion Date 1 7 1 2 2 0 2 2

Inspector Signature [Signature]

VEHICLE OWNER

NAME OF REBUILDER (if other than owner)

Name PACIFIC AUTOGEM AUTOSALES LTD
Address 1-11435 132 A ST
City SURREY Prov BC PC V3R7S2
Tel # +1 (604) 782-4852

Name ANDI'S AUTOBODY & REPAIR
Address 6771 PALM AVE
City BURNABY Prov BC PC V5J4M1
Tel # +1 (604) 430-0570

Vehicle Information

TYPE OF VEHICLE: Passenger Car MPV Truck Motorhome Taxi Bus

Licence Plate Odometer 82739 Year 2015 Make DODGE Model CARAVAN

Registration Number 11427792 VIN/Serial # 2 C 4 R D G B G 3 F R 6 6 6 1 0 5

I am satisfied that this rebuilt motor vehicle is the same as the one described in the record of rebuilding. Yes No

Table with 9 columns: Requirements of Rebuilding, Components, R, C, VIM Reference Section, Components, R, C, VIM Reference Section. Rows include Strut, Hinge (A) Pillar, Centre (B) Pillar, Lock (C) Pillar, Rocker Panel, Rear Strut Tower, Bumpers, Crossmember, Hood, Rad Support, Body, Frame, Bulkhead, Doors, Quarter Panels, Floor Pan.

"R" marked when item rejected

"C" marked when item corrected

I certify that this rebuilt vehicle meets all Structural Integrity requirements as defined in the Motor Vehicle Act Regulations and the BC Vehicle Inspection Manual.

Authorized Inspector Name (print) PARMVIR S SANDHU

Signature [Signature]