



Private Vehicle Inspection Report

Decal Number: FX64901
Decal Expiry Date: 2024-Apr-30
Inspection Number: 20467829

Inspection Result:
PASS

FACILITY: ABBOTSFORD TUNE-UP CENTER / S5838	INSP. TYPE: Complete	INSP. START: 2023-Mar-25 03:45 PM PDT
INSPECTOR: MOHAMMAD YUSOF, MOHAMMAD ARIS / 203635	INSP. CLASS: Class 1 - Light Vehicle with LGVW 5500 kg or less	INSP. COMPLETE: 2023-Apr-06 06:00 PM PDT
WORK ORDER #: 16349	INSP. REASON: Salvage Vehicle	COLL. REP. FACILITY: AMC AUTO
		COLL. REP. PHONE: (778) 317-1840
		COLL. REP. TECHNICIAN: ARIS YUSOF


VEHICLE JUR: British Columbia	REGI: 13624079	VIN: JM1BPAK71M1336535
PLATE #:	UNIT/FLEET#:	OWNER/LESSEE NAME: PACIFIC AUTO GEM, PACIFIC
LICENCED GWV(kg): 0	BODY STYLE: Hatchback	ADDRESS: #1 11435 132A STREET
VEHICLE YEAR: 2021	ODOMETER: 35368 KM	Surrey, British Columbia
MAKE: MAZDA	HUB ODOMETER:	V3T2T3, Canada
MODEL: MZDA3	BRAKE TYPE: Hydraulic	
	FUEL TYPE: Gasoline	

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3H - Hydraulic Brakes	Passed
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) REPLACED TIRES
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Not Applicable

Tire Tread Depth (mm)						Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	7			7	✓	Pad	8	8	Rotor	25.90	25.83
2	7			7		Pad	8	8	Rotor	9.66	9.62
Comment:						Comment:			Comment:		

Inspection Comments:

Has this Vehicle been road tested? Yes **Road Test Date:** After Inspection **Road Tester:** ARIS

Inspector: MOHAMMAD YUSOF, MOHAMMAD ARIS **Signature:** 

This Inspection Report was submitted to CVSE on 2023-Apr-07 10:51 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE013
4/7/2023 10:51:02 AMPDT

Structural Integrity Declaration Report

Commercial Vehicle Safety and Enforcement Branch

PASS All requirements met

FAIL Requirements NOT met

Designated Inspection Facility Information

Designated Inspection Facility Number: **5 5 8 3 8**

Facility Name: **ABBOTSFORD TUNE UP**

Authorized Inspector Number: **2 0 3 6 3 5**

Inspector Name: *Arif Yusof*

Inspector Signature: *[Signature]*

Date: *06/04/2023* Fiscal No.: *EX64901*

Vehicle Information

Owner: *Pacific Autodyem*

Registration # *13624079* Plate # *N/A*

Address: *#1-11435 132A ST.*

VIN # *JMIBPAK71M1336535*

City: *Surrey* Prov: *BC* PC: *132A*

Make: *MAZDA* Model: *3* Year: *2021*

Structural Integrity Declaration Report

Repair Standard and Vehicles Dimensions

1. I confirm that the repair / rebuild process for this vehicle has met or exceeded the rebuilding standards specified by the Inter-Industry Conference On Auto Collision Repair (I-CAR) and / or the Original Equipment Manufacturer (OEM), that the unitized vehicle body repair, including engine cradle, conforms to the OEM dimension standards and that a full-framed vehicle complies with the OEM, I-CAR repair standard.

Wheel alignment (all 4 wheels- attach printout) Alignment performed (facility name and address if other than above):
NAME: *Dynamic Auto*

ADDRESS: _____

Occupant Protection and Vehicle Components

2. I confirm that the assembly of body components have been performed in a manner that provides occupant protection that is equal to or exceeding OEM or I-CAR standards.

Please indicate numbers and measurements on diagram below:

From inside vehicle:	Front Left	Front Right
Camber	<i>-0.3</i>	Camber <i>0.0</i>
Caster	<i>5.3</i>	Caster <i>4.2</i>
Toe	<i>0.10</i>	Toe <i>0.05</i>
SAI		SAI
Included Angle		Included Angle
Turning Angle		Turning Angle

3. I confirm that the repairable structural components of the vehicle body have been assembled and repaired in accordance with methods, procedures and standards that will return the components to its original standard, quality and properties in accordance with the OEM, I-CAR standards.

4. I confirm that the assembly joints of the vehicle body are located in places and repaired in accordance with the OEM, I-CAR procedures and standards.

Rear Left **Rear Right**

Camber	<i>-1.4</i>	Camber <i>-1.4</i>
Caster		Caster
Toe	<i>0.10</i>	Toe <i>0.15</i>
SAI		SAI

Wheel Alignment

5. I confirm that a four-wheel alignment has been performed and that steering angles and wheel tolerances are within the OEM, requirements for this vehicle. A four-wheel alignment computer printout has been included as part of this declaration.

I certify that this vehicle has been repaired in accordance with OEM/I-CAR standards as noted in items 1 - 5 above.

ALIGNMENT PASS FAIL

Technician Name (please print): **ARIS YUSOF**

Date Rebuilt Completed: *06/04/2023*

Autobody Tech Trade Qualification #: **0014-AB-19**

Rebuilder Name (if different from technician): *Auto Auto*

Autobody Tech Trade Jurisdiction: **BC**

Technician Signature: *[Signature]*

Rebuilder Address: *#3-11435 132A ST.*

* The ORIGINAL copy of this form must be forwarded to the designated inspection facility indicated above, and MUST be retained by the facility.
* This form must be the authentic original version signed by the autobody technician. Any photocopied, modified, altered, or changed form is unacceptable and must be rejected.
* A photocopy must accompany the customer's copy of the Vehicle Inspection Report (CVSE0013).

DYNAMIC AUTO CENTRE LTD.

UNIT #105 - 8918 HOLT RD
SURREY, BC

Phone Number: 604-501-9700
Fax Number: 604-501-9701

Customer: AINI INTERPRISE	Date: 3/25/2023 3:07 PM
Company:	VIN JMIBPAK71M1336535
License No:	Technician: SAM
Odometer: 35368	Order No.:

VEHICLE ALIGNMENT REPORT

MAZDA, 2021, 3 All Models

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	5.5°	3.5°	5.5°	5.3°
		Right	4.9°	3.5°	5.5°	4.2°
	Camber	Left	-0.5°	-1.2°	0.8°	-0.3°
		Right	0.0°	-1.2°	0.8°	0.0°
	Toe	Left	-0.10°	-0.15°	0.20°	0.10°
		Right	-0.15°	-0.15°	0.20°	0.05°
Total		-0.25°	-0.30°	0.45°	0.15°	
Rear	Camber	Left	-1.4°	-2.5°	-0.5°	-1.4°
		Right	-1.3°	-2.5°	-0.5°	-1.4°
	Toe	Left	0.10°	-0.05°	0.40°	0.10°
		Right	0.15°	-0.05°	0.40°	0.15°
		Total	0.25°	-0.10°	0.85°	0.25°
	Thrust Angle		0.0°	-0.8°	0.8°	0.0°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left	8.2°	13.4°	13.4°	8.2°	
	Right	13.5°	13.4°	13.4°	13.5°	
Included Angle	Left	7.9°	---	---	7.9°	
	Right	13.5°	---	---	13.5°	
Toe Out On Turns	Left	---	---	---	---	
	Right	---	---	---	---	
Maximum Turns	Left	---	36.9°	42.9°	---	
	Right	---	36.9°	42.9°	---	
Toe Curve Change	Left	---	---	---	---	
	Right	---	---	---	---	
Setback	Front	0.3"	---	---	0.3"	
	Rear	0.1"	---	---	0.2"	
Track Width Diff.		-0.1"	---	---	-0.1"	
Wheel Base Diff.		0.1"	---	---	0.0"	
Front Ride Height	Left	---	---	---	---	
	Right	---	---	---	---	
Rear Ride Height	Left	---	---	---	---	
	Right	---	---	---	---	
Frame Angle		---	---	---	---	



Body Integrity Inspection Report

To be completed by the Designated Inspection Facility's Authorized Vehicle Inspector

Designated Inspection Facility Information

Designated Inspection Facility Number

5 5 8 3 8

Authorized Inspector Number

2 0 3 6 3 5

DIF Facility Name ABBOTSFORD TUNE UP CENTRE LTD.

Inspector Name

Aris Vlesop

Inspection Start Date

26 03 2023

Inspection Completion Date

06 09 2023

Inspector Signature

[Signature]

VEHICLE OWNER

Name

Pacific Auto

NAME OF REBUILDER (if other than owner)

Name

AUC Auto

Address

#1-11435 132A ST.

Address

#3-11435 132A ST.

City

Surrey Prov BC PC V3R1S2 City

City

Surrey Prov BC PC V3R1S2

Tel #

6047654905

Tel #

778 871800

Vehicle Information

TYPE OF VEHICLE:

- Passenger Car, MPV, Truck, Motorhome, Taxi, Bus

Licence Plate N/Ap

Odometer

35368

Year

2021

Make

Nissan

Model

3

Registration Number

18624079

VIN/Serial #

JM1BPAA71M13261535

I am satisfied that this rebuilt motor vehicle is the same as the one described in the record of rebuilding.

Yes No

Table with columns: Requirements of Rebuilding, Components, R, C, VIM Reference Section, Components, R, C, VIM Reference Section. Rows include: Photographs prior to rebuilding, Structural Integrity Declaration Report, 4 Wheel Alignment Printout, Welded and structural components that require protection, Vehicle meets symmetric and asymmetric specifications.

Front bumper, hood, suspension, fender doors, rad support, cooling, Air bag

"R" marked when item rejected "C" marked when item corrected

I certify that this rebuilt vehicle meets all Structural Integrity requirements as defined in the Motor Vehicle Act Regulations and the BC Vehicle Inspection Manual.

Authorized Inspector Name (print)

Aris Vlesop

Signature

[Signature]