



Private Vehicle Inspection Report

Decal Number: FY13963
Decal Expiry Date: 2024-Jun-30
Inspection Number: 20536891


Inspection Result:
PASS

FACILITY: ABBOTSFORD TUNE-UP CENTER / S5838	INSP. TYPE: Complete	INSP. START: 2023-Jun-03 11:30 AM PDT
INSPECTOR: MOHAMMAD YUSOF, MOHAMMAD ARIS / 203635	INSP. CLASS: Class 1 - Light Vehicle with LGVW 5500 kg or less	INSP. COMPLETE: 2023-Jun-03 01:00 PM PDT
WORK ORDER #: 16450	INSP. REASON: Salvage Vehicle	COLL. REP. FACILITY: AMC AUTO
		COLL. REP. PHONE: (778) 317-1840
		COLL. REP. TECHNICIAN: ARIS YUSOF

VEHICLE JUR: British Columbia	REGI: 03478002	VIN: 3VWPPW21C18M523244
PLATE #:	UNIT/FLEET#:	OWNER/LESSEE NAME: PACIFIC AUTO GEM, PACIFIC
LICENCED GWV(kg): 0	BODY STYLE: Hatchback	ADDRESS: #1 11435 132A STREET
VEHICLE YEAR: 2008	ODOMETER: 93910 KM	Surrey, British Columbia
MAKE: VOLKSWAGEN	HUB ODOMETER:	V3T2T3, Canada
MODEL: BEETL	BRAKE TYPE: Hydraulic	
	FUEL TYPE: Gasoline	

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) REPLACED CAM SHAFT SENSOR
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3H - Hydraulic Brakes	Passed
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Not Applicable

Tire Tread Depth (mm)					Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axes	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	12			12	✓	Pad	9	9	Rotor	25.51	25.47
2	11			11		Pad	10	10	Rotor	9.69	9.57
Comment:					Comment:			Comment:			

Inspection Comments:
 Has this Vehicle been road tested? Yes **Road Test Date:** After Inspection
Inspector: MOHAMMAD YUSOF, MOHAMMAD ARIS **Signature:**  **Road Tester:** ARIS

This Inspection Report was submitted to CVSE on 2023-Jun-03 01:13 PM PDT
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement
 CVSE0013
 6/3/2023 1:13:46 PM PDT



Body Integrity Inspection Report

To be completed by the Designated Inspection Facility's Authorized Vehicle Inspector

Designated Inspection Facility Information

Designated Inspection Facility Number

5 5 8 3 8

Authorized Inspector Number

2 0 3 6 3 5

DIF Facility Name ABBOTSFORD TUNE UP

Inspector Name ARIS YUSOF

Inspection Start Date 03/02/2023, Inspection Completion Date 03/02/2023

Inspector Signature

[Signature]

VEHICLE OWNER

Name Pacific Auto, Address #1-11455 132A St, City Surrey BC, Tel # 604-765-4245

NAME OF REBUILDER (if other than owner)

Name PML Auto, Address #3-11455 132A St, City Surrey BC, Tel # 778-778-1100

Vehicle Information

TYPE OF VEHICLE:

- Passenger Car, MPV, Truck, Motorhome, Taxi, Bus

Licence Plate N/A

Odometer 93910 Year 2008

Make VOLKS

Model Beetle

Registration Number

03C78002

VIN/Serial # 3UWPN21C1814523244

I am satisfied that this rebuilt motor vehicle is the same as the one described in the record of rebuilding.

Yes No

Table with columns: Requirements of Rebuilding, Components, R, C, VIM Reference Section, Components, R, C, VIM Reference Section. Rows include STRUT, HINGE (A) PILLAR, CENTRE (B) PILLAR, LOCK (C) PILLAR, ROCKER PANEL, REAR STRUT TOWER, BUMPERS, CROSSMEMBER, HOOD, RAD SUPPORT, BODY, FRAME, BULKHEAD, DOORS, QUARTER PANELS, FLOOR PAN.

Front bumpers, Hood, Headlamps, Rad supports, cooling fan

I certify that this rebuilt vehicle meets all Structural Integrity requirements as defined in the Motor Vehicle Act Regulations and the BC Vehicle Inspection Manual.

Authorized Inspector Name (print) ARIS YUSOF

Signature

[Signature]

DYNAMIC AUTO CENTRE LTD.

UNIT #105 - 8918 HOLT RD
SURREY, BC

Phone Number: 604-501-9700
Fax Number: 604-501-9701

Customer: AINI ENTERPRISE	Date: 5/23/2023 3:28 PM
Company:	VIN: 3VWPPW21C18M523244
License No:	Technician: ERIC
Odometer: 93910	Order No.:

VEHICLE ALIGNMENT REPORT

VOLKSWAGEN, 2008, BEETLE [1C/9C] (1GB) Hatchback, Rough Road Chassis

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	7.5°	6.8°	7.8°	7.5°
		Right	7.3°	6.8°	7.8°	7.3°
	Camber	Left	-0.3°	-0.8°	0.2°	-0.8°
		Right	-0.6°	-0.8°	0.2°	-0.8°
	Toe	Left	-0.05°	-0.10°	0.10°	0.05°
		Right	0.10°	-0.10°	0.10°	0.05°
Total		0.05°	-0.15°	0.15°	0.10°	
Rear	Camber	Left	-1.5°	-1.6°	-1.3°	-1.4°
		Right	-1.4°	-1.6°	-1.3°	-1.4°
	Toe	Left	0.10°	0.05°	0.15°	0.10°
		Right	0.20°	0.05°	0.15°	0.15°
		Total	0.30°	0.05°	0.35°	0.25°
	Thrust Angle			0.1°	-0.2°	0.2°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		14.9°	---	---	14.9°
	Right		15.5°	---	---	15.5°
Included Angle	Left		14.1°	---	---	14.1°
	Right		14.9°	---	---	14.7°
Toe Out On Turns	Left		1.6°	1.1°	1.8°	1.6°
	Right		2.1°	1.1°	1.8°	2.1°
Maximum Turns	Left		---	---	---	---
	Right		---	---	---	---



BRITISH COLUMBIA

Ministry of Transportation and Infrastructure

Designated Inspection Facility

(DIF must issue this form for completion by an autobody technician)

Structural Integrity Declaration Report

Commercial Vehicle Safety and Enforcement Branch

Print Form

PASS All requirements met

FAIL Requirements NOT met

Designated Inspection Facility Information

Designated Inspection Facility Number: 5 5 8 3 8

Facility Name: ABBOTSFORD TUNE UP

Authorized Inspector Number: 2 0 3 6 3 5

Inspector Name: ARIS YUSOF

Inspector Signature: [Signature]

Date: 03/06/2023 Decal No.: FY1963

Vehicle Information

Owner: Mr. Rukhpre

Registration #: 03478002 Plate #: N/A

Address: 383 12th St

VIN #: 3UWPN21C18M523244

City: New West Prov: BC PC 13MUTS

Make: Volvo Model: R200 Year: 2008

Structural Integrity Declaration Report

Repair Standard and Vehicles Dimensions

1. I confirm that the repair / rebuild process for this vehicle has met or exceeded the rebuilding standards specified by the Inter-Industry Conference On Auto Collision Repair (I-CAR) and / or the Original Equipment Manufacturer (OEM), that the unitized vehicle body repair, including engine cradle, conforms to the OEM dimension standards and that a full-framed vehicle complies with the OEM, I-CAR repair standard.

Wheel alignment (all 4 wheels- attach printout) Alignment performed (facility name and address if other than above):

NAME: Dignem Auto

ADDRESS:

Occupant Protection and Vehicle Components

2. I confirm that the assembly of body components have been performed in a manner that provides occupant protection that is equal to or exceeding OEM or I-CAR standards.

3. I confirm that the repairable structural components of the vehicle body have been assembled and repaired in accordance with methods, procedures and standards that will return the components to its original standard, quality and properties in accordance with the OEM, I-CAR standards.

4. I confirm that the assembly joints of the vehicle body are located in places and repaired in accordance with the OEM, I-CAR procedures and standards.

Please indicate numbers and measurements on diagram below:

From inside vehicle: Front Left Front Right

	Front Left	Front Right
-0.7	Camber	Camber -0.7
7.5	Caster	Caster 7.3
0.05	Toe	Toe 0.05
	SAI	SAI
	Included Angle	Included Angle
	Turning Angle	Turning Angle

Wheel Alignment

5. I confirm that a four-wheel alignment has been performed and that steering angles and wheel tolerances are within the OEM, requirements for this vehicle. A four-wheel alignment computer printout has been included as part of this declaration.

Rear Left Rear Right

-1.4	Camber	Camber -1.4
	Caster	Caster
0.10	Toe	Toe 0.15
	SAI	SAI

I certify that this vehicle has been repaired in accordance with OEM/I-CAR standards as noted in items 1 - 5 above.

Technician Name please print ARIS YUSOF

ALIGNMENT PASS FAIL

Autobody Tech Trade Qualification # 0014-AB-19

Date Rebuilt Completed 03/06/2023

Autobody Tech Trade Jurisdiction BC

Rebuilder Name (if different from technician) SCORCE

Technician Signature [Signature]

Rebuilder Address

* The ORIGINAL copy of this form must be forwarded to the designated inspection facility indicated above, and MUST be retained by the facility. * This form must be the authentic original version signed by the autobody technician. Any photocopied, modified, altered, or changed form is unacceptable and must be rejected. * A photocopy must accompany the customer's copy of the Vehicle Inspection Report (CVSE0013).