



2017 VOLKSWAGEN GOLF S

Hatchback | 4 Cylinders | Gas 3VW117AU5HM042603 Country of Assembly: Mexico Last Reported Odometer: 82,006 KM



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of June 13, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



(i)

INCIDENT DATE	DETAILS	AMOUNT
1 2017 May 4	Ontario, Canada	
	Police Reported Accident: Accident reported: minor damage	
	with another motor vehicle	
	Damage to front	
	Damage to right front	
) 2017 May 5	Ontario, Canada	
	Claim: Other Damage	\$2,248.00
) 2017 Dec 26	Ontario, Canada	
	Police Reported Accident: Accident reported: moderate damage	
	with another motor vehicle	
	Damage to left front	
	Claim: Collision	\$4,100.00
	Claim: Other Damage	\$4,600.00
) 2018 Apr 3	Ontario, Canada	
	Claim: Other Damage	\$917.00

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
() 2018 Apr 20	n/a	
	Damage Event: Damage reported: very minor damage	
	Damage to right rear	

Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

Service Records

DATE	ODOMETER	SOURCE	DETAILS	
2017 Feb 28		Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced	
2017 Aug 8	16,052 KM	Jiffy Lube Hamilton, Ontario, Canada	Vehicle serviced Oil and filter changed 	

	ODOMETER	SOURCE	DETAILS
2017 Aug 25	18,390 KM	Locke Street Tire & Automotive Hamilton, Ontario, Canada	Vehicle serviced Tire repaired
2019 Oct 31	82,006 KM	Locke Street Tire & Automotive Hamilton, Ontario, Canada	 Vehicle serviced Oil and filter changed Tire(s) replaced Tire(s) mounted

Open Recalls

Recall #: 42J5 | COIL SPRINGS Recall Date: 2019 Mar 28

Recall Description

The rear axle coil springs in affected vehicles may not have met factory specifications due to a defect in materials or because of problems in the spring production process. These issues can impact the long-term durability of the rear axle coil springs. Affected coil springs can break. A broken coil spring can damage a rear tire, become a hazard on the roadway and lead to a loss of vehicle control without warning, putting people at risk and possibly causing damage to other vehicles on the road.

Remedy

Replace the rear axle coil springs.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit Volkswagen's website.

Stolen Vehicle Check

This vehicle is not actively declared stolen.

Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Feb 28		Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2017 Mar 16		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal
2017 May 4		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: minor damage with another motor vehicle Damage to front Damage to right front
2017 May 5		Insurance Records Ontario, Canada		

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Jun 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Aug 8	16,052 KM	Jiffy Lube Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2017 Aug 25	18,390 KM	Locke Street Tire & Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2017 Dec 26		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: moderate damage with another motor vehicle Damage to left front
2017 Dec 26		Insurance Records Ontario, Canada		
2017 Dec 26		Insurance Records Ontario, Canada		
2018 Apr 3		Insurance Records Ontario, Canada		
2018 Apr 20			Damage Event	Damage reported: very minor damage Damage to right rear
2018 Jun 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Mar 28		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 42J5
2019 Oct 31	82,006 KM	Locke Street Tire & Automotive Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2020 Dec 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Nov 3		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada One Owner[™] Badge The CARFAX Canada One Owner[™] badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. Conditions of Use

© 2023 CARFAX Canada ULC. All rights reserved.

