




Vehicle History Report #: 47950611
Report Date: August 21, 2023 | 4:08 PM EDT
Report Status: Complete

2013 VOLKSWAGEN PASSAT S

Sedan | 5 Cylinders | Gas
1VWAH7A34DC011406
Country of Assembly: United States
Last Reported Odometer: 134,657 KM



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)




13 Service Records Found



No U.S. History Found



2 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.
Visit us at support.carfax.ca

This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of August 21, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2013 Apr 30	<p>Ontario, Canada</p> <p>Police Reported Accident: Accident reported Vehicle involved in a rear-end collision with another motor vehicle Damage to rear</p>	

Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2013 Mar 30	23,382 KM	Active Green & Ross Oakville, Ontario, Canada	<p>Vehicle serviced</p> <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2013 Jun 15	31,342 KM	Active Green & Ross Oakville, Ontario, Canada	<p>Vehicle serviced</p> <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2013 Aug 17	37,651 KM	Active Green & Ross Oakville, Ontario, Canada	<p>Vehicle serviced</p> <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2014 May 28	47,105 KM	Humberview Volkswagen Toronto, Ontario, Canada	<p>Vehicle serviced</p>
2016 Feb 8	62,225 KM	Humberview Volkswagen Toronto, Ontario, Canada	<p>Vehicle serviced</p> <ul style="list-style-type: none"> Stabilizer bar links replaced Drivability/performance checked
2016 Jun 14	65,795 KM	Humberview Volkswagen Toronto, Ontario, Canada	<p>Vehicle serviced</p> <ul style="list-style-type: none"> Steering gear replaced
2021 Jan 14	113,179 KM	401 Dixie Infiniti Mississauga, Ontario, Canada	<p>Vehicle serviced</p> <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2021 Aug 19		Service Facility	<p>Vehicle serviced</p> <ul style="list-style-type: none"> Inspection performed Alignment checked
2021 Sep 24		Krown St. Catharines St. Catharines, Ontario, Canada	<p>Vehicle serviced</p> <ul style="list-style-type: none"> Undercoating/rustproofing applied
2022 Aug 17	124,723 KM	Niagara Battery and Tire Welland, Ontario, Canada	<p>Vehicle serviced</p> <ul style="list-style-type: none"> Oil and filter changed
2022 Aug 29	124,724 KM	Niagara Battery and Tire Welland, Ontario, Canada	<p>Vehicle serviced</p>

1VWAH7A34DC011406

	ODOMETER	SOURCE	DETAILS
2022 Oct 27	127,075 KM	Niagara Battery and Tire Welland, Ontario, Canada	Vehicle serviced
2023 Jul 27	134,657 KM	Niagara Battery and Tire Welland, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed



Open Recalls

Recall #: 69Q9 | TAKATA SDI DRIVER INFLATOR Recall Date: 2018 Mar 15

Recall Description

The driver airbag may explode in a crash with airbag deployment. Sharp metal fragments can hit people and cause serious injury or death. Owners should schedule this recall repair immediately, even if an interim repair was recently done.

Remedy

Replace the driver frontal airbag inflator (final remedy repair).

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](#).

Recall #: 94L9 | HEADLAMP CAPS Recall Date: 2019 Jun 11

Recall Description

The headlights are not permitted to have a horizontal adjustment for vehicles certified according to regulatory requirements. The horizontal adjuster is blocked from further adjustment by means of a cap (after the initial adjustment is performed in the production process). Some vehicles did not have the required cap installed. Incorrectly adjusted headlights may result in reduced visibility (for the driver and other motorists) which could increase the risk of a crash.

Remedy

Inspect and, if necessary install missing headlight adjusting screw caps.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](#).



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2012 Aug 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2013 Mar 30	23,382 KM	Active Green & Ross Oakville, Ontario, Canada	Service Record	Vehicle serviced
2013 Apr 30		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> • Vehicle involved in a rear-end collision • with another motor vehicle • Damage to rear
2013 Jun 15	31,342 KM	Active Green & Ross Oakville, Ontario, Canada	Service Record	Vehicle serviced
2013 Jun 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2013 Aug 17	37,651 KM	Active Green & Ross Oakville, Ontario, Canada	Service Record	Vehicle serviced
2013 Oct 11	41,097 KM	Independent Source Oakville, Ontario, Canada	Odometer reading	
2014 May 28	47,105 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2015 Jun 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 Feb 8	62,225 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2016 Jun 14	65,795 KM	Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2017 Jun 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Mar 15		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 69Q9
2019 Jun 11		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 94L9
2020 Jun 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 Nov 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Jan 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2021 Jan 14	113,179 KM	401 Dixie Infiniti Mississauga, Ontario, Canada	Service Record	Vehicle serviced

1VWAH7A34DC011406

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Apr 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2021 Aug 19		Service Facility	Service Record	Vehicle serviced
2021 Sep 24		Krown St. Catharines St. Catharines, Ontario, Canada	Service Record	Vehicle serviced
2022 Aug 17	124,723 KM	Niagara Battery and Tire Welland, Ontario, Canada	Service Record	Vehicle serviced
2022 Aug 29	124,724 KM	Niagara Battery and Tire Welland, Ontario, Canada	Service Record	Vehicle serviced
2022 Oct 27	127,075 KM	Niagara Battery and Tire Welland, Ontario, Canada	Service Record	Vehicle serviced
2022 Nov 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2023 Jul 27	134,657 KM	Niagara Battery and Tire Welland, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© 2023 CARFAX Canada ULC. All rights reserved.

