

Vehicle History Report #: 49804084
Report Date: November 18, 2023 | 11:59 AM EST
Report Status: Complete

### 2013 CADILLAC SRX

Sport utility vehicle | 6 Cylinders | Gas 3GYFNAE30DS619534 Country of Assembly: Mexico Last Reported Odometer: 99,485 KM





Last Registered In: Ontario (Normal)



9 Service Records Found







Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of November 18, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# **Vehicle History Report**



INCIDENT DATE	DETAILS	AMOUNT
<b>1</b> 2015 Sep 11	Ontario, Canada	
	Police Reported Accident: Accident reported: minor damage	
	Vehicle involved in a rear-end collision	
	with another motor vehicle	
	Damage to rear	
	Claim: Unknown	\$5,045.00

## **Other Damage Records**

RECORD DATE	DETAILS	AMOUNT
① 2015 Sep 4	Ontario, Canada	
	Glass Record	\$586.00
<b>0</b> 2018 Apr 30	Ontario, Canada	
	Glass Record	\$85.00
<b>1</b> 2019 Apr 21	Ontario, Canada	
	Glass Record	\$118.00

# **Registration**

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



## Service Records

DATE	ODOMETER	SOURCE	DETAILS	
2016 Nov 2	52,086 KM	Lancaster Auto & Tire Discounter	Vehicle serviced	
		Burlington, Ontario, Canada	Four tires mounted	
		5 , ,	<ul> <li>Tire condition and pressure checked</li> </ul>	
			Nitrogen fill tires	
			Tire(s) balanced	
			<ul> <li>Tire(s) replaced</li> </ul>	
			Four tires replaced	
2017 Jul 25		Lancaster Auto & Tire Discounter	Vehicle serviced	
		Burlington, Ontario, Canada	Tire repaired	
2018 Feb 12	67,797 KM	Lancaster Auto & Tire Discounter	Vehicle serviced	
		Burlington, Ontario, Canada	Tires rotated	
2019 Feb 1	79,238 KM	Lancaster Auto & Tire Discounter	Vehicle serviced	
		Burlington, Ontario, Canada		

	ODOMETER	SOURCE	DETAILS
2019 Jul 4	84,692 KM	Lancaster Auto & Tire Discounter Burlington, Ontario, Canada	Vehicle serviced  • Brakes checked
		Burlington, Ontario, Cariada	Tires rotated
			Brake pads replaced
			Rear brakes replaced
2019 Nov 7	89,900 KM	Midas Auto Service Experts	Vehicle serviced
		Burlington, Ontario, Canada	Exhaust pipe replaced
		<b>3</b> , ,	Exhaust pipe seal replaced
2020 Sep 16	95,687 KM	Budds' Chevrolet, Cadillac, Buick,	Vehicle serviced
		GMC	<ul> <li>Engine/powertrain computer/module checked</li> </ul>
		Oakville, Ontario, Canada	Wiper(s) replaced
		, .	Oil and filter changed
2020 Oct 5	96,821 KM	Budds' Chevrolet, Cadillac, Buick,	Vehicle serviced
		GMC	
		Oakville, Ontario, Canada	
2020 Dec 7	99,485 KM	Active Green & Ross	Vehicle serviced
		Hamilton, Ontario, Canada	



### **Open Recalls**

Recall #: N212340980 | Rear Toe Link Separation Recall Date: 2021 Jun 24

#### **Recall Description**

General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2010 to 2016 model year Cadillac SRX and 2011 to 2012 Saab 9-4x vehicles. These vehicles may have received improper service requiring adjustment of a rear suspension toe link. In rare cases, dealers or independent repair shops may not have followed GM's published procedures for torquing the jam nut in the toe link adjusters to the proper specification. A loose toe link can cause the vehicle to sway or wander at highway speeds or allow water or other corrosive elements to enter the threads within the adjuster. If a toe link is improperly adjusted, corrosion combined with vehicle motion may eventually cause the threads within the link to wear and loosen. In very rare cases with continued use, the link could separate. Separation while the vehicle is being driven increases the risk of a crash.

#### Remedy

Dealers will replace the adjustable toe link with a design that prevents adjustment.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CADILLAC or visit **GM's website**.



#### Stolen Vehicle Check

This vehicle is not actively declared stolen.



DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 May 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as gray
2014 May 8		CADILLAC	Recall	Manufacturer Recall Issued Recall # N140132
2014 Jul 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2014 Sep 12		CADILLAC	Recall	Manufacturer Recall Issued Recall # N140457
2015 Jul 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2015 Sep 4		Insurance Records Ontario, Canada	Glass Record	\$586.00
2015 Sep 11		Police Reported Accident Ontario, Canada	Police Report	Accident Reported:
2015 Sep 11		Ontario, Canada	Unknown	
2016 Jul 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 Nov 2	52,086 KM	Lancaster Auto & Tire Discounter Burlington, Ontario, Canada	Service Record	Vehicle serviced
2017 Jul 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Jul 25		Lancaster Auto & Tire Discounter Burlington, Ontario, Canada	Service Record	Vehicle serviced
2018 Feb 12	67,797 KM	Lancaster Auto & Tire Discounter Burlington, Ontario, Canada	Service Record	Vehicle serviced
2018 Apr 30		Insurance Records Ontario, Canada	Glass Record	\$85.00
2018 Jul 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Feb 1	79,238 KM	Lancaster Auto & Tire Discounter Burlington, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Apr 21		Insurance Records Ontario, Canada	Glass Record	\$118.00
2019 Jul 4	84,692 KM	Lancaster Auto & Tire Discounter Burlington, Ontario, Canada	Service Record	Vehicle serviced
2019 Nov 7	89,900 KM	Midas Auto Service Experts Burlington, Ontario, Canada	Service Record	Vehicle serviced
2020 Sep 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2020 Sep 16		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as gray
2020 Sep 16	95,687 KM	Budds' Chevrolet, Cadillac, Buick, GMC Oakville, Ontario, Canada	Service Record	Vehicle serviced
2020 Oct 5	96,821 KM	Budds' Chevrolet, Cadillac, Buick, GMC Oakville, Ontario, Canada	Service Record	Vehicle serviced
2020 Dec 7	99,485 KM	Active Green & Ross Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2021 Jun 24		CADILLAC	Recall	Manufacturer Recall Issued Recall # N212340980
2021 Oct 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as gray



# Questions? We're here to help.

Visit us at **support.carfax.ca** 

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers service receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantablity, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada. Conditions of Use and any CARFAX Canada are greements as each may be amended from time to time by CARFAX Canada. Conditions of Use

© 2023 CARFAX Canada ULC. All rights reserved.

