


# 2018 VOLKSWAGEN GOLF S

Hatchback | 4 Cylinders | Gas 3VWG17AU7JM282476 Country of Assembly: Mexico Last Reported Odometer: 176,291 KM

(i)



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of July 17, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# **Vehicle History Report**



# Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
<b>1</b> 2020 Jan 7	Ontario, Canada	
	<b>Police Reported Accident:</b> Accident reported: minor damage Vehicle involved in a rear-end collision with another motor vehicle Damage to rear	
	Claim: Collision	\$0.00

## **Other Damage Records**

RECORD DATE	DETAILS	AMOUNT
9 2020 Nov 12	Ontario, Canada	
	Glass Record	\$175.00

# Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding. We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

### Service Records

DATE	ODOMETER	SOURCE	DETAILS	
2018 Jun 22		Humberview Volkswagen	Vehicle serviced	
		Toronto, Ontario, Canada		
2018 Jul 13		Humberview Trucks	Vehicle serviced	
		Etobicoke, Ontario, Canada		
2018 Jul 17		Humberview Volkswagen	Vehicle serviced	
		Toronto, Ontario, Canada		
2019 Oct 29	37,546 KM	Julie's Tire And Auto	Vehicle serviced	
		Thorold, Ontario, Canada		
2021 Apr 12		Service Facility	Vehicle serviced	
			<ul> <li>Inspection performed</li> </ul>	
			Alignment checked	

	ODOMETER	SOURCE	DETAILS
2024 Jul 4	176,291 KM	Jiffy Lube Hamilton, Ontario, Canada	Vehicle serviced <ul> <li>Oil and filter changed</li> </ul>

### ┥)) Open Recalls

Recall #: 20UF | SUCTION JET PUMP Recall Date: 2024 Feb 16

#### **Recall Description**

The suction jet pump inside the fuel tank is designed to purge fuel from the Evaporative Emissions (EVAP) system. If a specific seal inside an affected suction jet pump fails, the fuel may flow directly into the EVAP system. If this happens, fuel could accumulate in the EVAP system and may leak through the charcoal canister filter element. Leaking fuel, in the presence of an ignition source, may result in a fire.

#### Remedy

REPAIR NOT YET AVAILABLE

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit Volkswagen's website. (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)

### Stolen Vehicle Check

This vehicle is not actively declared stolen.

# Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Jun 22		Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2018 Jul 10		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Fleet Vehicle colour noted as white
2018 Jul 13		Humberview Trucks Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2018 Jul 17		Humberview Volkswagen Toronto, Ontario, Canada	Service Record	Vehicle serviced
2019 May 24	32,552 KM	Independent Source Cayuga, Ontario, Canada	Odometer reading	
2019 Aug 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as white

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Oct 29	37,546 KM	Julie's Tire And Auto Thorold, Ontario, Canada	Service Record	Vehicle serviced
2020 Jan 7		Police Reported Accident Ontario, Canada	Police Report	<ul> <li>Accident Reported:</li> <li>minor damage</li> <li>Vehicle involved in a rear-end collision</li> <li>with another motor vehicle</li> <li>Damage to rear</li> </ul>
2020 Jan 7		Insurance Records Ontario, Canada		
2020 Jul 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as white
2020 Nov 12		Insurance Records Ontario, Canada	Glass Record	\$175.00
2021 Apr 12		Service Facility	Service Record	Vehicle serviced
2021 Jun 28		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as white
2022 Jul 19		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as white
2024 Feb 16		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 20UF
2024 Jul 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2024 Jul 4	176,291 KM	Jiffy Lube Hamilton, Ontario, Canada	Service Record	Vehicle serviced



This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers reviewe data and information of more ternal solucres believed to be reliable, but no responsibility is assumed by CARFAX Canada, providers reviewe data and information performs, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantabile quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information content information obturt the vehicle that is the subject matter of this vehicle history report, including problems, may not been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about two vehicle that is the subject matter of this vehicle history report, you agree to be bound by all of the terms and conditions of Use and any CARFAX canada fuel User License Agreements as each may be amended from time to time by CARFAX Canada.

© 2024 CARFAX Canada ULC. All rights reserved.

