

2016 VOLKSWAGEN GTI S/SE

Hatchback | 4 Cylinders | Gas

3VW5T7AU0GM051011

Country of Assembly: Mexico

Last Reported Odometer: 193,768 KM

LIEN CHECK



No Lien Records Found



Accident/Damage Records Found

Last Registered In:
Ontario (Normal)

15 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of August 09, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report + Lien Check



Lien Check

✓ No lien records found in **Ontario**.

How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

CARFAX Canada Canadian Lien Guarantee



If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2022 Mar 20	Ontario, Canada Police Reported Accident: Accident reported: minor damage Vehicle involved in a rear-end collision with another motor vehicle Damage to rear	



Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2020 Jun 25		Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">• Drivability/performance checked• Four wheel alignment performed• Alignment checked• Alignment performed• Front brake rotor(s) replaced• Front brake pads replaced
2021 Jan 21	92,013 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">• Cooling system checked• Fluids checked• Oil and filter changed• Tire condition and pressure checked• Exterior lights checked• Thermostat replaced

	ODOMETER	SOURCE	DETAILS
2021 Mar 25	94,852 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced
2021 May 18	95,714 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Engine compression checked • Engine removed to complete repair • Transmission removed and reinstalled • Long block replaced • Oil and filter changed • Oil pressure sender/switch replaced • Spark plug(s) replaced • Drivability/performance checked
2021 Jun 8	96,944 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Fluids checked • Oil and filter changed • Tire condition and pressure checked • Exterior lights checked
2021 Jul 22	100,534 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Drivability/performance checked • Four wheel alignment performed • Alignment checked • Alignment performed • Fluids checked • Oil and filter changed • Tire condition and pressure checked • Exterior lights checked • Brakes checked
2021 Sep 29	110,610 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Brakes checked
2021 Dec 3	117,416 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Windshield replaced
2022 Feb 11	120,459 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Fluids checked • Oil and filter changed • Tire condition and pressure checked • Exterior lights checked • Brake fluid flushed/changed
2022 Jun 3	128,580 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Vehicle washed/detailed • Brakes checked
2022 Aug 17	133,252 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Vehicle washed/detailed
2022 Sep 30	143,536 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Oil and filter changed • Brakes checked
2023 Jan 23	154,986 KM	Chatham Volkswagen Chatham, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Tires rotated
2023 Nov 10	186,554 KM	Chatham Volkswagen Chatham, Ontario, Canada	Vehicle serviced
2024 Jan 2	193,768 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Front wheel bearing(s)/hub(s) replaced • One wheel replaced



Recall Description

The suction jet pump inside the fuel tank is designed to purge fuel from the Evaporative Emissions (EVAP) system. If a specific seal inside an affected suction jet pump fails, the fuel may flow directly into the EVAP system. If this happens, fuel could accumulate in the EVAP system and may leak through the charcoal canister filter element. Leaking fuel, in the presence of an ignition source, may result in a fire.

Remedy

Replace the suction jet pump.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Jul 21		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as black
2017 Aug 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Nov 21		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 Feb 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 Jun 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2020 Jun 10	86,305 KM	Independent Source Ontario, Canada	Odometer reading	
2020 Jun 25		Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2020 Jul 7		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black
2021 Jan 21	92,013 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2021 Mar 25	94,852 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2021 Mar 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 May 18	95,714 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2021 Jun 8	96,944 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2021 Jul 22	100,534 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2021 Sep 29	110,610 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2021 Dec 3	117,416 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2022 Feb 11	120,459 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2022 Mar 20		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> • minor damage • Vehicle involved in a rear-end collision • with another motor vehicle • Damage to rear
2022 Jun 3	128,580 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2022 Aug 17	133,252 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2022 Sep 30	143,536 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2023 Jan 23	154,986 KM	Chatham Volkswagen Chatham, Ontario, Canada	Service Record	Vehicle serviced
2023 Apr 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black
2023 Nov 10	186,554 KM	Chatham Volkswagen Chatham, Ontario, Canada	Service Record	Vehicle serviced
2024 Jan 2	193,768 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2024 Feb 16		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 20UF



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2024 CARFAX Canada ULC. All rights reserved.

