



2010 TOYOTA COROLLA BASE

Sedan | 4 Cylinders | Gas 2T1BU4EE2AC392818 Country of Assembly: Canada Last Reported Odometer: 74,390 KM



CARFAX Canada as of December 18, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



There are no accidents/damage reported on this vehicle.

🔋 Registration

🥑 This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

🧧 Service Records

DATE	ODOMETER	SOURCE	DETAILS
2015 Aug 8	74,390 KM	Midas Auto Service Experts Mississauga, Ontario, Canada	Vehicle serviced Oil and filter changed

) Open Recalls

Recall #: CAN234 | 234- Remedy Notice - Certain 2006-2010 MY Corolla, Matrix. Highlander, Tacoma, RAV4, Yaris vehicles Recall Date: 2014 Apr - Spiral Cable 09

Recall Description

The steering column assembly in the involved vehicles contains a spiral cable assembly with electrical connections to the drivers airbag module that could become damaged when the steering wheel is turned. If this occurs, the airbag warning lamp will illuminate. In addition, the drivers airbag could become deactivated, causing it to not deploy in the event of a crash. This could increase the injury to the driver.

Remedy

Toyota dealerships will replace the spiral cable assembly in the subject vehicle.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit Toyota's website. (https://www.toyota.ca/toyota/en/owners/recalls)

Recall #: CANR10 | R10 - Remedy Notice Certain Toyota Camry, Camry HV, RAV4, Corolla, Matrix, Tundra, Sequoia, Highlander,Recall Date:Yaris, Scion xB and Scion xD vehicles (2006 - 2011) Power Window Master Switch Assembly2015 Oct 21

Recall Description

The Power Window Master Switch (located on the driver's door) in the above vehicles may have been manufactured with insufficient lubricant grease. If sufficient grease is not applied, under certain conditions the switch may develop a short circuit that can cause the switch assembly to overheat and melt. A melting switch can produce smoke and potentially lead to a fire.

Remedy

The remedy will involve an inspection, switch disassembly, and application of a specialized grease. In a limited number of cases, the electronic circuit board in

the Power Window Master Switch will be replaced.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit **Toyota's website**. (https://www.toyota.ca/toyota/en/owners/recalls)

Recall #: CANR75 | R75 - Remedy Notice - Multiple Toyota Models and Model Years - Front Passenger Airbag Inflator Recall Date: 2019 Jan 09

Recall Description

The subject vehicles are equipped with front passenger airbag inflators produced by Takata. The propellant in these inflators may degrade after prolonged exposure to high absolute humidity and fluctuating high temperatures. Degraded propellant can cause the inflator to explode during airbag deployment.

Remedy

Toyota will replace the airbag inflator or the airbag assembly.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact TOYOTA or visit **Toyota's website**. (https://www.toyota.ca/toyota/en/owners/recalls)



This vehicle is not actively declared stolen.

Detailed History

ATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2010 May 31		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		First Owner Reported
				Vehicle colour noted as gray
2011 Feb 3		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		Previous Use: Commercial
2011 Dec 20	40,575 KM	Independent Source	Odometer reading	
		Milton, Ontario, Canada		
)12 Jan 4		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
		Ontario, Canada		New Owner reported
				Previous Use: Personal
)12 Aug 23		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
-		Ontario, Canada		Previous Use: Personal
2014 Apr 9		ΤΟΥΟΤΑ	Recall	Manufacturer Recall Issued
·				Recall # CAN234
2014 Aug 23		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed
-		Ontario, Canada		Previous Use: Personal
015 Aug 8	74,390 KM	Midas Auto Service Experts	Service Record	Vehicle serviced
-		Mississauga, Ontario, Canada		
015 Oct 21		ΤΟΥΟΤΑ	Recall	Manufacturer Recall Issued
				Recall # CANR10

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Jan 9		ΤΟΥΟΤΑ	Recall	Manufacturer Recall Issued Recall # CANR75
2024 Nov 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray
2024 Dec 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray



Questions? We're here to help.

Visit us at **support.carfax.ca**

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, doometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warrantices, express or implied, including any warranties of timelines, accuracy, merchantability, merchantability or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada and nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada. https://www.carfax.ca/about-carfax.privacy-legal/conditions-of-use

© 2024 CARFAX Canada ULC. All rights reserved.

