

2019 VOLKSWAGEN JETTA GLI

Sedan | 4 Cylinders | Gas

3VW6T7BUXKM197587

Country of Assembly: Mexico

Last Reported Odometer: 116,219 KM

One
Owner™ >



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



8 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of September 11, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2021 Oct 29	Mississauga, Ontario, Canada	
	Estimate: Not Available Estimate Date: 2021 Nov 3	\$6,346.55
	Claim: Unknown	\$7,220.00

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2021 Nov 1	n/a	
	Damage Event: Damage reported: minor damage Damage to front	



Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2019 Sep 4		Mississauga VW Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Pre-delivery inspection completed
2019 Sep 5		Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Pre-delivery inspection completedOutside mirror glass replaced
2019 Oct 15	3,674 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Antenna replacedHeadliner removed and reinstalled
2020 Feb 10	10,034 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Air dam repaired
2021 Jun 24		Service Facility	Vehicle serviced <ul style="list-style-type: none">Inspection performedAlignment checked
2021 Nov 30		Welland Honda Welland, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">A/C refrigerant rechargedA/C system flushed

	ODOMETER	SOURCE	DETAILS
2022 Jun 23	80,112 KM	Jiffy Lube Welland, Ontario, Canada	Vehicle serviced • Oil and filter changed
2023 Apr 11	116,219 KM	Take 5 Oil Change Grimsby, Ontario, Canada	Vehicle serviced • Oil and filter changed



Open Recalls

Recall #: 20UF | SUCTION JET PUMP Recall Date: 2024 Feb 16

Recall Description

The suction jet pump inside the fuel tank is designed to purge fuel from the Evaporative Emissions (EVAP) system. If a specific seal inside an affected suction jet pump fails, the fuel may flow directly into the EVAP system. If this happens, fuel could accumulate in the EVAP system and may leak through the charcoal canister filter element. Leaking fuel, in the presence of an ignition source, may result in a fire.

Remedy

Replace the suction jet pump.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Sep 4		Mississauga VW Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2019 Sep 5		Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2019 Sep 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as white
2019 Oct 15	3,674 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2020 Feb 10	10,034 KM	Hamilton Volkswagen Audi Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2021 Jun 24		Service Facility	Service Record	Vehicle serviced
2021 Oct 29		Ontario, Canada	Unknown	

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Nov 1			Damage Event	Damage reported: minor damage Damage to front
2021 Nov 3	97,587 KM	Insurance Records Mississauga, Ontario, Canada	Estimate Repair	Incident Date: 2021-10-29 Not Available
2021 Nov 30		Welland Honda Welland, Ontario, Canada	Service Record	Vehicle serviced
2022 Jun 23	80,112 KM	Jiffy Lube Welland, Ontario, Canada	Service Record	Vehicle serviced
2023 Apr 11	116,219 KM	Take 5 Oil Change Grimsby, Ontario, Canada	Service Record	Vehicle serviced
2024 Feb 16		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 20UF
2024 Jul 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada One Owner™ Badge

The CARFAX Canada One Owner™ badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2024 CARFAX Canada ULC. All rights reserved.

