

2016 VOLKSWAGEN GOLF S

Hatchback | 4 Cylinders | Gas

3VW117AUXGM056642

Country of Assembly: Mexico

Last Reported Odometer: 146,621 KM



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



11 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of April 24, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2016 Jul 5	Ontario, Canada	
	Police Reported Accident: Accident reported: moderate damage Involving front or side impact with another motor vehicle Damage to right rear Claim: Collision	\$8,153.00
2020 Feb 11	Ontario, Canada	
	Police Reported Accident: Accident reported: moderate damage Vehicle involved in a rear-end collision with another motor vehicle Damage to front Damage to left front	
2023 Jun 26	Aylmer, Ontario, Canada	
	Estimate: Not Available Estimate Date: 2023 Jul 6	\$3,534.07

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2023 Jul 6	n/a	
	Damage Event: Damage reported: minor damage Damage to left side	



Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2019 Sep 26		Tint World 4004 Mississauga, Ontario, Canada	Vehicle serviced
2020 Jan 27	92,790 KM	401 Dixie Volkswagen Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">Maintenance inspection completedOil and filter changed

	ODOMETER	SOURCE	DETAILS
2020 Nov 25	106,212 KM	Mississauga VW Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Vehicle washed/detailed
2021 Mar 27	110,238 KM	Milton Volkswagen Milton, Ontario, Canada	Vehicle serviced
2021 Apr 30	111,000 KM	Milton Volkswagen Milton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Tire condition and pressure checked
2021 May 19	112,834 KM	Milton Volkswagen Milton, Ontario, Canada	Vehicle serviced
2021 Jul 20	114,727 KM	Milton Volkswagen Milton, Ontario, Canada	Vehicle serviced
2021 Dec 8	123,845 KM	Milton Volkswagen Milton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked
2022 Mar 16	127,586 KM	Milton Volkswagen Milton, Ontario, Canada	Vehicle serviced
2022 Jun 9	129,308 KM	Meadowvale Tirecraft Mississauga, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed
2022 Jun 24	129,328 KM	Milton Volkswagen Milton, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Safety inspection performed



Open Recalls

Recall #: 20UF | SUCTION JET PUMP Recall Date: 2024 Feb 16

Recall Description

The suction jet pump inside the fuel tank is designed to purge fuel from the Evaporative Emissions (EVAP) system. If a specific seal inside an affected suction jet pump fails, the fuel may flow directly into the EVAP system. If this happens, fuel could accumulate in the EVAP system and may leak through the charcoal canister filter element. Leaking fuel, in the presence of an ignition source, may result in a fire.

Remedy

Replace the suction jet pump.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Jun 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as gray
2016 Jul 5		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> • moderate damage • Involving front or side impact • with another motor vehicle • Damage to right rear
2016 Jul 5		Insurance Records Ontario, Canada		
2016 Oct 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Oct 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Oct 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Aug 2	85,110 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	
2019 Sep 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal
2019 Sep 26		Tint World 4004 Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2020 Jan 27	92,790 KM	401 Dixie Volkswagen Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2020 Feb 11		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> • moderate damage • Vehicle involved in a rear-end collision • with another motor vehicle • Damage to front • Damage to left front
2020 Nov 25	106,212 KM	Mississauga VW Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2021 Mar 27	110,238 KM	Milton Volkswagen Milton, Ontario, Canada	Service Record	Vehicle serviced
2021 Apr 30	111,000 KM	Milton Volkswagen Milton, Ontario, Canada	Service Record	Vehicle serviced
2021 May 19	112,834 KM	Milton Volkswagen Milton, Ontario, Canada	Service Record	Vehicle serviced
2021 Jul 20	114,727 KM	Milton Volkswagen Milton, Ontario, Canada	Service Record	Vehicle serviced
2021 Dec 8	123,845 KM	Milton Volkswagen Milton, Ontario, Canada	Service Record	Vehicle serviced
2022 Mar 16	127,586 KM	Milton Volkswagen Milton, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2022 Jun 9	129,308 KM	Meadowvale Tirecraft Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2022 Jun 22		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray
2022 Jun 24	129,328 KM	Milton Volkswagen Milton, Ontario, Canada	Service Record	Vehicle serviced
2022 Jul 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as gray
2023 Jul 6			Damage Event	Damage reported: minor damage Damage to left side
2023 Jul 6	146,621 KM	Insurance Records Aylmer, Ontario, Canada	Estimate Repair	Incident Date: 2023-06-26 Not Available
2024 Feb 16		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 20UF
2024 Jul 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2025 Mar 31		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.



3WV117AUXGM056642