



Vehicle History Report #: 49834170

Report Date: November 20, 2023 | 3:55 PM EST

Report Status: Complete

## 2017 NISSAN PATHFINDER S

Sport utility vehicle | 6 Cylinders | Gas

5N1DR2MM3HC673600

Country of Assembly: United States

Last Reported Odometer: 199,189 KM



Accident/Damage Records  
Found



Last Registered In:  
Ontario (Normal)



7 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of November 20, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

5N1DR2MM3HC673600

# Vehicle History Report



## Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2020 May 24	Ontario, Canada	
	<b>Police Reported Accident:</b> Accident reported: minor damage with another motor vehicle Damage to left rear  <b>Claim:</b> Collision	\$532.00

## Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2021 Jun 27	Ontario, Canada	
	Glass Record	\$1,210.00



## Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

**We checked for:** Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2019 Oct 7	81,373 KM	MILTON NISSAN Milton, Ontario, Canada	<b>Vehicle serviced</b>
2019 Oct 15	81,869 KM	Great Canadian Oil Change Milton, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Maintenance inspection completed</li> <li>Oil and filter changed</li> <li>Air filter checked</li> <li>Air filter replaced</li> </ul>
2020 Oct 14	102,885 KM	Great Canadian Oil Change Milton, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Maintenance inspection completed</li> <li>Oil and filter changed</li> <li>Air filter checked</li> <li>Air filter replaced</li> </ul>
2021 Sep 9	122,997 KM	Niagara Auto Electric & Complete Service Centre Niagara Falls, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>A/C system checked</li> <li>A/C refrigerant recharged</li> <li>Front wheel bearing(s)/hub(s) replaced</li> </ul>

5N1DR2MM3HC673600

DATE	ODOMETER	SOURCE	DETAILS
2021 Oct 21	126,144 KM	Mobil 1 Lube Express Northern Auto Niagara Falls, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Brakes checked</li> <li>• Brakes serviced</li> <li>• Rear brake pads replaced</li> </ul>
2021 Dec 8	132,884 KM	Niagara Auto Electric & Complete Service Centre Niagara Falls, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Radiator fan replaced</li> </ul>
2023 Aug 21	179,353 KM	Active Green & Ross Niagara Falls, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Maintenance inspection completed</li> <li>• Lug nut(s)/bolt(s) replaced</li> <li>• Oil and filter changed</li> <li>• Brakes serviced</li> <li>• Tire repaired</li> <li>• Tire(s) replaced</li> <li>• Front strut(s) replaced</li> <li>• Front brake pads replaced</li> <li>• Brake rotor(s) replaced</li> <li>• Two tires mounted</li> <li>• Four wheel alignment performed</li> <li>• Two tires replaced</li> </ul>

## Open Recalls

Recall #: R1920 | MAXMURPATH ABS FT NTB19104 Recall Date: 2019 Nov 14

### Recall Description

The ABS actuator pump seal may leak, causing the electronic circuit board to malfunction and the ABS warning lamp to illuminate.

### Remedy

Dealers will replace the ABS actuator with a countermeasure part. The ABS actuator replacement repair time is three (3) hours. However, your dealer may require your vehicle for a longer period of time based on their work schedule.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit [Nissan's website](#).

## Stolen Vehicle Check

 This vehicle is not actively declared stolen.

## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Apr 7		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Fleet Vehicle colour noted as white

5N1DR2MM3HC673600

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Fleet
2019 Apr 4	68,927 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	
2019 Apr 16		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as white
2019 Oct 7	81,373 KM	MILTON NISSAN Milton, Ontario, Canada	Service Record	Vehicle serviced
2019 Oct 15	81,869 KM	Great Canadian Oil Change Milton, Ontario, Canada	Service Record	Vehicle serviced
2019 Nov 14		NISSAN	Recall	Manufacturer Recall Issued Recall # R1920
2020 May 24		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> <li>• minor damage</li> <li>• with another motor vehicle</li> <li>• Damage to left rear</li> </ul>
2020 May 24		Ontario, Canada	Collision	
2020 Oct 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
2020 Oct 14	102,885 KM	Great Canadian Oil Change Milton, Ontario, Canada	Service Record	Vehicle serviced
2021 Jun 27		Insurance Records Ontario, Canada	Glass Record	\$1,210.00
2021 Sep 9	122,997 KM	Niagara Auto Electric & Complete Service Centre Niagara Falls, Ontario, Canada	Service Record	Vehicle serviced
2021 Oct 21	126,144 KM	Mobil 1 Lube Express Northern Auto Niagara Falls, Ontario, Canada	Service Record	Vehicle serviced
2021 Dec 8	132,884 KM	Niagara Auto Electric & Complete Service Centre Niagara Falls, Ontario, Canada	Service Record	Vehicle serviced
2022 Sep 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as white

5N1DR2MM3HC673600

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2023 Aug 21	179,353 KM	Active Green & Ross Niagara Falls, Ontario, Canada	Service Record	Vehicle serviced
2023 Nov 6	199,189 KM	Independent Source St. Catharines, Ontario, Canada	Odometer reading	



Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© 2024 CARFAX Canada ULC. All rights reserved.



5N1DR2MM3HC673600