

# 2008 HYUNDAI SONATA GLS

Sedan | 4 Cylinders | Gas  
5NPET46CX8H394417  
Country of Assembly: United States  
Last Reported Odometer: 131,828 KM

No Reported Accidents™ >



No Accident/Damage Records Found



Last Registered In: Ontario (Normal)



2 Service Records Found



No U.S. History Found



4 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of June 28, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# Vehicle History Report



## Accident/Damage

✓ There are no accidents/damage reported on this vehicle.



## Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

*We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2014 Feb 13	131,828 KM	Active Green & Ross Brampton, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Safety inspection performed</li><li>Electrical system checked</li></ul>
2014 Feb 14		Active Green & Ross Brampton, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Emissions inspection performed</li></ul>



## Open Recalls

Recall #: R0054 | OCCUPANT CLASSIFICATION SYSTEM Recall Date: 2008 Jun 02

### Recall Description

On certain vehicles equipped with an advanced airbag system, the Occupant Classification System (OCS), installed in the right front seat of the vehicle, may misclassify a small stature adult as a child and deactivate the passenger airbag. This would cause the right front airbag to not inflate in a crash that merits airbag deployment, and may result in injury to the right front seat occupant. Correction: Dealers will verify that the OCS does not recognize a properly seated adult occupant. After verification, the right front seat cushion assembly will be removed and reprogrammed.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit [Hyundai's website](https://recall.hyundaicanada.com/). (<https://recall.hyundaicanada.com/>)

Recall #: R0079 | STOP LAMP SWITCH - Same Recall as R0082 (31C017) Recall Date: 2013 Apr 22

### Recall Description

On certain vehicles, the stop lamp switch may fail and cause intermittent operation of the brake lights. Failure of the brake lights to

illuminate when the brake pedal is depressed could result in a crash causing property damage and/or personal injury. Correction: Dealers will replace the switch.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit [Hyundai's website](https://recall.hyundaicanada.com/). (https://recall.hyundaicanada.com/)

Recall #: R0082 | STOP LAMP SWITCH - Same Recall as R0079 (31C017) Recall Date: 2013 Apr 22

#### Recall Description

On certain vehicles, the stop lamp switch may fail and cause intermittent operation of the brake lights. Failure of the brake lights to illuminate when the brake pedal is depressed could result in a crash causing property damage and/or personal injury. Correction: Dealers will replace the switch.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit [Hyundai's website](https://recall.hyundaicanada.com/). (https://recall.hyundaicanada.com/)

Recall #: R0081 | REAR CROSSMEMBER Recall Date: 2013 Oct 01

#### Recall Description

On certain vehicles, road salt can corrode the rear crossmember assembly, which may ultimately lead to separation of the control arm at the mounting point. This would allow the wheel to rotate off its designed axis, and could result in a loss of vehicle control and a crash causing property damage and/or personal injury. Correction: Dealers will repair or replace the rear crossmember assembly.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit [Hyundai's website](https://recall.hyundaicanada.com/). (https://recall.hyundaicanada.com/)



## Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2008 Apr 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as black
2008 Jun 2		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0054
2008 Oct 28	16,940 KM	Hyundai Canada	Service Record	

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2009 Mar 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2010 Mar 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2011 Mar 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2011 Apr 28		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal
2012 Mar 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2013 Apr 22		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0079
2013 Apr 22		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0082
2013 Oct 1		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0081
2014 Feb 13	131,828 KM	Active Green & Ross Brampton, Ontario, Canada	Service Record	Vehicle serviced
2014 Feb 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal
2014 Feb 14		Active Green & Ross Brampton, Ontario, Canada	Service Record	Vehicle serviced
2015 May 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 May 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Sep 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal
2019 Mar 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal
2023 May 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as black



# Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

#### **CARFAX Canada No Reported Accidents™ Badge**

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2024 CARFAX Canada ULC. All rights reserved.

