

MECHANICAL FITNESS ASSESSMENT

As required by Vehicle Inspection Regulation (A/R 211/2006)

Dealer: Diamond Motors

AMVIC Licence Number:

Address: 3403 93ST NW EDM AB, T6E-6A4

VEHICLE INFORMATION

Year: 2018 Make: HONDA Model: ODYSSEY Previous Province of Registration:

Vehicle Identification Number: 5FNRL6H24JB507008 Odometer Reading: 154126 (km / mi)

Truck Motorcycle Bus Van Light Truck Auto Motorized RV Other

Please check mark (✓) each item as C=Complies or N=Non-Compliant. If item is Not Applicable indicate as N/A in the C column

Powertrain	C	N
Accelerator	/	
Fuel System	/	
Exhaust	/	
Transmission	/	
Front/Rear/Spindles Axles	/	
Clutch	/	
Fluid Levels (power steering, brake)	/	
CV Joints	/	

Lamps	C	N
Head Lamp Hi Beam	/	
Head Lamp Lo Beam	/	
Head Lamp Location	/	
Daytime Running Lamps	/	
Tail Lamps	/	
Brake Lamps	/	
Turn Signal Lamps	/	
Hazard Warning Lamps	/	
Licence Plate Lamp	/	
Back-up Lamps	/	

Instruments	C	N
Speedometer/Odometer	/	
Indicator Lamps	/	
Horn	/	
Hi Beam Indicator	/	

Brakes	C	N
Parking/Emergency Brake	/	
Hydraulic System	/	
Vacuum System	/	
Drum Brakes	/	
Disc Brakes	/	
Shoes/Pads	/	
Anti-Lock (if OEM equipped)	/	

Steering	C	N
Steering Lash	/	
Steering Linkage	/	
Rack & Pinion	/	
Power Steering System	/	
King Pin	/	
Ball Joints	/	

Suspension	C	N
Leaf springs	/	
Struts and Shocks	/	
Coil spring	/	
Torsion Bar	/	
Independent/Multilink Rear	/	
Computer Controlled	/	

Diagnostic	C	N
Diagnostic Trouble Codes	/	

Frame & Body	C	N
Hood Latch	/	
Door Latches & Hinges	/	
Bumpers	/	
Windshield Wipers & Washer	/	
Rear Wiper & Washer	/	
Windshield	/	
Windows	/	
Defrost/Heaters	/	
Mirrors	/	
Seats	/	
Seat Belts/Airbags	/	
Mudguards	/	
Window Glazing	/	
Structural Integrity	/	

Tires & Wheels	C	N
Tread Depth	/	
Tread Section	/	
Sidewalls	/	
Wheels	/	

Electrical	C	N
Wiring	/	
Battery	/	
Switches	/	
Alternator	/	

Technician Comments

This is to certify that I have assessed the vehicle described above in accordance with the Traffic Safety Act, Vehicle Equipment Regulation (A/R 122/2009). By signing this assessment, I verify the contents of this document are true and correct.

I, the buyer of this vehicle, acknowledge receipt of this assessment.

Signature of Certified Journeyman Technician: [Signature]

Signature of Buyer

Technician Name (Print): M. DEAN

Buyer (Print)

Technician Trade Certificate Number: 103197A

Signature of Salesperson

Date: FEB 20 2024

Salesperson (Print)

This assessment expires 120 days after the date it was issued.

Date



**Out of Province Vehicle Inspection Certificate
Traffic Safety Act**

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Automotive	Seating Capacity:	
GVW:		Brake Type:	Hydraulic
Owner Name:	DIAMOND MOTORS		
Address:	3403 93 ST		
City:	EDM	Province:	AB
		Postal Code:	T6E-6A4
Telephone Number:	(587) 444-3300		
Vehicle Identification Number:	5FNRL6H24JB507008		
Make:	Honda	Model:	Odyssy COD
Year:	2018	Unit Number:	
Odometer:	154126 KM	Licence Plate Number:	
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Out of Province Vehicle.

Inspection Facility Name:	Dean's Automotive Services Ltd.	Facility Number:	11566
Inspection Technician Name:	Mohammed Dean	Technician Number:	B6625
Inspection Technician Signature:			
Inspection Date:	2024/02/20		

NOTICE TO VEHICLE OWNER

1. This inspection certificate expires after 14 days from the Inspection date. After 14 days, a complete re-inspection of the vehicle is required.
2. The original of this Certificate must be presented to an Alberta Registry Agent within 14 days; however, there is no requirement to register the vehicle when the certificate is presented.

MOTOR VEHICLE RECORD OF INSPECTION

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Vehicle Information

VIN	5	F	N	R	L	6	H	2	4	J	B	5	0	7	0	0	8
-----	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

Make Honda	Model Odyssey COD	Year 2018	Odometer 154126
----------------------	-----------------------------	---------------------	---------------------------

Customer Information

Organization Name DIAMOND MOTORS	
Address 3403 93 ST	Postal Code T6E-6A4

Section 1 - Pre-Inspection

Component	P	F	NA	Component	P	F	NA
1.1a. Request for Inspection (RFI)	✓			1.3c. Vehicle Wanders or Pulls	✓		
1.1b. Vehicle Accurately Described On The RFI	✓			1.3d. Brake System Performance	✓		
1.2a. VIN Plate Condition	✓			1.3e. Driveability	✓		
1.2b. VIN Consistent With RFI	✓			1.3f. Speedometer Operation	✓		
1.3a. CV Joint Road Test Result	✓			1.3g. Odometer (if equipped) Operation	✓		
1.3b. Universal Joint Road Test Result	✓						

NOTES:

Section 2 - Onboard Diagnostic Systems

Component	P	F	NA	Component	P	F	NA
2.1a. PCM Codes Present	✓			2.4b. SRS Lamp Fails To Illuminate	✓		
2.1b. PCM (MIL, SES, etc) Lamp Fails To Illuminate	✓			2.4c. SRS Lamp Remains Illuminated	✓		
2.2a. ABS Codes Present	✓			2.4d. Airbag(s) Present	✓		
2.2b. ABS Lamp Fails to Illuminate	✓			2.4e. Airbag Cover Integrity	✓		
2.2c. ABS Lamp Remains Illuminated	✓			2.5. Electronic Stability Control (ESC)	✓		
2.3a. Brake System Warning Lamp Fails to Illuminate	✓			2.6. Powertrain Warning Lamps	✓		
2.3b. Brake System Warning Lamp Remains Illuminated	✓			2.7. Other Safety Systems	✓		
2.4a. SRS Codes Present	✓						

NOTES:

Section 3 - Interior

Component	P	F	NA	Component	P	F	NA
3.1. Doors	✓			3.11. Instrument Panel Lamps	✓		
3.2. Rear View Mirror	✓			3.12. HVAC	✓		
3.3. Sun Visors	✓			3.13. Windshield Wiper and Washer Operation	✓		
3.4. Horn	✓			3.14. Accelerator	✓		
3.5. Seats	✓			3.15. Service Brake Pedal	✓		
3.6. Seatbelts	✓			3.16. Clutch Pedal Assembly			✓
3.7. Signal Lamp Switch and Indicator	✓			3.17. Park Brake	✓		
3.8. Hazard Lamps	✓			3.18. Neutral Safety Switch Operation	✓		
3.9. Headlamp Switch and High Beam Indicator	✓			3.19. Entertainment Display Lockout	✓		
3.10. Auxiliary Lamp Indicator(s)			✓				

NOTES:

MOTOR VEHICLE RECORD OF INSPECTION

Section 4 - Glass

Component	P	F	NA	Component	P	F	NA
4.1a. Windshield Marked AS-1, AS-10, or AS-14	✓			4.2b. Side Window Operation	✓		
4.1b. Windshield Condition	✓			4.2c. Side Window Aftermarket Tint	✓		
4.1e. Windshield Tinting / Decals	✓			4.2d. Side Window Visibility (general)	✓		
4.1f. Windshield Visibility (general)	✓			4.3a. Rear Window AS-1, AS-2, AS-3, AS-10, or AS-11	✓		
4.2a. Side Glass Marked AS-1, AS-2, AS-10, or AS-11	✓			4.4a. Other Glass	✓		

NOTES:

Section 5 - Lamps

Component	P	F	NA	Component	P	F	NA
5.1. Lamps (general)	✓			5.7. Front Side Reflectors	✓		
5.2. Daytime Running Lamps	✓			5.8. Rear Side Marker Lamps	✓		
5.3. High Mount Brake Lamp	✓			5.9. Rear Side Reflectors	✓		
5.4. Headlamps	✓			5.10. Licence Plate Lamp	✓		
5.5. Auxiliary Lamps			✓	5.11. Emergency Lighting	✓		
5.6. Front Side Marker Lamps	✓						

NOTES:

Section 6 - Exterior, General

Component	P	F	NA	Component	P	F	NA
6.1. Fuel Cap	✓			6.3. Bumpers	✓		
6.2. General Body Condition	✓			6.4. Aftermarket Equipment Installation			✓

NOTES:

Section 7 - Under Hood

Component	P	F	NA	Component	P	F	NA
7.1. Hood Latch Mechanism	✓			7.7. Clutch Master Cylinder			✓
7.2. Hood Prop / Struts	✓			7.8. Fuel System	✓		
7.3. Remote Starter Operation			✓	7.9. Exhaust Manifold(s)	✓		
7.4. Battery	✓			7.10. Oil Leaks	✓		
7.5. Accessory Belt Drive System	✓			7.11. Engine and Transmission Mounts	✓		
7.6. Brake Master Cylinder	✓						

NOTES:

Section 8 - Steering and Suspension

Component	P	F	NA	Component	P	F	NA
8.1. Wheel Bearings	✓			8.8. Steering Gear			✓
8.2. Ball Joints (front and rear)	✓			8.9. Rack & Pinion	✓		
8.3. Tie Rod Ends (inner and outer)	✓			8.10. Power Steering System	✓		
8.4. Pitman Arm			✓	8.11. Control Arms	✓		
8.5. Idler Arm			✓	8.12. Struts and Shocks	✓		
8.6. Steering Stabilizer / Damper			✓	8.13. Springs	✓		
8.7. Steering Shaft Assembly	✓						

NOTES:

MOTOR VEHICLE RECORD OF INSPECTION

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tread Depth- LF:9 mm,RF:9 mm,LR:9 mm,RR:9 mm	✓			9.4. Tire Serial Numbers & Dates of Manufacture	✓		
9.2. Tire Condition (general)	✓			9.5. Wheels	✓		
9.3. Tire Size	✓			9.6. Wheel Nuts and Studs	✓		

NOTES:

Section 10 - Brakes

Component	P	F	NA	Component	P	F	NA
10.1. Brakes (general)	✓			10.6. Park Brake Drum Diameter- LR:NA mm,RR:NA mm			✓
10.2. Park Brake Lining- LR:NA mm,RR:NA mm			✓	10.6. Brake Rotor Thickness- LF:28 mm,RF:28 mm	✓		
10.2. Brake Lining- LF:11 mm,RF:11 mm,LR:8 mm,RR:8 mm	✓			10.7. Brake Drum Condition (general)	✓		
10.3. Brake Lines and Hoses	✓			10.8. Brake Rear Rotor- LR:10 mm,RR:10 mm	✓		
10.4. Brake System Wiring	✓			10.9. Park Brake	✓		
10.5. Brake Rotor Condition (general)	✓						

NOTES:

Section 11 - Under Vehicle

Component	P	F	NA	Component	P	F	NA
11.1. Bumpers	✓			11.5. Drive Axles / Propeller Shafts	✓		
11.2. Engine	✓			11.6. Floor Pan	✓		
11.3. Transmission / Transaxle / Transfer Case	✓			11.7. Fuel System	✓		
11.4. Differential(s)	✓			11.8. Exhaust System	✓		

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED (Certificate #5719719)** the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection 2024/02/20	Technician Number B6625	Facility Number 11566	Signature 
---	-----------------------------------	---------------------------------	--

Customer Acknowledgment

<p>I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.</p>	Date (Year/Month/Day) 2024/02/20
Customer Signature	