

Millwoods Auto Inspection & Repair

3456 - 91 Street

Edmonton, AB

T6E 5R1

Tel.#: (780) 462-2799 FAX: (780) 988-2453



VEHICLE INFORMATION

Year: 2019 Make: MB Model: E 300 Previous Province of Registration: _____
Vehicle Identification Number: WDDZF41FB8KA524091 Odometer Reading: 159 164 ☒ (km / mi) ☐

☐ Truck ☐ Motorcycle ☐ Bus ☐ Van ☐ Light Truck ☒ Auto ☐ Motorized RV ☐ Other

Please check mark (✓) each item as C = Complies N = Non-Compliant N/A=Not Applicable

Powertrain	C	N
Accelerator	✓	
Fuel System	✓	
Exhaust	✓	
Transmission	✓	
Front/Rear/Spindles Axles	✓	
Clutch	✓	
Fluid Levels (power steering, brake)	✓	
CV Joints	✓	

Lamps	C	N
Head Lamp Hi Beam	✓	
Head Lamp Lo Beam	✓	
Head Lamp Location	✓	
Daytime Running Lamps	✓	
Tail Lamps	✓	
Brake Lamps	✓	
Turn Signal Lamps	✓	
Hazard Warning Lamps	✓	
Licence Plate Lamp	✓	

Instruments	C	N
Speedometer/Odometer	✓	
Indicator Lamps	✓	
Horn	✓	
Hi Beam Indicator	✓	

Brakes	C	N
Parking/Emergency Brake	✓	
Hydraulic System	✓	
Vacuum System	✓	
Drum Brakes	✓	
Disc Brakes	✓	
Shoes/Pads	✓	
Anti-Lock (if OEM equipped)	✓	

Steering	C	N
Steering Lash	✓	
Steering Linkage	✓	
Rack & Pinion	✓	
Power Steering System	✓	
King Pin	N	A
Ball Joints	✓	

Suspension	C	N
Leaf springs	N	A
Struts and Shocks	✓	
Coil spring	✓	
Torsion Bar	N	A
Independent/Multilink Rear	✓	
Computer Controlled	✓	
Diagnostic Trouble Codes	✓	

Frame & Body	C	N
Hood Latch	✓	
Door Latches & Hinges	✓	
Bumpers	✓	
Windshield Wipers & Washer	✓	
Rear Wiper & Washer	✓	
Windshield	✓	
Windows	✓	
Defrost/Heaters	✓	
Mirrors	✓	
Seats	✓	
Seat Belts/Airbags	✓	
Mudguards	✓	
Window Glazing	✓	
Structural Integrity	✓	

Tires & Wheels	C	N
Tread Depth	✓	
Tread Section	✓	
Sidewalls	✓	
Wheels	✓	

Electrical	C	N
Wiring	✓	
Battery	✓	
Switches	✓	
Alternator	✓	

Technician Comments

This is to certify that I have assessed the vehicle described above in accordance with the **Traffic Safety Act, Vehicle Equipment Regulation (A/R 122/2009)**. By signing this assessment, I verify the contents of this document are true and correct.

Signature of Certified Journeyman Technician: _____

Technician Name (Print): mike.

Technician Trade Certificate Number: B4954

Date: Oct 24 2025

I, the buyer of this vehicle, acknowledge receipt of this assessment.

Signature of Buyer _____

Buyer (Print) _____

Signature of Salesperson _____

Salesperson (Print) _____

Date _____



CERTIFICATE NUMBER
**Out of Province Vehicle Inspection Certificate
Traffic Safety Act**
**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Automotive	Seating Capacity:	
GVW:		Brake Type:	Hydraulic
Owner Name:	DIMOND MOTORS		
Address:	3403 93ST NW		
City:	EDMONTON	Province:	AB
		Postal Code:	T6T6A4
Telephone Number:	(780) 340-7080		
Vehicle Identification Number:	WDDZF4KB8KA524091		
Make:	Mercedes Benz	Model:	E300
Year:	2019	Unit Number:	
Odometer:	159164 KM	Licence Plate Number:	
		Province:	BC

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Out of Province Vehicle.

Inspection Facility Name:	Facility Number:
Millwoods Auto Inspection & Repairs Ltd.	20648
Inspection Technician Name:	Technician Number:
Azim Mohamed	B4954
Inspection Technician Signature:	
Inspection Date:	2025/10/24

NOTICE TO VEHICLE OWNER

1. This inspection certificate expires after 14 days from the Inspection date. After 14 days, a complete re-inspection of the vehicle is required.
2. The original of this Certificate must be presented to an Alberta Registry Agent within 14 days; however, there is no requirement to register the vehicle when the certificate is presented.

MOTOR VEHICLE RECORD OF INSPECTION

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Vehicle Information

VIN	W	D	D	Z	F	4	K	B	8	K	A	5	2	4	0	9	1
-----	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

Make
Mercedes Benz

Model
E300

Year
2019

Odometer
159164

Customer Information

Organization Name
DIMOND MOTORS

Address
3403 93ST NW

Postal Code
T6T6A4

Section 1 - Pre-Inspection

Component	P	F	NA	Component	P	F	NA
1.1a. Request for Inspection (RFI)	✓			1.3c. Vehicle Wanders or Pulls	✓		
1.1b. Vehicle Accurately Described On The RFI	✓			1.3d. Brake System Performance	✓		
1.2a. VIN Plate Condition	✓			1.3e. Driveability	✓		
1.2b. VIN Consistent With RFI	✓			1.3f. Speedometer Operation	✓		
1.3a. CV Joint Road Test Result	✓			1.3g. Odometer (if equipped) Operation	✓		
1.3b. Universal Joint Road Test Result	✓						

NOTES:

Section 2 - Onboard Diagnostic Systems

Component	P	F	NA	Component	P	F	NA
2.1a. PCM Codes Present	✓			2.4b. SRS Lamp Fails To Illuminate	✓		
2.1b. PCM (MIL, SES, etc) Lamp Fails To Illuminate	✓			2.4c. SRS Lamp Remains Illuminated	✓		
2.2a. ABS Codes Present	✓			2.4d. Airbag(s) Present	✓		
2.2b. ABS Lamp Fails to Illuminate	✓			2.4e. Airbag Cover Integrity	✓		
2.2c. ABS Lamp Remains Illuminated	✓			2.5. Electronic Stability Control (ESC)	✓		
2.3a. Brake System Warning Lamp Fails to Illuminate	✓			2.6. Powertrain Warning Lamps	✓		
2.3b. Brake System Warning Lamp Remains Illuminated	✓			2.7. Other Safety Systems	✓		
2.4a. SRS Codes Present	✓						

NOTES:

Section 3 - Interior

Component	P	F	NA	Component	P	F	NA
3.1. Doors	✓			3.11. Instrument Panel Lamps	✓		
3.2. Rear View Mirror	✓			3.12. HVAC	✓		
3.3. Sun Visors	✓			3.13. Windshield Wiper and Washer Operation	✓		
3.4. Horn	✓			3.14. Accelerator	✓		
3.5. Seats	✓			3.15. Service Brake Pedal	✓		
3.6. Seatbelts	✓			3.16. Clutch Pedal Assembly	✓		
3.7. Signal Lamp Switch and Indicator	✓			3.17. Park Brake	✓		✓
3.8. Hazard Lamps	✓			3.18. Neutral Safety Switch Operation	✓		
3.9. Headlamp Switch and High Beam Indicator	✓			3.19. Entertainment Display Lockout	✓		
3.10. Auxiliary Lamp Indicator(s)	✓						

NOTES:

MOTOR VEHICLE RECORD OF INSPECTION

Section 4 - Glass								
Component	P	F	NA	Component	P	F	NA	
4.1a. Windshield Marked AS-1, AS-10, or AS-14	✓			4.2b. Side Window Operation	✓			
4.1b. Windshield Condition	✓			4.2c. Side Window Aftermarket Tint	✓			
4.1e. Windshield Tinting / Decals	✓			4.2d. Side Window Visibility (general)	✓			
4.1f. Windshield Visibility (general)	✓			4.3a. Rear Window AS-1, AS-2, AS-3, AS-10, or AS-11	✓			
4.2a. Side Glass Marked AS-1, AS-2, AS-10, or AS-11	✓			4.4a. Other Glass	✓			

NOTES:

Section 5 - Lamps								
Component	P	F	NA	Component	P	F	NA	
5.1. Lamps (general)	✓			5.7. Front Side Reflectors	✓			
5.2. Daytime Running Lamps	✓			5.8. Rear Side Marker Lamps	✓			
5.3. High Mount Brake Lamp	✓			5.9. Rear Side Reflectors	✓			
5.4. Headlamps	✓			5.10. Licence Plate Lamp	✓			
5.5. Auxiliary Lamps	✓			5.11. Emergency Lighting	✓			
5.6. Front Side Marker Lamps	✓							

NOTES:

Section 6 - Exterior, General								
Component	P	F	NA	Component	P	F	NA	
6.1. Fuel Cap	✓			6.3. Bumpers	✓			
6.2. General Body Condition	✓			6.4. Aftermarket Equipment Installation				✓

NOTES:

Section 7 - Under Hood								
Component	P	F	NA	Component	P	F	NA	
7.1. Hood Latch Mechanism	✓			7.7. Clutch Master Cylinder				✓
7.2. Hood Prop / Struts	✓			7.8. Fuel System	✓			
7.3. Remote Starter Operation			✓	7.9. Exhaust Manifold(s)	✓			
7.4. Battery	✓			7.10. Oil Leaks	✓			
7.5. Accessory Belt Drive System	✓			7.11. Engine and Transmission Mounts	✓			
7.6. Brake Master Cylinder	✓							

NOTES:

Section 8 - Steering and Suspension								
Component	P	F	NA	Component	P	F	NA	
8.1. Wheel Bearings	✓			8.8. Steering Gear				✓
8.2. Ball Joints (front and rear)	✓			8.9. Rack & Pinion	✓			
8.3. Tie Rod Ends (inner and outer)	✓			8.10. Power Steering System	✓			
8.4. Pitman Arm			✓	8.11. Control Arms	✓			
8.5. Idler Arm			✓	8.12. Struts and Shocks	✓			
8.6. Steering Stabilizer / Damper			✓	8.13. Springs	✓			
8.7. Steering Shaft Assembly	✓							

NOTES:

MOTOR VEHICLE RECORD OF INSPECTION

Section 9 - Tires and Wheels							
Component	P	F	NA	Component	P	F	NA
9.1. Tread Depth- LF:6.77 mm,RF:6.56 mm,LR:6.10 mm,RR:5.46 mm	✓			9.4. Tire Serial Numbers & Dates of Manufacture	✓		
9.2. Tire Condition (general)	✓			9.5. Wheels	✓		
9.3. Tire Size	✓			9.6. Wheel Nuts and Studs	✓		

NOTES:
 245/45R18

Section 10 - Brakes							
Component	P	F	NA	Component	P	F	NA
10.1. Brakes (general)	✓			10.6. Park Brake Drum Diameter- LR:N/A mm,RR:N/A mm	✓		
10.2. Park Brake Lining- LR:8.97 mm,RR:8.99 mm	✓			10.6. Brake Rotor Thickness- LF:35.65 mm,RF:35.78 mm	✓		
10.2. Brake Lining- LF:6.21 mm,RF:6.27 mm,LR:8.97 mm,RR:8.99 mm	✓			10.7. Brake Drum Condition (general)	✓		
10.3. Brake Lines and Hoses	✓			10.8. Brake Rear Rotor- LR:22.11 mm,RR:22.10 mm	✓		
10.4. Brake System Wiring	✓			10.9. Park Brake	✓		
10.5. Brake Rotor Condition (general)	✓						

NOTES:
 E-BRAKE ON CALIPER ELECTIC

Section 11 - Under Vehicle							
Component	P	F	NA	Component	P	F	NA
11.1. Bumpers	✓			11.5. Drive Axles / Propeller Shafts	✓		
11.2. Engine	✓			11.6. Floor Pan	✓		
11.3. Transmission / Transaxle / Transfer Case	✓			11.7. Fuel System	✓		
11.4. Differential(s)	✓			11.8. Exhaust System	✓		

NOTES:

Certification			
The Vehicle for which this Record of Inspection is issued has PASSED (Certificate #5893177) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.			
Date of Inspection 2025/10/24	Technician Number B4954	Facility Number 20648	Signature
Customer Acknowledgment			
I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.			Date (Year/Month/Day) 2025/10/24 Customer Signature