

DIAMOND MOTORS

Ph: (587) 444-3300

info@diamondmotors.ca

**DIAMOND
MOTORS****Inspection #179**

Created: 11/06/25 04:33 PM

Completed: 11/06/25 05:26 PM

Diamond Motors

3403 93 Street NW

Edmonton, AB, T6E 6A4

Mobile: (587) 444-3300

2019 Mercedes-Benz E300

L4-2.0L DOHC 16v DI Turbocharged 274.920 241hp GAS

VIN: WDDZF4KB8KA524091

Mileage: In 158950 | Out 158950

Multipoint Vehicle Inspection Harnoor**Vehicle Inspection Pre-Checks**

Tsbs & Recalls	OK	Mil Lamp / Dtcs	OK	Pre-Scan	OK
----------------	----	-----------------	----	----------	----

Vehicle Interior

Warning Lights	OK	Air Conditioning	OK	Cabin Air Filter	OK
Interior Lights	OK	Heating System	OK	Seat Belt	OK

Vehicle Exterior

Wiper Blades	OK	Body Panels	OK
Lights	OK	Windows & Mirrors	OK

Under Hood

Air Filter	OK	Coolant	OK	Engine Oil	OK
Battery, Cables, And Connections	OK	Power Steering Fluid	OK	Transmission Fluid	OK
Belt(S) And Hoses	OK	Brake Fluid	OK	Window Washing Fluid	OK
Front Left		Front Right		Rear Right	
Tread Depth	OK	Tread Depth	OK	Tread Depth	OK
Tread Wear	OK	Tread Wear	OK	Tread Wear	OK
Pressure (Inspect / Set)	OK	Pressure (Inspect / Set)	OK	Pressure (Inspect / Set)	OK

Rear Left

Tread Depth	OK
Tread Wear	OK
Pressure (Inspect / Set)	OK

Brakes

Brake Pads/Shoes	OK	Brake Hoses/Lines	OK	Covers	OK
Brake Rotors/Drums	OK	Brake Calipers/Wheel Cylinders	OK		

Condition Codes

NC Not Checked	2 Request Need/Convenience	A No Longer Performing Purpose
OK Okay	3 Comply with Manufacturer	B Does Not Meet Specification
1 Close to End of Useful Life	4 Technician Recommendation	C Missing

AMVIC: B2023690

Page 1 of 4



DIAMOND MOTORS

Ph: (587) 444-3300 • info@diamondmotors.ca

Inspection #179**2019 Mercedes-Benz E300**

Diamond Motors

Under Vehicle

Steering System	OK	Shocks And Struts	 OK
Exhaust System	 OK	Fuel Lines	OK
Right rear shocker picture is in exhaust system column			

Underhood Harnoor**Underhood**

Air Filter	OK	Hoses	OK	Fuel	OK
Cabin Air Filter	OK	Radiator	OK	Other	OK
Belts	OK	Ignition System	OK		

Condition Codes

NC	Not Checked	2	Request Need/Convenience	A	No Longer Performing Purpose
OK	Okay	3	Comply with Manufacturer	B	Does Not Meet Specification
1	Close to End of Useful Life	4	Technician Recommendation	C	Missing

DIAMOND MOTORS

Ph: (587) 444-3300 • info@diamondmotors.ca

Inspection #179

2019 Mercedes-Benz E300


Diamond Motors



Tread Wear




Tread Wear



Tread Wear



Tread Wear



Covers



Exhaust System

DIAMOND MOTORS

Ph: (587) 444-3300 • info@diamondmotors.ca

Inspection #179

2019 Mercedes-Benz E300

Diamond Motors



Exhaust System




Exhaust System



Shocks and Struts



Shocks and Struts



Shocks and Struts