SUBARU OF MISSISSAUGA

Vehicle Operation History Report

SO	OP Code	Date In / Out	MileOut	C	Status
943970	WRY-24	01/14/2026	125682	0.00	Original
	Description	Non-compliance with exhaust regulations on certain 2017-2019 MY Forester and WRX			
943970	MCA	01/14/2026	125682	93.75	Original
	Description	Service 'A' H4 2012+ -			
943970	MAINT	01/14/2026	125682	0.00	Approved
	Description	Vehicle Walk Around - Maintenance Inspection Report			
934549	CHECK	07/10/2025	117694	0.00	Original
	Description	Check and report on there being no volume coming from speakers when car is connected to phone. Although, radio functions correctly. Customer just had head unit replaced. This is an intermittent issue that seems to be happening with more frequency.			
934549	TXT	07/10/2025	117694	0.00	Original
	Description	**NOTE** SCi employee			
933411	CHECK	06/16/2025	116936	84.50	Original
	Description	Check Engine light testing/diagnosis. ******* TEXT REPORT WHEN READY ********			
933411	MCAT	06/16/2025	116936	91.85	Original
	Description	Service Maintenance A H4 Turbo 2012+			
933411	INSTALL	06/16/2025	116936	255.05	Original
	Description	Replace leaking crankcase vacuum hoses as required. See history.			
933411	INSTALL	06/16/2025	116936	42.25	Approved
	Description	ecm update for 02 sensor response MFI OBDII ECM Reprogramming A455-288 UPG-48 0.4			
933411	MAINT	06/16/2025	116936	0.00	Approved
	Description	Vehicle Walk Around - Maintenance Inspection Report			
931802	INSTALL	05/28/2025	116538	0.00	Original
	Description	Confirmed audio unit screen is bubbled and is not working. Confirmed/Approved by Mitch. A replacement unit has been ordered. *** WARRANTY ENHANCEMENT ***			
924180	CHECK	12/20/2024	112444	82.50	Original
	Description	Check and report on check engine light being on solid. RAB is off, eyesight is off. There doesn't sem to be any performance issues with vehicle. Vehicle is also consuming more gas			
924180	MCA	12/20/2024	112444	90.16	Original
	Description	Service 'A' H4 2012+ -			
924180	INSTALL	12/20/2024	112444	123.75	Approved
	Description	repair turbo wastegate solenoid wiring			
924180	INSTALL	12/20/2024	112444	257.06	Approved
	Description	replacement car battery			
914709	MCA	06/20/2024	106459	85.81	Original
	Description	Service 'A' H4 2012+ -			
914709	maint-qs	06/20/2024	106459	0.00	Approved
	Description	Vehicle Walk Around - Maintenance Inspection Report			

SO	OP Code	Date In / Out	MileOut	C	Status
908611	CHECK	02/28/2024	100643	0.00	Original
	Description	Further diagnostics for bluetooth issue and low volume output front speakers			
908385	CHECK	02/23/2024	100212	60.00	Original
	Description	Check when bluetooth running, other end cannot hear driver			
905455	MCDT	12/14/2023	98248	790.91	Original
	Description	Service 'D' H4 Turbo 2012+ **** USE SUPPLIED SPARK PLUGS **** Service A, B, + Replace Spark Plugs, Transmission and Differential Fluids			
905455	Brake	12/14/2023	98248	0.00	Original
	Description	Brake Sytem- Technical Inspection Report			
905455	MAINT	12/14/2023	98248	0.00	Approved
	Description	Vehicle Walk Around - Maintenance Inspection Report			
896916	CHECK	06/26/2023	90316	0.00	Original
	Description	C/S: CVT pump chain leak repair - leak noted on previous RO# 889479			
896517	Check In	06/14/2023	89699	0.00	Original
	Description	Check In Inspection			
896517	MCA	06/14/2023	89699	84.77	Original
	Description	Service 'A' H4 2012+ -			
896517	CHECK	06/14/2023	89699	0.00	Original
	Description	Check and repair leaking CVT pump chain cover - noted at last service			
896517	MAINT	06/14/2023	89699	0.00	Approved
	Description	Vehicle Walk Around - Maintenance Inspection Report			
889479	MCA	01/10/2023	80861	106.64	Original
	Description	Service 'A' H4 2012+ -			
889479	MAINT	01/10/2023	80861	0.00	Approved
	Description	Vehicle Walk Around - Maintenance Inspection Report			
883576	CHECK	08/26/2022	71629	0.00	Original
	Description	C/S: check and repair leaking transmission pan			
883576	CHECK	08/26/2022	71629	0.00	Approved
	Description	Check for vibration while accelerating			
883307	PRS	08/19/2022	71235	0.00	Original
	Description	postponed recommended service C			
883307	MCA	08/19/2022	71235	88.87	Original
	Description	Service 'A' H4 2012+ -			
883307	MAINT	08/19/2022	71235	0.00	Approved
	Description	Vehicle Walk Around - Maintenance Inspection Report			
876270	MCAT	03/05/2022	61586	68.97	Original
	Description	Service Maintenance A H4 Turbo 2012+ ** SCI **			
876270	MAINT	03/05/2022	61586	0.00	Approved
	Description	Vehicle Walk Around - Maintenance Inspection Report			

SO	OP Code	Date In / Out	MileOut	C	Status
869929	WRG-21	09/30/2021	52961	0.00	Original
	Description	Fuel Pump Impeller Failure			
869929	MCA	09/30/2021	52961	64.11	Original
	Description	Service 'A' H4 2012+ -			
869929	MAINT	09/30/2021	52961	0.00	Approved
	Description	Vehicle Walk Around - Maintenance Inspection Report			
864355	MCB	05/20/2021	45444	161.78	Original
	Description	Service 'B' H4 2012+ Service A + Complete Brake Service rotate tires to proper location			
864355	TXT	05/20/2021	45444	0.00	Original
	Description	does not require air and cabin filters lug nuts tool in trunk			
864355	MAINT	05/20/2021	45444	0.00	Approved
	Description	Vehicle Walk Around - Maintenance Inspection Report			
864355	Brake	05/20/2021	45444	0.00	Approved
	Description	Brake Sytem- Technical Inspection Report			
857516	MCAT	11/23/2020	39326	61.07	Original
	Description	Service Maintenance A H4 Turbo 2012+ -			
857516	MAINT	11/23/2020	39326	0.00	Approved
	Description	Vehicle Walk Around - Maintenance Inspection Report			
850751	MCA	07/08/2020	31112	61.07	Original
	Description	Service 'A' H4 2012+ -			
850751	INSTALL	07/08/2020	31112	24.00	Original
	Description	Install 4 window deflectors - parts on passenger seat			
850751	INSTALL	07/08/2020	31112	12.00	Original
	Description	Install CVT shift knob - parts on passenger seat			
850751	MaintA	07/08/2020	31112	0.00	Approved
	Description	Maintance A Inspection Report			
846008	MCB	02/21/2020	25443	207.85	Original
	Description	Service 'B' H4 2012+ Service A + Complete Brake Service - DEFAULT			
846008	Brake	02/21/2020	25443	0.00	Approved
	Description	Brake Sytem- Technical Inspection Report			
846008	MAINT	02/21/2020	25443	0.00	Approved
	Description	Maintenance Inspection Report			
838891	MCA	09/26/2019	15919	67.87	Original
	Description	Service 'A' H4 2012+ -			

SO	OP Code	Date In / Out	MileOut	C	Status
838891	MaintA	09/26/2019	15919	0.00	Approved
	Description	Maintance A Inspection Report			
834219	INSTALL	06/25/2019	7185	36.00	Original
	Description	Install window deflectors and arm rest extension. Parts supplied.			
834219	MCA	06/25/2019	7185	72.07	Original
	Description	Service 'A' H4 2012+			
834219	MaintA	06/25/2019	7185	0.00	Approved
	Description	Maintance A Inspection Report			
828796	SUB	03/13/2019	340	0.00	Original
	Description	SUBLET - RUST PROTECTION			
828796	IP	03/13/2019	340	0.00	Original
	Description	Interior Protection Protection (Fabric and or Leather) - Symtech			
828796	PP	03/13/2019	340	0.00	Original
	Description	Paint Protection - Symtech			
828334	PDI-SOMI	03/06/2019	102	0.00	Original
	Description	New Vehicle PDI Inspection WHEEL LOCKS			
828334	INSTALL	03/06/2019	102	12.00	Original
	Description	STI SHIFT KNOB			
828334	INSTALL	03/06/2019	102	0.00	Original
	Description	COMPASS HOMELINK MIRROR			
828334	NVD	03/06/2019	102	0.00	Original
	Description	New Vehicle Detailing AND GAS FOR MAR 5 @ 12PM FOR MARCUS			
828334	INSTALL	03/06/2019	102	182.38	Approved
	Description	BLOCK HEATER			
828334	INSTALL	03/06/2019	102	24.00	Approved
	Description	DOOR SILL PLATE			
828334	INSTALL	03/06/2019	102	84.00	Approved
	Description	REMOTE STARTER			
828334	INSTALL	03/06/2019	102	30.00	Approved
	Description	BODY SIDE MOULDINGS			
828334	INSTALL	03/06/2019	102	0.00	Approved
	Description	CARGO TRAY			
828334	INSTALL	03/06/2019	102	24.00	Approved
	Description	DOOR EDGE GUARD			