

Vehicle History Report + Lien Check #: 55533449

Report Date: August 15, 2024 | 5:14 p.m. EDT

Report Status: Complete



2013 VOLKSWAGEN JETTA BASE

Sedan | 4 Cylinders | Gas

3VW2K7AJ0DM278691

Country of Assembly: Mexico

Last Reported Odometer: 67,423 KM


LIEN CHECK



No Lien Records Found



No Accident/Damage
Records Found



Last Registered In:
Ontario (Normal)



12 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of August 15, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When

3VW2K7AJ0DM278691

buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

3W2K7AJ0DM278691

Vehicle History Report + Lien Check

Lien Check

No lien records found in **Ontario**.

How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

CARFAX Canada Canadian Lien Guarantee



If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased

the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.

Accident/Damage

There are no accidents/damage reported on this vehicle.

Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2013 Mar 28		Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed VIN glass etching vin etched Nitrogen fill tires

3W2K7AJ0DM278691

	ODOMETER	SOURCE	DETAILS
			<ul style="list-style-type: none"> Vehicle washed/detailed
2013 Jul 25		Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed
2013 Aug 16	7,380 KM	Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed Oil and filter changed
2013 Nov 18	15,144 KM	Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed Oil and filter changed
2014 Jul 11	28,048 KM	Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed
2015 Jan 12	37,886 KM	Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed Oil and filter changed
2015 Jul 14	47,490 KM	Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Brakes checked Vehicle washed/detailed Tires rotated Oil and filter changed
2015 Nov 24	55,046 KM	Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Vehicle washed/detailed Four tires mounted
2016 Mar 16	61,673 KM	Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Vehicle washed/detailed Oil and filter changed
2016 Aug 10	63,154 KM	Service Maxx Windsor, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Windshield washer checked Oil and filter changed Safety inspection performed
2016 Nov 8	63,188 KM	Service Maxx Windsor, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Safety inspection performed
2017 Jan 5	67,423 KM	Service Maxx Windsor, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed



Open Recalls

Recall #: 37M2 | MICRO SWITCH Recall Date: 2019 Aug 27

3VW2K7AJ0DM278691

Recall Description

Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.

Remedy

Install an additional switch and circuit board.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit Volkswagen's website. (<https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html>)



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Mar 28		Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Service Record	Vehicle serviced
2013 Apr 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as black
2013 Jul 25		Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Service Record	Vehicle serviced
2013 Aug 16	7,380 KM	Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Service Record	Vehicle serviced

3VW2K7AJ0DM278691

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Oct 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2013 Nov 18	15,144 KM	Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Service Record	Vehicle serviced
2014 Jul 11	28,048 KM	Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Service Record	Vehicle serviced
2015 Jan 12	37,886 KM	Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Service Record	Vehicle serviced
2015 Jul 14	47,490 KM	Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Service Record	Vehicle serviced
2015 Aug 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2015 Oct 16		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2015 Nov 24	55,046 KM	Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Service Record	Vehicle serviced
2016 Mar 16	61,673 KM	Northside Volkswagen Sault Ste. Marie, Ontario, Canada	Service Record	Vehicle serviced
2016 Jul 18	63,072 KM	Auto Auction	Auction Announcement	Vehicle sold Listed as a fleet/lease vehicle
2016 Aug 10	63,154 KM	Service Maxx	Service Record	Vehicle

3W2K7AJ0DM278691

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
		Windsor, Ontario, Canada		serviced
2016 Nov 8	63,188 KM	Service Maxx Windsor, Ontario, Canada	Service Record	Vehicle serviced
2017 Jan 5	67,423 KM	Service Maxx Windsor, Ontario, Canada	Service Record	Vehicle serviced
2017 Jul 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal
2018 Feb 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Aug 27		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 37M2
2020 Dec 31		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as black
2022 Aug 16		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black

3VV2K7AJ0DM278691



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada. <https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2024 CARFAX Canada ULC. All rights reserved.



3VW2K7AJ0DM278691