



Vehicle History Report #: 62410946  
Report Date: June 24, 2025 | 5:19 p.m. EDT  
Report Status: Complete

## 2018 FORD EXPLORER PLATINUM

Sport utility vehicle | 6 Cylinders | Gas  
1FM5K8HT6JGA60611  
Country of Assembly: United States  
Last Reported Odometer: n/a



No Accident/Damage Records  
Found




Last Registered In:  
Ontario (Normal)



0 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of June 24, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.



# Vehicle History Report



## Accident/Damage

✓ There are no accidents/damage reported on this vehicle.



## Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

*We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



## Open Recalls

Recall #: 24S02 | EXTERIOR A-PILLAR APPLIQUE MOLDING INSPECTION Recall Date: 2024 Jan 23

### Recall Description

IN SOME OF THE AFFECTED VEHICLES, IT MAY BE POSSIBLE THAT SOME OF THE EXTERIOR A-PILLAR APPLIQUE TRIM CLIP ATTACHMENTS ARE NOT PROPERLY ENGAGED DUE TO IMPROPER ASSEMBLY OR REPAIR. IF THIS OCCURS, THE A-PILLAR APPLIQUE TRIM, WHICH BORDERS THE RIGHT AND LEFT SIDE OF THE WINDSHIELD, MAY BE LOOSE, MISSING OR BECOME DETACHED.

### Remedy

FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT AND REPAIR ANY LOOSE OR MISSING EXTERIOR A-PILLAR TRIM MOLDINGS FREE OF CHARGE PARTS AND LABOR. A TEMPORARY REPAIR MAY ALSO BE COMPLETED AS NEEDED.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit [Ford's website](https://www.ford.ca/support/recalls/). (<https://www.ford.ca/support/recalls/>)



## Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



## Detailed History



DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Feb 21		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Dealer took registration of this vehicle while it was in inventory First Owner Reported Vehicle colour noted as black
2018 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2019 Mar 10		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2019 May 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black
2020 Mar 12		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black
2022 Aug 22		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black
2024 Jan 23		FORD	Recall	Manufacturer Recall Issued Recall # 24502
2024 Jul 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2025 Mar 10		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal





## Questions? We're here to help.

Visit us at **support.carfax.ca**

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.



1FM5K8HT6JGA60611