

2016 NISSAN PATHFINDER S

Sport utility vehicle | 6 Cylinders | Gas 5N1AR2MM0GC657291 Country of Assembly: United States

Country of Assembly: United States Last Reported Odometer: 120,096 KM





Last Registered In: Manitoba (Normal)



24 Service Records Found







Not Actively Declared Stolen




Questions? We're here to help.

Visit us at support.carfax.ca

(i)

This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of September 14, 2022 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



INCIDENT DATE	DETAILS AMOUNT		
① 2019 Jan 23	Manitoba, Canada		
	Estimate: Rear Estimate Date: n/a	\$807.26	
	Claim: Collision Rear	Not Reported	
0 2020 Jul 3	Manitoba, Canada		
	Estimate: Front Estimate Date: n/a	\$751.69	
	Claim: Non-collision Front	Not Reported	

Registration

This vehicle has been registered in the province of Manitoba in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2016 Jun 10		VICKAR NISSAN	Vehicle serviced
		Winnipeg, Manitoba, Canada	 Pre-delivery inspection completed
			Wheel locks installed
2016 Nov 22		VICKAR NISSAN	Vehicle serviced
		Winnipeg, Manitoba, Canada	Vehicle washed/detailed
2016 Dec 21		VICKAR NISSAN	Vehicle serviced
		Winnipeg, Manitoba, Canada	 Running boards/tubes/steps installed
			 Vehicle washed/detailed
			 Fabric protection applied
			Paint protection applied
			Undercoating/rustproofing applied
2017 Jun 29		VICKAR NISSAN	Vehicle serviced
		Winnipeg, Manitoba, Canada	Recommended maintenance performed
2017 Oct 13		VICKAR NISSAN	Vehicle serviced
		Winnipeg, Manitoba, Canada	 Recommended maintenance performed
			Maintenance inspection completed
			Oil and filter changed
2018 Jan 2		VICKAR NISSAN	Vehicle serviced
		Winnipeg, Manitoba, Canada	 Undercoating/rustproofing inspected

DATE	ODOMETER	SOURCE	DETAILS		
2018 Jan 25		VICKAR NISSAN Winnipeg, Manitoba, Canada	Vehicle serviced		
2018 Feb 16		VICKAR NISSAN Winnipeg, Manitoba, Canada	Vehicle serviced		
2018 Apr 27		VICKAR NISSAN Winnipeg, Manitoba, Canada	Vehicle serviced Recommended maintenance performed Maintenance inspection completed Oil and filter changed		
2018 Jul 16		VICKAR NISSAN Winnipeg, Manitoba, Canada	Vehicle serviced Recommended maintenance performed Maintenance inspection completed Oil and filter changed Tire condition and pressure checked Vehicle washed/detailed		
2018 Nov 5		VICKAR NISSAN Winnipeg, Manitoba, Canada	Vehicle serviced Recommended maintenance performed Maintenance inspection completed Oil and filter changed		
2019 Jan 11		VICKAR NISSAN Winnipeg, Manitoba, Canada	Vehicle serviced • Undercoating/rustproofing inspected		
2019 May 7	54,306 KM	VICKAR NISSAN Winnipeg, Manitoba, Canada	Vehicle serviced Recommended maintenance performed Maintenance inspection completed Oil and filter changed Vehicle washed/detailed		
2019 Aug 6		VICKAR NISSAN Winnipeg, Manitoba, Canada	Vehicle serviced Recommended maintenance performed Maintenance inspection completed Tire condition and pressure checked Oil and filter changed Vehicle washed/detailed		
2020 Jan 6		VICKAR NISSAN Winnipeg, Manitoba, Canada	Vehicle serviced Recommended maintenance performed Maintenance inspection completed Oil and filter changed Vehicle washed/detailed		
2020 Jan 17		VICKAR NISSAN Winnipeg, Manitoba, Canada	Vehicle serviced • Undercoating/rustproofing inspected • Vehicle washed/detailed		
2020 Mar 30		VICKAR NISSAN Winnipeg, Manitoba, Canada	Vehicle serviced Oil and filter changed Vehicle washed/detailed		
2020 Apr 8	80,124 KM	Midas Auto Service Experts Winnipeg, Manitoba, Canada	Vehicle serviced		
2020 Jun 27	86,013 KM	Kal Tire - Winnipeg Winnipeg, Manitoba, Canada	Vehicle serviced • Four wheel alignment performed • One tire mounted • One tire balanced		
2020 Jun 30	86,610 KM	Kal Tire - Estevan Estevan, Saskatchewan, Canada	Vehicle serviced • Four wheel alignment performed		

DATE	ODOMETER	SOURCE	DETAILS
2020 Dec 11		VICKAR NISSAN	Vehicle serviced
		Winnipeg, Manitoba, Canada	 Recommended maintenance performed
			 Maintenance inspection completed
			 Vehicle washed/detailed
			 Oil and filter changed
			Tire condition and pressure checked
2021 Mar 3		VICKAR NISSAN	Vehicle serviced
		Winnipeg, Manitoba, Canada	Vehicle washed/detailed
		1 3	Undercoating/rustproofing inspected
2021 Jun 11	120,096 KM	McPhillips Nissan	Vehicle serviced
-		Winnipeg, Manitoba, Canada	Maintenance inspection completed
		p 25,stoba, cariada	Oil and filter changed
2022 Jan 24		VICKAR NISSAN	Vehicle serviced
-		Winnipeg, Manitoba, Canada	 Undercoating/rustproofing inspected



Open Recalls

Recall #: R22A2 | PATH HOOD LOCK ASSY NTB22053 Recall Date: 2022 Jun 28

Recall Description

On certain 2013-2016 Pathfinder vehicles, dust or dirt contamination may accumulate on and around the secondary latch lever pivot joint. Over time, the build-up of contamination, combined with a lack of proper inspection and maintenance of the secondary latch (as described in the Owner's Manual), can create mechanical binding that could cause the lever to remain in the open position after it has been disengaged. In addition, this contamination can scratch the secondary latch's protective anti-corrosion coating, allowing corrosion of the bare metal in the pivot joint.

Remedy

Nissan will mail affected owners an Interim Owner Letter that will instruct the owners how to properly inspect the hood lock and secondary latch for proper working condition (no sticking). If the lever moves freely, the owner can clean and condition the lever per the Owner s Manual general maintenance requirements in Section 8 Maintenance and DIY. If the lever does not move freely, the customer will be instructed to take their vehicle to a Nissan dealer. The dealer will inspect the hood lock and secondary latch and, if functioning properly, clean and condition by applying lubricant. If either of these components do not function properly, the hood lock and/or secondary latch will be replaced.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit Nissan's website.



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE ODOMETER SOURCE RECORD TYPE DETAILS

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Jun 10		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2016 Nov 22		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2016 Dec 21		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2016 Dec 29		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2017 Jun 29		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2017 Oct 13		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2017 Dec 19		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Jan 2		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2018 Jan 25		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2018 Feb 16		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2018 Apr 27		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2018 Jul 16		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2018 Nov 5		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2018 Dec 19		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Jan 11		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2019 Jan 23	49,307 KM	Manitoba, Canada	Collision	Rear
2019 Jan 23		Insurance Records Manitoba, Canada	Collision	Estimate Date: n/a Rear
2019 May 7	54,306 KM	VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2019 Aug 6		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Dec 19		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jan 6		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2020 Jan 17		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2020 Mar 30		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2020 Apr 8	80,124 KM	Midas Auto Service Experts Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2020 Jun 27	86,013 KM	Kal Tire - Winnipeg Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2020 Jun 30	86,610 KM	Kal Tire - Estevan Estevan, Saskatchewan, Canada	Service Record	Vehicle serviced
2020 Jul 3		Manitoba, Canada	Non-collision	Front
2020 Jul 3		Insurance Records Manitoba, Canada	Non-collision	Estimate Date: n/a Front
2020 Dec 11		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2020 Dec 19		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Mar 3		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2021 Jun 11	120,096 KM	McPhillips Nissan Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2021 Dec 19		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed
2022 Jan 24		VICKAR NISSAN Winnipeg, Manitoba, Canada	Service Record	Vehicle serviced
2022 Jun 28		NISSAN	Recall	Manufacturer Recall Issued Recall # R22A2
2022 Aug 23		Motor Vehicle Dept. Manitoba, Canada	Canadian Renewal	Registration Issued or Renewed



This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or indicating any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada. Conditions of Use

© Copyright 2005 - 2022 CARFAX Canada ULC. All rights reserved.

